

Yolo County Hazardous Waste and Leaky Underground Tank Cases

Facility	File/Number	Status	Comments
621 Houston St	HM 26 W. Sac. Waste Oil	Closed	File H 26 - Investigation of motor oil contamination found in surface soils from crank case oil change operations as part of truck maintenance. Hydrocarbons were limited to surface soils and motor oil levels less than 250 ppb in groundwater. No remedial action required. Case closed December 2000 and file archived to 00026HWG in December 2003.
A BEST AUTO Galveston St	UST 4 e W. Sac. Gasoline	Closed	In 1996 a 5,000 gallon unleaded gasoline UST was abandoned in place beneath the site. Soil and groundwater sampling in 1993 and 1995 showed TPHg and BTEX hydrocarbons in portions of the backfill material around the UST. Biological agents were injected in the backfill material in 1993, but did not appear to have degraded all hydrocarbons in the UST backfill. Soil and groundwater samples collected in 1998 showed gasoline oxygenates were not present in soil and groundwater within 5 feet of the UST, and at the perimeter of the site. TPHg and BTEX were not detected in soil and groundwater within 5 feet of the UST, and at the perimeter of the site, but benzene and toluene below 1 ppm were detected in water samples within 5 feet of the UST, and at the perimeter of the site. Based on the results of soil and groundwater sampling, it appears that minor gasoline contamination, excluding gasoline oxygenates, is present in tank backfill material at the southeast corner of the UST and at the edge of the site. Results show that hydrocarbons do not represent a threat to groundwater quality. A No Further Action Required letter was issued by the Central Valley Regional Water Quality Control Board in October 2001. File scanned and incorporated into File 4UTH.
A E HARTER VOLKSWAGON Chiles Rd	UST 3 e Davis Gasoline	Closed	LEAK DISCOVERED DURING JUNE 1987 TANK REMOVAL, SOIL REMEDIATION COMPLETED JULY 1987. FILE CLOSED. File archived as 00003UTH in December 2003.
A E TEICHERT CR 29 & HWY 113	UST 368 Davis Waste Oil, Eiesel, Gasoline	Closed	Files A & B: 1993 removal of two 10,000 gallon diesel underground storage tanks soil contamination was observed down to groundwater. 8,300 cubic yards of soils were excavated and bioremediated onsite. Post monitoring included four soil borings and three groundwater monitoring wells. Both soil and groundwater samples were below detection levels for hydrocarbons. Groundwater flow direction is generally to the southeast at 70 to 90 feet above sea level. Yolo County closed the case in June 1995, the monitoring wells were destroyed in November 1995. Case closed. File scanned June 2003 to 368UTH.
A H ROMINGER & SONS, INC 28686 CR 29A	UST 551 Winters Gasoline & Diesel	Closed	FILE A: 1997/1998 GENERAL FILE: INVESTIGATION IN PROGRESS. Feb 2002 found hydrocarbons and TAME in at all three wells at depth of approximately 25 feet. Three phased Remediation Workplan for Groundwater Investigation and Remediation Feasibility Study approved in April 2003. Plan includes ground assessment and interim ozone injection system and feasibility study for air-sparging/vapor extraction. RWQCB contact is David Stavarek, (916) 255-3073
A H ROMINGER AND SONS 28686 CR 29A	UST 551 B WINTERS GASOLINE AND DIESEL	OPEN	
A MART #716 1592 Main St (East)	HM 81 Woodland Gasoline	Closed	GASOLINE SPILL DUE TO DISPENSOR FILTER FAILURE (ER-118) RESULTED IN SITE ASSESSMENT. MINOR IMPACT TO SOILS. CASE CLOSED.

Facility	File/Number	Status	Comments	
A MART #716 1592 Main St (East)	UST Woodland	506 Gasoline	Closed	SOIL ASSESSMENT REQUIRED OCT 1, 1989 BY YCEH TO DETERMINE EXTENT OF CONTAMINATION FROM SPILL THAT OCCURRED ON AUG 28, 1989. SEE ER-89118 & HM 8981. SITE CLOSED. File archived to removal section of 506UTH in November 2003.
A T & T BERRYESSA PEAK CR 78A & HWY 16	UST Winters	26 Diesel	Closed	SOIL CONTAMINATION DISCOVERED DURING 1989 UST REMOVAL. SOILS ABOVE 300 PPM TYP EXCAVATED. PASSIVE IN-SITU TREATMENT COMPLETED ON REMAINING SOILS. FILE CLOSED.
A T & T DUNNIGAN CR 6 - 3 MILES W Of I-5	UST Dunnigan	27 Diesel	Closed	File L 27 - Diesel in soils from ruptured pipes. Soil remediation completed. No groundwater impacted. Tanks were removed Oct 97, 60 yards of soils were excavated to near non-detect for BTEX and TPH as diesel. File closed in 1997 and archived as 00027UTH in December 2003.
ABC Dental 970 Sacramento Ave	HM W. Sac	443 Photo Waste	Closed	Complaint received that photo fixer waste was disposed into the sanitary sewer. Investigation found facility to have records for appropriate disposal. Information from this file has been scanned to the Adobe 5225CPI file. Case closed.
ADAMS 102 DRYER CR 102 & HWY 16	UST Woodland	5 Diesel	Closed	FILE A 1990-1993: THREE 10,000 GAL DIESEL TANKS REMOVED DEC 13, 1990. TWO TANKS LEAKED. CONTAMINATED SOILS EXCEEDING 100 PPM EXCAVATED. GROUNDWATER IMPACT INVESTIGATION REQUESTED. FILE B 1994: ADDITIONAL SOILS EXCAVATED, GROUNDWATER INVESTIGATION FOUND NO GROUNDWATER IMPACT. YC CLOSED CASE OCT 1995. File archived to 00005UTH in December 2003.
ADAMS GRAIN-UNION STORAGE FAC Gibson & East	HM Woodland	186 e Fumigants & Hydrocarbons	Closed	H 186 - Investigation conducted following a report of seed treatment with fumigants buried on site in the past. Only low levels found. A narrow band of hydrocarbons, possibly asphalt residuals found. Case closed, file archived as 00616HWG in February 2004.
ADAMS SCHWAB ADAMS- 1020 East St	UST Woodland	616 Gasoline	Open	L 616 – Gasoline contaminated soils observed during routine UST removal. After excavation pit bottom soil sample contained 3,000 ppm TPH. Groundwater impact has not been defined. Case assumed by the CVRWQCB March 2000. Further investigation to be initiated in 2003.
ADAMS TRUCKING 1470 Kentucky Ave (East)	UST Woodland	6 Diesel	Closed	FILE A - PRE 1993- SOILS CONTAMINATD BY UST REMOVED IN 1990. PIPE TO ABOVE GROUND TANK LEAKED SAME SITE 1991. SOILS EXCAVATED, GRAVEL BACKFILL EXCAVATED. FILE B 1993/1995 - ADDITIONAL INVESTIGATION SOIL EXCAVATION COMPLETED. FILE C 1996/1997 DATA: POST REMEDIAL MONITORING OF GROUNDWATER CONDUCTED. CASE CLOSED BY YCEH AND CONCURED BY RWQCB IN OCTOBER 1997. File archived to 00006UTH in December 2003.
ADCO LUMBER 629 Houston St	UST W. Sac.	7 e Diesel	Closed	LEAK DISCOVERED DURING SEPT 1988 REMOVAL OF A 1,000 AND 10,000 GAL TANKS, ASSESSMENT IN PROGRESS. BOTH TANKS PASSED 1987 TESTING, WERE IN POOR CONDITION WHEN REMOVED. CONTAMINATED SOILS EXCAVATED AND AERATED ONSITE. FILE CLOSED 9-29-88. File archived to 00007UTH in December 2003.
ADVANCED AUTO REPAIR 965 Olive Dr	HM Davis	77 Hydrocarbons	Closed	File H 77 - Waste oil storage area contaminated with oils. Soils excavated & disposed. Waste oil storage drum replaced. Case closed November 1991. File archived as 3949HWG in January 2004.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
AGRIFORM FARM SUPPLY CO 40189 CR 18C	HM Woodland	156 Phosphoric Acid	Closed
FILE H 156 - In 1992 approximately 6,000-gallons of phosphoric acid was released during rail car off loading procedures. Liquids were recovered from trenches on each side of tracks by flushing the ballast. Contaminated soils were excavated, both soil and liquids were applied to fields as fertilizer under controlled conditions. File archived as 3953HWG in January 2004.			
AGRIFORM FARM SUPPLY CO 40189 CR 18C	HM Woodland	195 DDT, TPH(D)	Closed
H 195 - File includes reports of the investigation and clean up for former pesticides handling areas. File archived as 03953HWG in February 2004.			
Agrium (formerly Unocal, Prodicta) 3961 Channel Dr	HM W. Sac.	60 Cutting Oil	Closed
MAY 1989 CLEANUP OF CUTTING OIL CONTAMINATED SOILS AT SITE ACQUIRED BY UNOCAL ADJACENT TO THE EXISTING PLANT. BIO-REMEDIATION COMPLETED JAN 1990. FILE CLOSED.			
Agrium (formerly Unocal, Prodicta) 3961 Channel Dr	HM W. Sac.	60 Information File	Closed
REPORTS, PROPOSALS, COMMENTS OF PROPOSED EXPANSION OF PURGE SYSTEM, SOME ADDITIONAL GENERAL INFORMATION IS CONTAINED IN THIS FILE.			
Agrium (formerly Unocal, Prodicta) 3961 Channel Dr	HM W. Sac.	61 A Nitrates	Closed
FILE A:1987-89 NITRATES FOUND IN GW RESULTS IN SEVERAL INVESTIGATIVE REMEDIATION OF GW ORDERED BY RWQCB IN PERCHED ACQUIFER IN NOV 90. BY 1994 MONITORING FOUND NO IMPACT DUE TO REMEDIAL EFFORTS.			
Agrium (formerly Unocal, Prodicta) 3961 Channel Dr	HM W. Sac.	61 B Nitrates	Open
FILE B 1990-2000: UNOCAL ORDERED TO REASSESS GROUNDWATER CONDITIONS IN REPORT DUE JULY 1995. Investigation of multiple releases in progress.			
Agrium (formerly Unocal, Prodicta) 3961 Channel Dr	HM W. Sac.	62 Hydrocarbons	Closed
MARCH 1987 SMALL DIESEL SPILL AT DIESEL RECEIVING RACK, SOIL EXCAVATED & DISPOSED AS HAZARDOUS WASTE.			
Agrium (formerly Unocal, Prodicta) 3961 Channel Dr	UST W. Sac.	3349 Diesel	Open
One 10,500 gallon diesel tank.			
AGRIVENTURE 1341 PROPERTY CR 124	He WEST SACRA	497 DIESEL	OPEN
THERE ARE TWO SITES ON THIS PROPERTY THAT ARE CONTAMINATED. GROUNDWATER SAMPLES FROM THE SOUTHERN SITE CONTAINDE TBH AS DIESEL, ETHYLBENZENE AND XYLENES. AT THE NORTHERN SITE, A GROUNDWATER SAMPLE CONTAINED TPH AS DIESEL, TOLUENE, ETHYBENZENE, XYLENES, AND MTBE. REMEDIAL EFFORTS ARE RECOMMENDED. REMEDIATION IS LIKLEY TO INCLUDE EXCAVATION OF SOIL. THE INSTALLATION OF MONITORING WELLS IS PROBABLE.			
ALBERT'S AUTOMOTIVE 497 1/2 Kentucky Ave	HM Woodland	267 Waste Oil, Antifreeze & Gas	Closed
INSPECTION CONDUCTED OF HAZARDOUS WASTE STORAGE AND DISPOSAL VIOLATIONS NOTED. COUNTY ORDER HAS BEEN ISSUED. CASE CLOSED OCT 1, 1994.			
ALL STAR RENTS 1207 ARMFIELD AVE	H WOODLAND	492 e DIESEL AND CADMIUM	CLOSED

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
AMERICAN INTERNATIONAL MANUF 1230 Fortna Ave	HM Woodland	224 Nickel	Closed SLIGHTLY ELEVATED LEVELS OF NICKEL FOUND IN SHALLOW GROUNDWATER. FILE CLOSED.
AMES COMPANY INC 1485 TANFORAN AVE	HM WOODLAND	474 TRPH AND SOLVENTS	OPEN TOTAL RECOVERABLE PETROLEUM HYDROCARBONS AND SOLVENTS FOUND IN GROUNDWATER DURING A SITE ASSESSMENT
ANTHONY, CHARLES (KENWORTH) 3025 Evergreen Ave	HM W. Sac.	342 Sludge, Petroleum	Closed ILLEGAL TRANSPORTATION & DISPOSAL OF SLUDGE FROM INDUSTRIAL STEAM CLEANING. - - Well permits for pre-sale environmental investigation of Kenworth property 4/12/99.
ARCO #5786 847 W HARBOR BLVD	UST WEST SAC	576 MTBE	Open SOIL SAMPLES WERE TAKEN DURING AN UPGRADE MTBE IS PRESENT IN TWO SAMPLES.
ARCO BULK PLANT 1701 South River Road	HM W. Sac.	1 Be Petroleum Hydrocarbons	Closed FILE B: 1994 CORRESPONDENCE/DATA FILE: FREE PRODUCT, & SOIL & GW PUMES ARE PRESENT UNDER & EXTEND OFFSITE. A HOLT MONITORING & FREE PRODUCT RECOVERY PROGRAM IS CURRENTLY BEING CONDUCTED AT THE SITE.
ARCO BULK PLANT 1701 South River Road	HM W. Sac.	1 C Petroleum Hydrocarbons	Open FILE C: 1995-1996 DATA: CASE SUMMARY. SEE ALSO FILE C: 1994 QTR REPORTS: SEE ALSO RELATED FILES: TESORO OIL H83, JEFFERSON BLVD SPILL H57, RAMOS OIL H148, SFPP H8, AND SHELL OIL H59. A dual phase extraction program was implemented on January 2, 2002.
ARCO BULK PLANT 1701 South River Road	HM W. Sac.	1 E Gasoline & Diesel	Open FILE E: DRAFT CLEANUP & ABATEMENT ORDER FROM THE REGIONAL BOARD AND ARCO'S RESPONSE. 2ND QUARTER 1994 MONITORING AND WORK COMPLETED.
ARCO BULK PLANT 1701 South River Road	HM W. Sac.	1 Ae Petroleum Hydrocarbons	Closed FILE A: PRE 1994 DATA - IN APR 1989 FLOATING PRODUCT DISCOVERED IN TRENCHES ALONG JEFFERSON BLVD. SUBSEQUENT INVESTIGATION HAVE FOUND PRODUCT UNDER SEVERAL SITES.
ARCO BULK PLANT 1701 South River Road	HM W. Sac.	1 D Petroleum Hydrocarbons	Closed FILE D: PHASE U ENVIRONMENTAL SITE ASSESSMENT REPORT.
ARCO FACILITY #5332 705 RUSSELL BLVD	UST DAVIS	248 F GASOLINE	OPEN FILE F : 2003 DATA
ARCO FACILITY #5332 705 Russell Blvd	UST Davis	248 C Gasoline	Closed FILE C 1994 - 1997: QUARTERLY REPORTS: INTERIM REMEDIAL PROPOSAL TO CONDUCT SOIL VAPOR EXTRACTION & AIR SAPARGING TO BE SUBMITTED. QUARTERLY MONITORING CONTINUES.
ARCO FACILITY #5332 705 Russell Blvd	UST Davis	248 B Gasoline	CLOSED FILE B TECHNICAL REPORTS: QUARTERLY GROUNDWATER MONITORING INITIATED EARLY '92. FREE PRODUCT FOUND NOV '92. PASSIVE SKIMMERS INSTALLED, MONITORED BIWEEKLY. SITE ASSESSMENT TO DEFINE LATERAL CONTAMINATION IN PROGRESS.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
ARCO FACILITY #5332 705 Russell Blvd	UST Davis	248 D Gasoline	Closed FILE D: 1998 - 1999; GENERAL FILE. PLANS FOR REMEDIATION SYSTEM. VAPOR EXTRACTION & AIR SPARGE WELLS INSTALLED IN SUMMER 1995.
ARCO FACILITY #5332 705 Russell Blvd	UST Davis	248 A Gasoline	Closed FILE A GENERAL FILE: SOIL CONTAMINATION FOUND DURING 1990 UST REMOVAL & REPLACEMENT. SITE INVESTIGATION DEFINED LIMITED SOIL IMPACT MAY '91. SOIL VAPOR STUDY CONDUCTED OCT '91. GROUNDWATER INVESTIGATION CONDUCTED NOV '91 CONFIRMED GROUNDWATER IMPACTED
ARCO FACILITY #5332 705 Russell Blvd	UST Davis	248 E Petroleum	Open FILE E: 2000 - GENERAL FILE. There are 8 GW, 8 sparge and 8 vapor extraction wells at this site. Soil contamination has been defined above 45 feet, vertical assessment below 45 feet is needed. Groundwater assessment has yet to be completed. Quarterly GW monitoring in progress. RWQCB is the lead agency.
ARCO-FORMER STATION (SWIFT) 1800 Olive Dr	UST Davis	459 Gasoline	Closed FILE 459:1988-1992: LEAK DISCOVERED DURING JULY 1987 TANK REMOVAL. SOIL EXCAVATED TO 20 FT IN 1988. Nov 1991 Cleanup & abatement order issued. 1994 closure requested and denial by regional board. Additional monitoring and remediation conducted through case close by the RWQCB in 10/31/96. See also #UST-89 Van Wert Motors for case on adjacent site at 1700 Olive Drive. Case closed. File archived to 459UTH in November 2003.
Asbestos (Abandoned) CR 25 BTWN 89 & 90	HM Madison	429 Asbestos Sheets	Open ABANDONED ASBESTOS WASTE CR 25 BETWEEN CR 89 & 90
AUTO EXPRESS 803 Grant Ave #4	HM Winters	2 e Waste Oil & Automotive Fluids	Closed SPILLED AUTOMOTIVE FLUIDS OBSERVED ON GROUND SURFACE. FLUIDS WERE IN TOP SOIL IN ALLEY AND ALONG ELLIOT STREET. SOILS WERE EXCAVATED, DISPOSED, DOWN TO VISIBLY CLEAN SOIL. FILE CLOSED.
AVILLA, MRS (PROPERTY) CR 99, 1/2 MI N OF I-5	HM Woodland	133 Calcium Arsenate	Closed BARN FIRE IN JULY 1991 RELEASED CALCIUM ARSENATE. CONTAMINATED MATERIAL REMOVED AS HAZARDOUS WASTE. SAMPLES CONFIRMED REMAINING LEVELS BELOW ACTION LEVEL. FILE CLOSED.
B C GAS 450 CR 102	UST Woodland	5212 D	Closed Formerly file L258. June 2002 report finds that fuel oxygenates and additives have increased, groundwater flow direction varied significantly in 2001, and reversals in groundwater flow have made formerly down gradient wells the upgradient wells. Further investigation is needed to determine if an additional release has occurred and investigate off site sources.
B C GAS 450 CR 102	UST Woodland	5212 B Gasoline	Closed 1997 TO PRESENT: File containing reports and letters including RBCA report and feasibility study. Formerly file L258.
B C GAS 450 CR 102	UST Woodland	5212 C Gasoline	Closed PROBLEM ASSESSMENT REPORT WRITTEN RECOMMENDING A PILOT STUDY USING OZONE-AIR SPERGING AND GROUND WATER EXTRACTION. Formerly file L258
B C GAS 450 CR 102	UST Woodland	5212 E Petroleum	Open Formerly file L258. 2002 Data including the October 2002 Assessment Report for Groundwater Extraction and Pilot Remediation Test.

<i>Facility</i>	<i>File/Number</i>		<i>Status</i>	<i>Comments</i>
B C GAS 450 CR 102	UST	5212 A	Closed	1992 - 1997 File: PAR REVIEWED. SIGNIFICANT CONTAMINATION NOTED IN SOIL & GROUNDWATER. OWNER ORDERED TO FURTHER DEFINE PLUME & INITIATE REMEDIATION ACTIVITIES. Formerly file L258.
	Woodland	Gasoline, Hydrocarbons		
B C STOCKING 341 Industrial Way	UST	32 e	Open	GASOLINE & DIESEL CONTAMINATION. WORKPLAN TO BEGIN SITE INVESTIGATION YET TO BE SUBMITTED.
	Woodland	Gasoline & Diesel		
B F LAWLER TRUST 640 E St	HM	264	Closed	WASTE OIL CONTAMINATION DETECTED ON THE PROPERTY. THE SOIL WAS EXCAVATED AND TRANSPORTED OFF SITE FOR TREATMENT. TWO EXCAVATION SOIL SAMPLES WERE NONDETECT. CASE CLOSED.
	W. Sac.	Waste Oil		
B J TITON SERVICES 80 Bee Jay Way	UST	51	Closed	File L 51 - Minor soil contamination observed during Jan 1990 removal of 4000 gal gasoline and 4000 gal diesel tanks. All soils contaminated with 10-ppm TPH or more were excavated and treated off site. Case closed in May 1991 and archived to 00031UTH in December 2003.
	Woodland	Gas, Diesel		
B O R INDUSTRIES 2505 Rice Ave	HM	5	Closed	1986 INVESTIGATION INTO POSSIBLE TRANSPORTATION & STORAGE VIOLATIONS OF HAZARDOUS WASTE REGULATIONS BY THE DEPT OF HEALTH SERVICES. File archived as 53HWG in December 2003.
	W. Sac.	Hazardous Waste		
B O R INDUSTRIES 2505 Rice Ave	UST	53	Closed	SURFACE SOIL CONTAMINATION FOUND IN 1986. SOILS OVER 10 PPM EXCAVATED & AERATED TO LESS THAN 350 PPM THEN SPREAD IN PARKING AREA. FILE CLOSED. File archived as 53UTI
	W. Sac.	Gasoline, Diesel		
BANK OF AMERICA TRUST CO Jefferson & Marshall	HM	34 e	Closed	ABANDONED DRUMS DETERMINED TO CONTAIN OIL & NON-HAZARDOUS WASTES WERE REMOVED BY CONTRACTOR FOR BANK OF AMERICA.
	W. Sac.	Abandoned Drums		

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
BARBER CASHEW (FORMER) ESPARTO HWY 16 & CR 86A	HM Esparto	308 NO3, fuel, pesticides	Open
Files 308 A - D: File A-1995 Data, File B-1996-1997, File C-1998 to 2000, File D- 2001 to current data. Site assessment for sale of property found very high levels of nitrogen in shallow soils & groundwater. Hydrocarbons also found in surface soils along with trace levels of pesticides. Soils containing high nitrates were excavated in 1996, to below 250 mg/kg but failed to meet the CVRWQCB goal of 250 mg/kg. A draft Cleanup and Abatement Order was proposed by the CVRWQCB in 1997, if issued we do not have a copy on file. Soil impact was defined by January 1999, but groundwater impact and remediation has not yet been determined. A work plan for remediation was approved by the State to further define groundwater conditions but has not been implemented as of August 2000. Phytoremediation proposed in 2001 and implemented late in the year. This site has three shallow groundwater monitoring wells and one deep (200 ft) production well. Another production well is located just off site to the SE on the Segura property. Groundwater monitoring in March 2002 found Nitrate as nitrogen at 49 to 74 mg/L. Ammonia as nitrogen was detected between 0.21 mg/L and 0.33 mg/L in the monitoring wells. Groundwater flow direction in the 3rd Quarter 1991 and 1st Quarter 2002 was to the NE. First-encountered groundwater contains nitrate as nitrogen and Ammonia as nitrogen, both are decreasing in concentration over time. These trends indicate that water quality at the site is improving or stabilized. Phytoremediation is currently being employed as a remedial action at the Site. Hybrid Poplar trees were planted in November 2001 along the south and east property boundaries to facilitate the up take and translocation of nitrogen from soil and groundwater into plant tissue. All trees are currently leafed out healthy specimens. The consultant recommends that one additional sampling event occur in the first quarter 2003 to document Phytoremediation progress and decreasing or stabilized nitrate as nitrogen concentrations in groundwater. If this confirms continued decreasing or stabilized nitrate as nitrogen concentration, request case closure. The CVRWQCB responded in February 2003 request additional soil assessment and implementation of an annual Monitoring and Reporting Program..			
BARBER CASHEW/WIBLUR-ELLIS 350 Industrial Way	HM Woodland	304 Fertilizer	Closed
STUDY OF SUBSURFACE SOILS AT CLOSED FACILITY FOUND TKN MINERAL-SALT CONCENTRATIONS IN DITCH, NITROGEN DECREASING WITH DEPTH ONSITE & LOWLEVELS OF DINOSEB & 4, 4-DDT PRESENTING NO ENVIRONMENTAL RISKS. CASE CLOSED.			
BARBOSA'S AUTO CENTER 400 Railroad Ave	UST Winters	224 Gasoline	Open
DURING TANK REMOVAL SOIL CONTAMINATION FOUND. EXPLORATORY EXCAVATING TO 19 FT INDICATES INCREASING LEVELS OF CONTAMINATION. Additional investigation requested by the CVRWQCB August 2002. RBCA submitted Dec 2002.			
BARTHELS MOBILE HOME PARK Barthel Lane	HM Davis	4 1,1-Dichloroethene	Closed
ELEVATED LEVELS FOUND IN DRINKING WATER WELL. ASSESSMENT CONDUCTED AT NEIGHBORING MOLLER CORP, 1222 RESEARCH PARK DRIVE IN PROGRESS. FILE WAS COMBINED WITH ASSESSMENT (H 75). MOBIL HOME PARK IS NOW ON CITY WATER, WELL HAS BEEN DESTROYED. ASSESSMENT HAS BEEN COMPLETED, FILE CLOSED, AND COMBINED FILE ARCHIVED TO 3473HWG. File archived in December 2003 as 3473HWG.			
BEACON 29770 CR 8	HM Dunnigan	372 Diesel	Closed
SPILL OF 75 GALLONS & DISCHARGE OF DIESEL CONTAMINATED OIL WATER SEPERATOR GRIT.			
BEACON #694 USA Petroleum #3088 1001 Sacramento Ave	UST W. Sac.	222	Closed
File moved to L5583 in December 2002. Please see L 5583 for all data			

Facility	File/Number	Status	Comments	
BEACON #694 USA Petroleum #3088 1001 Sacramento Ave	UST W. Sac.	5583 B Gasoline	Closed	FILE B 1988 TO PRESENT: QUARTERLY GROUNDWATER MONITORING IN PROGRESS. SOIL VAPOR EXTRACTION IN DESIGN PHASE.
BEACON #694 USA Petroleum #3088 1001 Sacramento Ave	UST W. Sac.	5583 C Gasoline	Closed	FILE C: 1993 REPORTS - SOIL VAPOR EXTRACTION NEVER IMPLEMENTED.
BEACON #694 USA Petroleum #3088 1001 Sacramento Ave	UST W. Sac.	5583 E Gasoline	Open	FILE E: 1998/2000 data: PLUME IS DIMINISHING. CHANGED QUARTERLY MONITORING TO SEMI MONITORING. MONITORING CONTINUING. CVRWQCB is the lead agency. MTBE is present in several wells up to 33,000 ppb. Additional investigation required by the CVRWQCB in Nov 2002. Workplan for additional investigation approved January 2003
BEACON #694 USA Petroleum #3088 1001 Sacramento Ave	UST W. Sac.	5583 D Gasoline	Closed	FILE D: 1994 REPORTS - NO REMEDIATION HAS OCCURRED - THEY WILL BE PRODDED.
BEACON #694 USA PETROLEUM #3088 1001 SACRAMENTO AVE	UST WEST SAC	5583 GASOLINE	REVISE	FILE F: MONITORING WELLS INDICATE THAT LATERAL AND VERTICAL EXTENTS OF GROUNDWATER PETROLEUM IMPACTS ARE ADEQUATELY DEFINED.
BEACON #694 USA Petroleum #3088 1001 Sacramento Ave	UST W. Sac.	5583 A Gasoline	Closed	FILE A PRE 1988: SOIL CONTAMINATION FOUND AFTER TANKS FAILED TESTING. TANK SYSTEMS REPLACED, HEAVILY CONTAMINATED SOILS EXCAVATED & REMEDIATED ON-SITE. BOTH SOIL & GROUNDWATER CONTAMINATION REMAINS. FILE CONTINUES TO 222B.
BEACON STATION #447 3 Main Street	UST Woodland	35		Please see file L 5582. All contents were moved to this file in December 2002.
Bechtel Fiber Optic Slurry Waste 2935 Jefferson Blvd	HM W. Sac.	435 Slurry	Closed	Complaint investigation of a water/soil slurry mix disposal from installation of fiber optic lines. RWQCB Waste discharge requirements were waived with conditions.
Bechtold Property 454 East St (North)	UST Woodland	145 Gasoline, Diesel	Open	L 145 - FILE A: PRE 1991 Investigation finds soil & groundwater contamination. Site has underground tanks, previously had aboveground tanks. FILE B 1991/1994: Investigation roughly defined plumes. Owners death stopped further action. Site was denied cleanup funds. FILE C 1995 - 2000 Correspondence File. FILE D 1997 - 1999 Quarterly Reports. FILE E: Problem Assessment Report (1997), In-Situ Bioremediation Pilot Test Workplan (1998), Corrective Action Plan (1999). FILE F: 2000 Data File - Soil Vapor Extraction is operating. Lateral and vertical extent of contamination remains undefined. Investigation in progress to complete the above and a feasibility study proposed to determine effective remedial alternatives. FILE G 2001 Data - Soil plume is defined, groundwater plume above 40 feet is defined, additional assessment required to complete deeper water zone plume definition. Soil vapor extraction shut down in March to allow water table recovery. Revisions to vapor extraction and air sparging have been completed and is in operation in 2002
BEL MART 855 F ST	HM W. Sac.	92 PAINT	Closed	File H 92 - Paint & related waste products disposed in pit. Contaminated soils excavated & disposed as hazardous waste. Case closed January 1991. File archived as 00040HWG in January 2004.

Facility	File/Number	Status	Comments	
BEMMERLY RANCH BIOSOLIDS I-505 & I-5	HM Dunnigan	281 Biosolids	Closed	NOTICE OF TENTATIVE WDR FOR PROJECT LOCATED ON BOTH SIDES OF I505 BETWEEN DUNNIGAN AND ZAMORA. APPLICATION BY TERR GRO, INC. FILE CLOSED.
BENETO TANK LINES 1875 South River Road	UST W. Sac.	42 Hydrocarbons	Closed	FILE L 42 - Soil and minor groundwater contamination by gasoline and diesel was discovered following the 1994 removal of 13 underground storage tanks and investigation of runoff area from card-lock dispensers. Extensive soil excavation removed most of the contaminated soils. Case closed December 1996 and file archived to 00042UTH in December 2003.
BENETO TANK LINES 4076 Seaport Blvd	HM W. Sac.	228 Sludge	Closed	ALLEGED DISPOSAL OF WASTE CLASSIFIER SLUDGE TO TRASH. INVESTIGATION PENDING STAFF AVAILABILITY. CASE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.
Beneto Tank Lines 4076 Seaport Blvd,	UST West Sacrame	2669 Diesel, Methanol, Xylene	Open	Sampling during UST upgrade, found contamination
BENETO/RELIABLE DIESEL 504 Harbor Blvd	UST W. Sac.	41 Oil	Closed	File L 41 - Soil contamination discovered during 1989 removal of a 8,000 gallons motor oil and 500 gallons waste oil tank. Soils exceeding 10 ppm were excavated and disposed. File closed June 1990. File archived to 00041UTH in December 2003.
Beoshanz Property 25635 CR 96	HM Davis	443 Chlordane	Closed	Chlordane was sprayed behind the baseboards of the Family room by the owner of the residence. Investigation determined that levels where below PRG. No further action required, case closed. Recorded in Envision, FA 4820
Best Western: Dunnigan CR 89	HM Dunnigan	422 Investigation: Sewage Ponds	Closed	H 422 - This file was moved November 2002 to the Water Program files.
Big J Gas/Sigma Gas & Food 845 East St	UST Woodland	373 Gasoline	Open	Files A - B: ABANDONED TANKS. REPORTS OF PIPING LEAKS UNKNOWN EXTENT. Tanks removed in April 2000. Groundwater sampling found gasoline, diesel and MTBE. CVRWQCB has assumed lead agency responsibility and directed site to conduct an investigation to determine the lateral and vertical extent of contamination. FILE SEALED BY DA.
BLUE SHIELD - SPRR SITE 663 Sixth St	HM Woodland	184 e Lead, Chromium, Hyrdocarbons	Closed	FILE A GENERAL FILE: PRE-DEVELOPMENT FOUND BURIED TANKS & HYDROCARBON CONTAMINATED SOILS. TANKS & SOILS EXCAVATED & DISPOSED IN 1933. FILE B: PHASE I & II ASSESSMENTS, 1993 REMEDIATION REPORT. GROUNDWATER FOUND TO CONTAIN GASOLINE ACROSS FROM EXXON STATION (SEE #L-83) & CHROMIUM & LEAD NEAR MCL AT SOUTH END. FILE C: ATTACHMENTS TO 1993 REMEDIATION REPORT. COUNTY & CITY TO CONSIDER FURTHER ACTION TO EVALUATE GROUNDWATER CONDITIONS. BLUE SHIELD DEVEOPMENT APPROVED TO PROCEED. FILE D: CLOSURE REPORT-HYDROCARBON REMEDIATION COMPLETED & APPROVED WITH CONDITIONS. NO FURTHER REQUIREMENTS FOR GROUNDWATER. CASE CLOSED
BOCKROTH DWELLING 1305 Tulip Lane	HM Davis	3 e Waste Oil	Closed	SON POURED WASTE OIL ON GROUND. SOIL WAS REMOVED AND DISPOSED. FILE CLOSED 04/04/87.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
BOWLSBY RESIDENCE 3482 Greenview Dr	UST Davis	55 Gasoline	Closed TANK FAILED AUG 1986 TEST. REMOVED MAY 1988. PRODUCT SUCTION LINE HAD A SMALL HOLE, SOIL REMEDIATION COMPLETED SEPT 1988. FILE CLOSED.
BOY SCOUT CABIN PROPERTY 616 First St	HM Davis	400 Diesel, VOC'S	Open PHASE II SITE ASSESSMENT REVEALS DIESEL IN SOIL AND GROUNDWATER.
BP STATION 1705 W Capitol Ave	UST W. Sac.	12 e Gasoline	Closed File L 12 - Three 8,000-gallon gasoline tanks were removed from the site and a waste oil tank apparently abandoned in place in 1996. Different consultants have completed several investigations but the site has not been thoroughly defied. However, there is enough data to indicate that the occurrence of subsurface contamination is spotty and minor in nature. Case closed by the CVRWQCB in June 1997. File archived to 00012UTH in December 2003.
BP STATION I-5 & CR 6	UST Dunnigan	249 Waste Oil	Closed SOIL CONTAMINATION FOUND DURING 1990 REMOVAL OF 1,000 GAL WASTE OIL TANK. CLEAN-UP COMPLETED. FILE CLOSED.
Brandenburger Property CR 32B (near I-80 onramp)	HM Davis	420 Petroleum	Open H 420 - Investigation of site of former gas station prior to purchase by the City of Davis. This is an old nuisance site at the east end of CR 32B and the onramp to I-80. SB permit issued to hand install 3 temporary shallow wells to be sampled and then abandoned by 9/25/00. No installation inspection, but will inspect abandonment.
Broadway Auto Service 7 - 2-31 W Capitol Ave & Merkley	HM W. Sac	459 Petroleum	Open File H 459: Surface soil contamination found during pre assessment sale. Soil Remediation Work Plan submitted November 2002.
BRODERICK PROPERTIES 900 E St	UST W. Sac.	362 Hydrocarbons	Closed FILE A GENERAL FILE 1987-1991: TWO UST LEAKS & OTHER SPILLS/DISCHARGES OF GASOLINE, WASTE OIL, & STEAM CLEANING WASTES HAVE BEEN DOCUMENTED. FILE B GENERAL FILE 1992-1997: SOME WASTE OIL CONTAMINATED SOIL EXCAVATED. ASSESSMENT CONDUCTED IN 1992. FINAL REMEDIAL ACTION PLAN DUE 1993. FILE C: contains August 1992 Soil and Groundwater Investigation Report and November 1993 Problem Assessment Report, Feasibility Study and Remedial Action Workplan. FILE D: Contains 1993 Site Status and Final Remediation Reports, and 1994 Site Closure Report. Case Closed. File scanned June 2003 to 362 UTH.
Broderick Properties CR 30	HM Davis	362 Standardized DTSC Permit	Open FILE A: FACT SHEET & DRAFT NEGATIVE DECLARATION FOR PROPOSED DTSC STANDARDIZED PERMIT FOR STORAGE AND TRANSFER OF HAZARDOUS WASTE.
BUCHANAN, MIKE 404 Fourth St	HM W. Sac.	164 Muriatic Acid	Closed AFTER CLEANING SWIMMING POOL, MR. BUCHANAN DUMPED 10 GALS OF ACID INTO STORM DRAIN. CASE REFERRED TO DA FOR PROSECUTION. CASE CLOSED.
BUDGET 8 MOTEL 4930 CR99W	UST Dunnigan	2272 Gasoline and Diesel	Open L 2272 - TANK CLOSURE OF TANKS NOT RECENTLY USED. SAMPLING FOUND CONTAMINATION UNDER DISPENSERS BUT NOT IN TANK EXCAVATION. CONTAMINATION APPEARS CONFINED TO SURFACE SOILS NEAR THE FORMER DISPENSERS. INVESTIGATION IN PROGRESS TO DELINEATE EXTENT, CONFIRM NO IMPACT ON GROUNDWATER. SOIL EXCAVATION UNDER CONSIDERATION.

Facility	File/Number	Status	Comments	
BUG SHOP, THE East St	HM Woodland	234 Solvents	Closed	FACILITY AT OLIVE TREE PLAZA SPRAYS DEGREASER ON VEHICLES & WASHES OFF INTO STORM DRAIN. INVESTIGATION PENDING STAFF AVAILABILITY. FILE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.
BUSH, DAVID AND JANINE 1120 GUM AVE	HM WOODLAND	476 H HYDRAULIC OIL	CLOSED	HYDRAULIC OIL FROM DRUM LEAKED ONTO ASPHALT AND SOIL N OF THE APL QUANSET HUT.
C & S BATTERY 860 RISKE LANE	HM WEST SACRA	477 LEAD	CLOSED	BATTERY RECYCLING COMPANY CAUSED LEAD CONTAMINATION IN SOIL.
C D F LEWIS MORAN FAC 5800 CHILES ROAD	HM Davis	456 Possiblel Pesticide	Open	SITE ASSESSMENT IN PROGRESS TO CHARACTERIZE AND OLD DISPOSAL SUMP.
C D F LEWIS MORAN FACILITY 5950 Chiles Rd	UST Davis	68 Gasoline & Diesel	Open	DURING REMOVAL OF UST OBVIOUS SOIL CONTAMINATION SITE OVEREXCAVATED & BACKFILLED. In 2002 MTBE was found in three of four GWMW's. RWQCB Issued a Cleanup & Abatement order for this site and further investigation is in progress in 2002 and a Notice of Violation in April 2003. RWQCB contact is Davis Staravek (916) 255-3073
C D F LEWIS MORAN FACILITY 5800 Chiles Rd	UST Davis	69 Gasoline	Closed	FILE 69: Soil and groundwater contamination found associated with a 550-gallon gasoline tank removed in 1989. This tank had failed tank testing. Soils were excavated, a soil vapor extraction system operated from Oct 1992 to Feb 1993. The release does not appear to extend beyond 65 feet north of the former UST basin. The RWQCB determined that "groundwater at the site will meet water quality objectives through natural attenuation prior to beneficial use of the groundwater at the site." Case closed November 1998, file archived to 69UTH in December 2003.
C F MOTORFREIGHT 900 F ST	HM W. Sac.	386 Gasoline, Diesel	Open	TANK TESTING FAILED THEREFORE UST WAS REMOVED JULY 25, 1996. PRELIMINARY INVESTIGATION & EVALUATION REPORT, SUBSEQUENT WORK PLANS,GROUNDWATER GAS MONITORING REPORTS, FIRST, SECOND, & THIRD QUARTERLY,MONITORING REPORTS CONTAINED IN THIS FILE.
CABLE CAR WASH 904 THIRD STREET	UST DAVIS	74 Ce GASOLINE, CHLORINATED SOLVE	OPEN	SEE RELATED FILES, H324, H369, H528
Cable Car Wash 904 Third St	UST Davis	74 Be Gasoline, Chlorinated Solvents	Open	1998\1999 DATA. Groundwater flow was to the SW, gasoline, benzene, toluene, ethylbenzene, xylene, MTBE were detected in one or more groundwater wells during the first quarter of 2002.
CABLE CAR WASH 904 Third St	UST Davis	74 Ae Gasoline, Chlorinated Solvents	Open	SEE RELATED FILE HM 324
Cache Creek Casino Hwy 16	HM Rumsey	462 General File	Open	General File for future issues - Waste water treatment issues were forwarded to the General Unit.

Facility	File/Number	Status	Comments	
CACHE CREEK RANCH CR 17B	UST Woodland	11 e Gasoline, Unleaded	Closed	FILE A: 1989 - 1994 Data, FILE B: 1995 - 1996 Data. CASE SUMMARY: The facility is an active tomato farm. One diesel tank was removed in 1989, investigation found soil and groundwater contamination. Approximately 17,000 cubic yards of soil was excavated and one additional tank was found and evidence of previous tanks observed. Two soil treatment cells were constructed and inoculated with nutrients, tilled, plowed, disked and irrigated during 1994 and 1995. Both primary and secondary hydrocarbon sources were removed resulting in a total removal of 99% of soil and groundwater hydrocarbons. The site was categorized as low risk through RBCA analysis in December 1995. Monitoring wells were removed in 1996 and No Further Action issued by the RWQCB and Yolo County in November 1996. Case closed. File archived to 2461UTH in December 2003.
CACHE CREEK/PUTAH CREEK Yolo County & Lake County	HM CAPAY	403 Mercury, Methylated	Open	GRANT GIVEN BY SWRCB TO STUDY ECOTOXICITY OF PUTAH/CACHE CREEK. ON GOING EXPECTED TO BE COMPLETED IN 2000.
CAIETTI'S TRUCK REPAIR 404 Harbor Blvd	HM W. Sac.	215 Petroleum	Closed	INVESTIGATION OF ALLEGATION FACILITY DISCHARGES PETROLEUM CONTAMINATED ABSORBANTS TO GARBAGE DUMPSTER. FILE CLOSED AFTER OPERATOR DEMONSTRATED APPROPRIATE DISPOSAL PRACTICES.
CAL CENTRAL PRESS (FORMER) 3704 Parkway Ave	HM W. Sac.	318 Investigation	Closed	WORKPLAN PROPOSAL FOR LIMITED SOIL INVESTIGATION TO EVALUATE POTENTIAL FOR PRESENCE OF METALS, HYDROCARBONS, VOLATILE ORGANIC COMPOUNDS & ACIDIC OR BASIL CONDITIONS.
CAL DEPT OF WATER RESOURCES 1450 Riverbank Rd	UST W. Sac.	73 e Gasoline	Open	LEAK REPORTED JUNE 1986. STATUS UNCLEAR.
CAL HWY PATROL ACADEMY 3500 Reed Ave	UST W. Sac.	64 Gasoline	Open	TANK LEAK DISCOVERED AND SOIL REMEDIATION COMPLETED NOV 1985. FILE CLOSED. Soil boring installed for Tracer testing in January 2001 found floating product on groundwater. File reopened. Tanks tested and one tank failed uluage test. Further investigation and remediation will be required
CAL TRANS 4761 WEST CAPITAL AVE	HM W. Sac.	410 Petroleum	Open	During a pre-acquisition investigation by Cal Trans found soil and groundwater impact from diesel. Site is at the I-80/Enterprise and W Cap Ave interchange including parcels with 4761 and 4891 W Cap Addresses. Proposing to inject O2 generating compounds, install MW's and monitor
CAL TRANS HWY 16 & Yolo St	UST Esparto	3885 Diesel, Gasoline	Closed	SOIL CONTAMINATION DISCOVERED DURING UST REMOVAL & EXCAVATED TO NON-DETECTABLE LEVELS. CASE CLOSED 1992. File archived as 3885UTH in December 2003. This was formerly file number 70.
CAL TRANS - ESPARTO	UST Esparto	70 A Gas, Diesel	Closed	File was inadvertently deleted in the Envision Database. It was re-entered as facility 3885. See 3885 for this record.
CAL TRANS (FORMER W SAC FAC) 801 Riske Ln	HM W. Sac.	399 Diesel	Open	MINOR DIESEL CONTAMINATION FOUND IN GROUND WATER IN A PARTIAL ASSESSMENT.

Facility	File/Number	Status	Comments	
CAL TRANS (OLD WDLD YARD) 205 Main St (West)	UST Woodland	71 Gasoline, Diesel	Closed	File L 71 - In 1988 one diesel and one gasoline UST's were removed. Remediation included soil excavation, soil vapor extraction, and groundwater pump and treatment. Remaining hydrocarbons are degrading, the plume appears stable, no municipal water supply wells are threatened and the case was closed in June 2000. Fiile was archived to 71UTH in December 2003.
CAL TRANS (W SAC) 1040 South River Road	UST W. Sac.	72 Diesel	Open	File L 72 - 2,000 gal diesel tank failed tank testing Nov 1994. Product removed from tank. Tank removed and minor soil contamination was excavated and used by Caltrans as road base. Case closed March 1995. File archived to 00072UTH in January 2004.
CAL VET DIAGNOSTIC CR 28H & CR 104	HM Davis	158 Medical Waste	Closed	ALLEGED MEDICAL WASTES DISPOSED AT YOLO CENTRAL LANDFILL. CASE REFERRED TO DISTRICT ATTORNEY. CASE CLOSED. FILE SEALED TO PUBLIC ACCESS BY DISTRICT ATTORNEY.
CALDERON, JORGE 1711 Sixth St	HM Woodland	154 Waste Oil	Closed	A GALLON OF WASTE OIL INTENTIONALLY DUMPED. CASE SEALED PENDING DISTRICT ATTORNEY'S INVESTIGATION. CASE CLOSED.
CALGENE INC 1920 Fifth St	HM Davis	82 HW Violations	Closed	File H 82 - Dept of health services 1989 report of violations & schedule for compliance. Violations include lack of written training records & storage of waste in unlabeled drums. Case closed in 1991. File archived to 004016HWG in January 2004.
CALGENE INC 1920 Fifth St	HM Davis	181 Laboratory Chemicals	Closed	FIRE IN TWIN LAB RESULTED IN RELEASE OF LAB REAGENTS INTO RUNOFF, MOSTLY FROM WATER SYSTEM PIPE RUPTURE. DRY CITY POND IMPACTED. AFFECTED SOILS REMOVED. FILE CLOSED.
CALIFORNIA CASCADE INDUSTRIES 1492 Churchill Downs	HM Woodland	65 Chromium VI, Arsenic, Copper	Open	RUPTURED PIPE RESULTED IN DISCHARGE TO FRENCH DRAIN. DRAIN & SOIL EXCAVATED, GROUNDWATER PUMPED FOR A BRIEF PERIOD IN 1987. RWQCB IS LEAD AGENCY. Also known as. Western Wood Treatment. Currently monitoring 16 wells for pH, specific conductance, copper, chromium, arsenic, sodium, potassium and magnesium on a biennial basis. Eastern extent of contamination is not fully defined. Site remediation was initiated during 2000. Groundwater extraction, treatment with calcium polysulfide and injection is occurring intermittently as of June 2002 ending in March 2003. Groundwater monitoring continues in 2003 while other remedial alternatives are being evaluated.. RWQCB contact is Amy Terrell (916) 255-3080.
California Distribution Center 2080 Enterprise Ave	HM W. Sac.	263 Diesel	Closed	Approximately 20 gallons of diesel were release due to overfilling of aboveground tank. Vacuum truck was used to remove diesel from a drainage ditch, 10 cubic yards of adsorbent was used to remove diesel from parking lot surface, and 6 inches of soil were removed from ditch. Contaminated soil, adsorbent and water were disposed as hazardous waste
CAMPBELL RESIDENCE 52333 Netherlands Rd	UST Clarksburg	2832 Diesel	Closed	NO LEAKY FILE CREATED. SEE DATA IN UST FILE #2832, BLUE LABEL. 60 YDS DIESEL CONTAMINATED SOIL EXCAVATED DURING SEP '96 REMOVAL OF TWO 500 GAL USTS. SIDEWALL HAVE LESS THAN 100 PPM TPHD AFTER EXCAVATION. FILE CLOSED
CAMPBELL SOUP Mace Blvd	UST Davis	514 Diesel	Closed	MINOR LEAK DISCOVERED DURING DEC 1988 TANK REMOVAL. SOILS EXCAVATED TO LESS THAN 250 PPM. SOILS AERATED. SITE CLOSED DEC 5, 1989. File archived to 514UTH in November 2003.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
CAPAY CANYON RANCH 14650 CR 87	HM Esparto	449 Phostoxin	Open
CAPITOL PLATING 319 Third St	HM W. Sac.	7 Ce Metals, Chlorinated Solvents	Open
CAPITOL PLATING 319 Third St	HM W. Sac.	7 De Metals and Chlorinated Solvent	Open The site is a former metal plating facility on the east side of 3rd Street near the corner of Second Street. During several site investigations between 1997 and 1999, ground water has been found to be impacted by chromium, nickel, copper, arsenic, cyanides and 1,2-DCA and possibly cadmium. Groundwater flow in 2nd Qtr 2002 was to the east. Quarterly monitoring continues under the direction of CVRWQCB.
CAPITAL CIGAR & CANDY (FORMER) 1105 Terminal St	UST W. Sac.	79 Gasoline, Diesel	Closed Two USTs removed in 1997, both had numerous holes and visible corrosion along the bottom. Soil contamination appears to be primarily within 5 feet of UST cavity. Water sampling results indicate the plume is stable and defined laterally and vertically. No further action letter issued by State RWQCB January 16, 2001. File Closed. AKA EII Properties. File scanned/archived to adobe UTH 79 in July 2003.
CAPITOL CITY APARTMENTS 1500 Madrone Ave	HM W. Sac.	241 Unknown	Closed REPORTED 2 PARTIALLY FILLED DRUMS LOCATED IN BACK OF MAINTENANCE SHED. DRUMS NOT LEAKING BUT IN POOR CONDITION. INVESTIGATION PENDING STAFF AVAILABILITY. CASE CLOSED DUE TO LACK OF TIMELY INVESTIGATION
CAPITOL CITY TRUCK-BUS REPAIR 4300 W Capitol Ave	HM W. Sac.	159 Petroleum, Lead	Closed PRE-SALE SITE ASSESSMENT FOUND SURFACE SOILS WITH ELEVATED LEAD & PETROLEUM HYDROCARBON LEVELS. SALE FELL THROUGH. NO CLEANUP CONDUCTED. REMEDIATION MAY BE REQUIRED PRIOR TO DEVELOPMENT. Case was combined with adjacent properties. Case closed. File archived as 600UTH in December 2003.
CAPITOL COORS COMPANY 2424 Del Monte St	UST W. Sac.	80 Diesel	Closed LEAK FOUND DURING REMOVAL OF TWO TANKS THAT HAD PASSED TANK TESTS. VISIBLE HOLES IN TANKS. SOIL & GROUNDWATER CLEAN-UP COMPLETED. FILE CLOSED.
CAPITOL PLATING 319 Third St	HM W. Sac.	7 Ae Metals	Closed GENERAL CORRESPONDENCE. PLUS REPORTS 1998-1999 REPORTS AND WORKPLANS. Investigation of soil and groundwater conditions at former Plating Facility which last operated in 1985.
CAPITOL PLATING 319 Third St	HM W. Sac.	7 Be 1,2 DCA, Chromium, Nickel	Open DEC 1999 TO PRESENT. PROP 65 ISSUED 12/99 FOR ELEVATED 1,2 DCA, NICKEL & CHROM IN GROUNDWATER. INVESTIGATION CONTINUES.
CARGIL INC Port of Sacramento	UST W. Sac.	82 Diesel	Closed Soil contamination observed during 1988 removal of 10,000 gallon diesel tank. Soils were over excavated and aerated on site. Groundwater contains low levels of diesel and waste oil. No wells are located within 2000 feet of the site, no fuel oxygenates or additives were detected. The State RWQCB issued a No Further Action Required letter in October 2000. Site is located with the Port of Sacramento property. File closed. File archived to Adobe file 82 UTH in July 2003.

Facility	File/Number	Status	Comments	
CARLON 1776 Beamer St (East)	HM Woodland	284 Hydrocarbons	Closed	ELEVATED LEVELS OF LONG CHAIN HYDROCARBONS FOUND DURING PRE DEVELOPMENT ASSESSMENT OF VACANT LOT. ENTIRE AREA OF CONTAMINATION WILL BE UNDER A PROPOSED WAREHOUSE AND ASPHALT PARTKING LOT. NO FURTHER ASSESSMENT OR REMEDIATION REQUIRED. FILE CLOSED.
CARRANZA TEXACO 1123 Main Street (East)	UST Woodland	83 Diesel, Gasoline	Open	Fuel loss was detected from daily inventory reconciliation records in May 1991. Source identified as delivery piping in March 1992. Tanks and piping systems replaced in 1992, soils over excavated. Assessment of soil and groundwater conditions continues. File A - 1991-1993, File B & C 1994 reports and data, File D 1995 to 1998 data, File E 1999 to 2001 data. File F 2002 to 2003 Data. See Sire File FA 83 & FA 3229, it's not all scanned yet. Also see H-83.
CARTHEN, COE Jefferson Blvd	HM W. Sac.	11 e Waste Oil	Closed	WASTE OIL USED TO KILL WEEDS & NO OIL/WATER SEPARATOR FOR STEAM CLEANING WASTE. ORDERED TO REMOVE CONTAMINATED SOIL & INSTALL SEPARATOR OF SEWER DISCHARGE.
CASSIL, JIM (WELL) RT 1 Box 294A	HM Winters	8 e Trifluralin	Closed	TRIFLURALIN FOUND IN GROUNDWATER AT 0.01 PPB. NO ACTION LEVEL FOR THIS CHEMICAL HAS BEEN SET. EIGHT NEARBY WELLS ALL TESTED NON DETECTABLE. NO ACTION REQUIRED. FILE CLOSED JUNE 1987.
CELONI OIL - WOODLAND 1121 Gum Ave	UST Woodland	86 Gasoline	Closed	A UST was removed and contaminated soil excavated. Soil and groundwater investigations have defined the lateral and vertical extent of the plume. The plume trends southwest-northeast and appears to be stable. Oxygenates are absent in groundwater except MtBE in one well, the down gradient well, at 1.1 ppb. The concentration of MtBE in this well has ranged from 0.3 to 2.3 since November 1999, showing the plume is relatively stable. A sensitive receptor survey showed no water supply wells or surface water within 2,000 feet of the site. A trend analysis of hydrocarbon concentrations in groundwater shows that hydrocarbons are degrading and do not appear to be a threat to water supplies and human health. A No Further Action Required letter was issued by the Central Valley Regional Water Quality Control Board in October 2001. File scanned and incorporated into file number 86UTH.
CEN-CAL WALLBOARD SUPPLY 880 South River Road	UST W. Sac.	87 Gasoline	Closed	File L 87 - Minor soil contamination observed during Jan 1990 removal of 2000 gal gasoline tank. All soils with 10-PPM TPH or more was excavated and soils were aerated onsite. Case closed June 1990. File archived to 00087UTH in January 2004.
CENTRAL MOTORS College & Lincoln Ave	UST Woodland	90 Gasoline	Closed	File L 90 - Soil & groundwater contamination found during 1989 removal of a 300 gallon UST. Soils excavated to 1,600 ppm. Groundwater was evaluated, and trace levels of hydrocarbons were observed. Case closed in 1993. Since that time the structure was removed, additional soils were excavated, and lot has been paved by the City of Woodland and is now (2003) a parking lot. File archived to 00090UTH in January 2004.
CENTURY BUICK PONTIAC 333 Main St	UST Woodland	91 Gasoline	Open	FILE A: Soil contamination discovered during Dec 1989 removal of 550 Gal tank. Located inside shop structure. Site contamination workplan approved. FILE B: 1994 data - quarterly monitoring reports. FILE C: Problem assessment report, former onsite tanks outside facility implicated as possible additional sources, offsite migration detected. FILE D: 1995 data. FILE E: Additional investigation completed, other possible sources identified. FILE F: Investigation expands to adjacent sites. FILE G: 1997 data, RBCA completed, corrective action levels proposed. Groundwater plume defined to be 600 ft by 400 feet at 27 feet below ground surface extending offsite. File H and J includes 1998/1999 data, case transferred to the CVRWQCB. Vapor extraction and air sparging system began operation in 1998 and continued operation through 2000. File K - 2000 data. Air sparging, vapor extraction and groundwater monitoring continues.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
CESAR CHAVEZ ELEMENTARY SCHOOL 1221 ANDERSON ROAD	HM Davis	431 Asbestos	Closed SCHOOL DISTRICT EMPLOYEES REMOVED ASBESTOS CONTAINING FLOOR TILE IMPROPERLY, RESULTING IN POTENTIAL EXPOSURE TO STUDENTS & STAFF.
CHANGE OF PACE/DAVE MIRAMONTES 2217 Shenadnoah	HM Davis	273 Ink, Solvent & Degreaser	Closed A COMPLAINT THAT SOLVENT, INK, AND DEGREASER ARE BEING DUMPED ONTO THE GROUND. investigation FOUND NO EVIDENCE OF DISCHARGE. CASE CLOSED.
CHARTER, DAVID 32030 CR 10	HM ZAMORA	458 DRUG LAB WASTE	NEW
CHECA, HELIODORO aka Woodland Plaz 37493 SACRAMENTO AVE	HM YOLO	451 WASTE OIL	CLOSED FORMERLY THE SITE OF AN AUTOMOTIVE REPAIR SHOP. WASTE OIL FOUND ON SOIL IN ONE LOCATION. OWNER WAS ASKED TO REMOVE THE CONTAMINATED SOIL. CONTAMINATED SOIL SATISFACTORILY REMOVED ON 05/18/02. THE SOIL WAS DISPOSED OF AT THE HOUSEHOLD HAZARDOUS WASTE DAY AT THE YOLO COUNTY LANDFILL ON 05/18/02.
CHEVRON 1381 W Capitol Ave	UST W. Sac.	13 Ae Gasoline	Closed QUARTERLY MONITORING OF GROUNDWATER CONTINUES. WELLS COMPLETED IN THE DEEPER ACQUIFER ARE NON-DETECT OR NEARLY NO SINCE GROUNDWATER ROSE THIS SPRING. MCL FOR BENZENE EXCEEDED IN ONE SHALLOW WELL.
CHEVRON 1381 W Capitol Ave	UST W. Sac.	13 Be Gasoline	Open FILE B 1994 DATA: QUARTERLY MONITORING CONTINUES TO FIND BENZENE EXCEEDING MCL FOR DRINKING WATER IN 2 UPPER AQUIFERS. NO ACTIVE REMEDIATION IN OR PROPOSED.
CHEVRON 304 Main St	UST Woodland	93 Petroleum	Closed File L 93 - Vapor study found hydrocarbons & soils appeared impacted during 1990 tank removal and upgrade. Waste oil found near waste oil tank also removed. Contaminated soils excavated for off site treatment. Groundwater monitored 2 yrs. RWQCB closed case August 1993. File archived in January 2004.
CHEVRON # 9-1420 1935 ANDERSON ROAD	UST DAVIS	95 De GASOLINE	OPEN MTBE FOUND IN MW-6 & MW-7. See FA 3412
CHEVRON #9-1420 1935 ANDERSON RD	UST Davis	95 Ce Gasoline	Open FILE C-2000: QUARTERLY MONITORING CONTINUES WITH HYDROCARBONS PRESENT IN TWO WELLS. Investigation continued through 2001. The lateral extent of the plume has not been defined. See FA 3412
CHEVRON #9-1420 1935 Anderson Rd	UST Davis	95 Ae Gasoline	Closed FILE A-1995/1997 DATA- SOILS OVER 1800 PPM TPH REMOVED DURING 1995 TANK REMOVAL. 1997 ASSESSMENT CONFIRMS GROUNDWATER IMPACT. SITE ASSESSMENT REQUIRED. See FA 3412
CHEVRON #9-1420 1935 ANDERSON RD	UST Davis	95 Be Gasoline	Open FILE B-1998/1999: QUARTERLY MONITORING CONTINUES WITH HYDROCARBONS PRESENT IN TWO WELLS. Investigation report in August 1999 indicates additional investigation needed to fully evaluate the extent of dissolved-phase hydrocarbons. See FA 3412

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
CHEVRON #9-2446 CR 6, I-5	UST Dunnigan	96 Gasoline, Oil	Closed File L 96 - Four underground tanks were removed in 1994; soils excavated and aerated onsite then removed for offsite treatment. Case closed in October 1995. File archived to 00096UTH in January 2004.
CHEVRON #9-5043 (WINTERS) 999 East Grant St	UST Winters	94 A Hydraulic Fluid	Closed L 94 A HYDRAULIC OIL LEAK FROM EXEMPT SMALL TANK. SOME CONTAMINATED SOIL EXCAVATED, REMAINING CONTAMINATION RESTRICTED BY CONFINING CLAY LAYER. FURTHER MIGRATION DEEMED UNLIKELY. FILE CLOSED JUNE 1989.
CHEVRON #9-5043 (WINTERS) 999 East Grant St	UST Winters	94 B Gasoline, MTBE	Closed FILE B: Soil contamination found in soils during 1996 tank replacement. Investigation found limited soil impact detected under dispenser island, GW impact limited to small area of former (&new) tank & dispenser islands at low levels. Quarterly monitoring. FILE C-1998/99 DATA. MTBE exceeded 10,000 PPB in one well. FILE D-2000 DATA. MTBE exceeded 14,000 PPB in one well. FILE E - 2001 DATA. Lateral and vertical extent of contamination not delineated. A soil vapor extraction system began operation early 2002. Additional investigation was required to evaluate the hydraulic connection between water layers, extent of MTBE, and to investigate methods for removing MTBE from ground water.
CHEVRON #9-5631 980 Olive Dr	UST Davis	98 C Hydrocarbons/Solvents	Open FILE C: 1992 TO 1995 - QTR MONITORING OF 6 WELLS CONTINUES. 3 REMAIN ND BUT ONE WELL HAS TRACES OF XYLENES & TULUENE AND 2 WELLS PERSISTANTLY HAVE 1,2-DCA PRESENT.
CHEVRON #9-5631 980 Olive Dr	UST Davis	98 B EDC	Closed FILE B 1990-1991: PHASE II INVESTIGATION FOUND TRACE LEVELS OF EXYLENES & CHLOROFORM IN ONE SOIL BORING. PCE & 1,2-DCA FOUND IN GROUNDWATER. QUARTERLY MONITORING CONDUCTED. FILE CONTINUES.
CHEVRON #9-5631 980 Olive Dr	UST Davis	98 A Gasoline	Closed FILE A 1988-1989: GASOLINE & WASTE OIL TANKS REMOVED DURING 1988 STATION CLOSURE. TWO INVESTIGATIONS FOUND EDC PRESENT ABOVE MCL IN ONE WELL. FILE CONTINUES.
CHEVRON #9-6726 4800 W Capitol Ave	UST W. Sac.	101 e Hydrocarbons	Open L 101 File A Pre 2001 Data, File B 2001 Data: SOIL & GROUNDWATER IMPACT OBSERVED DURING TANK REMOVAL. GROUNDWATER WAS PUMPED & TREATED FROM THE EXCAVATION. RWQCB is lead agency, requesting additional investigation 7/2000. Investigation continues in 2002.
CHEVRON #9-9148 4475 Chiles Rd	UST Davis	99 B Gasoline	Closed FILE 99B REMOVAL REPORTS: FILE CONTAINS DETAILED REPORT OF TANK REMOVALS & INSTALLATION OF GROUNDWATER MONITORING & EXTRACTION & VAPOR MONITORING & EXTRACTION SYSTEM. SYSTEMS NEVER ACTIVATED.
Chevron #9-9148 4475 Chiles Rd	UST Davis	99 E Gasoline	Open FILE 99E - 1998 - 2000 Data. File F - 2001 Data. Quarterly monitoring continued. As of October 2002 the CVRWQCB determined that soil contamination has been defined. Both vertical and lateral extent in groundwater has not been defined. Further site investigation continued through 2002.
CHEVRON #9-9148 4475 Chiles Rd	UST Davis	99 D Gasoline	Closed FILE 99D - 1996 & 1997 Data. Additional investigation conducted, quarterly monitoring continued.

Facility	File/Number	Status	Comments	
CHEVRON #9-9148 4475 Chiles Rd	UST Davis	99 A Gasoline	Closed	FILE 99A CORRESPONDENCE: UST LEAK RESULTING IN SOIL & GROUNDWATER CONTAMINATION. YOLO COUNTY ORDERED ASSESSMENT JUNE 25, 1992. SECOND ORDER ISSUED NOV 1992. AUG 94: PAR IN THE WORKS.
CHEVRON #9-9148 4475 Chiles Rd	UST Davis	99 C Gasoline	Closed	FILE 99C - 1995 Data
CHEVRON (LANDERS) 9-2597 I-5 & CR 102	UST Woodland	97 Petroleum Hydrocarbons	Open	FILE 97A 1987-1991 DATA: Gasoline & waste oil found in soils & groundwater. Groundwater monitoring wells installed. Waste oil tank removed. FILE 97B 1992-1994 DATA: Groundwater monitoring being conducted quarterly. FILE C: 1995 DATA - Qtr GW monitoring continues. Three wells to be monitored annually. FILE D: 1998 Groundwater monitoring continues. Gasoline levels continue to decrease in two wells & is non-detectable in the remaining three. MTBE is present in three wells. FILE E 1999/2000: Five USTs and contaminated were removed from this site. Site investigations 3show that relatively low concentrations of hydrocarbons affect soil beneath the site, but relatively high concentrations of gasoline hydrocarbons, including MTBE, affect ground water. Gasoline hydrocarbons in ground water may be from a 450 gallon release in 1989, and have migrated beyond the location of the release, and threaten an onsite water supply well within 60 feet of the plume. A workplan for further investigation was approved by the RWQCB to be submitted by March 2000. Modeling was completed in September 2000 that the consultant believes that no further action is required. RWGCB requested additional information in October. FILE F 2001 Data - In May 2001 RWQCB requests testing for Chromium six near former waste oil tank and notes MTBE has not been fully characterized.
CHEVRON (RICK'S) #9-3284 1350 Jefferson Blvd	UST W. Sac.	100 Gasoline, Diesel	Closed	File L 100 - Gasoline contaminated soils from underground tanks removed in 1987 was excavated to less than 10 PPM and aerated on site. Minor groundwater contamination was observed, no MTBE, monitored for 10 years and does not appear to be migrating. Case closed in November 1997. File archived in January 2004 to 100UTH.
Chevron (Video & Gas) (Ricky's) 1015 Jefferson Blvd	USTe W. Sac.	221 Gasoline, BTEX,MTBE	Open	TANK REMOVAL REVEALED GASOLINE CONTAMINATION. WORKPLAN FOR SITE INVESTIGATION IN PROCESS OF BEING PREPARED. RWQCB taking the lead May 2000. Investigation in progress to define extent of MtBE and gasoline hydrocarbons is groundwater. MTBE still not defined as of October 2003. RWQCB contact is David Stavarek (916) 255- 3073.
CHEVRON FUEL TERMINAL HWY 99	HM DUNNIGAN	23 Ke HYDROCARBONS	OPEN	See FA 3892
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 De Hydrocarbons	Closed	FILE D: 1993/1995 DATA - SEMI ANNUAL MONITORING CONTINUES. DIESEL WAS DETECTED IN ONE WELL, 1,2-DCA IN TWO OTHERS, GASOLINE, BTEX, & 1,2-DCA IN A FOURTH - ALL OTHERS ARE NO. See FA 3892
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 Ce Hydrocarbons	Closed	FILE C 1992: RWQCB INITIATED ACTION TO DETERMINE REMEDIAL ACTIONS, GROUNDWATER MONITORING CONTINUES. See FA 3892
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 He Hydrocarbons	Closed	FILE H: 1999 DATA - MONITORING CONTINUES. CVRWQCB IS LEAD AGENCY - CONTACT IS MS. GAIL WIGGETT. NO FREE PHASE HYDROCARBONS WERE DETECTED DURING 1999. DISSOLVED HYDROCARBONS AS TPHG WERE OBSERVED IN GROUNDWATER UP TO 5,220 PPB IN MW-1 DURING THE THIRID QUARTER & TPHD AT 2,689 PPB. See FA 3892

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 Ge Hydrocarbons	Closed FILE G: 1998 DATA See FA 3892
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 Fe Hydrocarbons	Closed FILE F: 1997 DATA - QUARTERLY MONITORING CONTINUES. WATER SUPPLY WELL IS CONTAMINATED. LEVELS STILL EXCEED 8,500 PPB TPH AND UP TO 1,000 PPB BENZENE. See FA 3892
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 Ae Hydrocarbons	Closed FILE A 1988-1990: ABOVE GROUND BULK FUEL FACILITY. FACILITY HAS FIVE ABOVEGROUND FUEL TANKS. THIS FACILITY HAS OPERATED SINCE 1913. SOIL & GROUNDWATER CONTAMINATION CONFIRMED. LEVELS ARE LOW. EXTENT LIMITED. FILE CONTINUES TO 8923B. See FA 3892
Chevron Fuel Terminal #1001546 CR 6 & HWY 99	HM Dunnigan	23 Ee Hydrocarbons	Closed FILE E: 1996 DATA See FA 3892
Chevron Fuel Terminal #1001546 4040 CR 89	HM DUNNIGAN	23 Je Hydrocarbons	OPEN ADD NEW J FILE
Chevron Fuel Terminal #1001546 (Celoni) CR 6 & HWY 99	HM Dunnigan	23 Ie Hydrocarbons	Closed FILE J: 2000 DATA - MONITORING CONTINUES. CVRWQCB IS LEAD AGENCY. Monitoring and Reporting Program issued by CVRWQCB August 2002. Cleanup and Abatement Order issued September 2002. The CVRWQCB requested a workplan for site assessment as part of the C& A Order to delineate the lateral and vertical extent of contamination. Workplan approved with comments on Nov 13, 2002. See FA 3892
Chevron Fuel Terminal #1001546 (Celoni) CR 6 & HWY 99	HM Dunnigan	23 Be Hydrocarbons	Closed FILE B 1991: GROUNDWATER MONITORING OF WEATHERED HYDROCARBONS. See FA 3892
Chevron I-5 5 Main (West)	UST Woodland	347 MTBE	Closed L 347 - Initial contamination found in one sample at 3 feet (MTBE 4600 MG/KG). Soils were excavated in an 8 by 8 by 5-foot area. Samples at excavation limits were non-detectable. No further action required. File scanned to FA 347 UTH.
CHIEF'S AUTO PARTS 1400 W Capitol Ave	HM W. Sac.	235 Waste Oil	Closed ALLEGED SPILL TO GROUND NEAR DUMPSTER NOT PROPERLY CLEAN-UP. INVESTIGATION PENDING STAFF AVAILABILITY. THIS FILE IS CLOSED.
CHIMA'S MARKET CR 89 & I-5	UST Dunnigan	102 Waste Oil	Closed During routine tank removal, samples collected showed waste oil and diesel constituents present. Soils were excavated and treated. Case closed September 1995. File archived to 00102UTH in January 2004.
CHIMA'S TEXACO CR 89 & I-5	HM Dunnigan	146 Diesel	Closed DIESEL JOBBER OVERFILLED ABOVE GROUND DIESEL TANK. SOIL EXCAVATED, STOCKPILED ON PLASTIC, & COVERED. SOIL TRANSPORTED & DISPOSED PROPERLY. FILE CLOSED.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
CHRIS FULLER PAINTS G St	Davis	HM 238 Varnish	Closed	REPORT OF DISPOSAL OF VARNISH INTO CARDBOARD WHICH LEAKED TO GROUND. FILE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.
CHUCK'S USED TRUCK PARTS 512 Harbor Blvd	W. Sac.	HM 101 Waste Oil	Closed	SURFACE SOIL CONTAMINATION WAS EXCAVATED & DISPOSED AS HAZARDOUS WASTE. OCT '93 FILE REOPENED TO INVESTIGATE ALLEGATION FACILITY DISPOSES CONTAMINATED MATERIALS TO GARBAGE DUMPSTER. SITE VISIT CONDUCTED, OPERATOR ISSUED WARNING. FILE CLOSED.
Cigna Esparto, Valle Vista Fa 26361 CR 25, W Of CR 76	Esparto	UST 500 Diesel, Gasoline	Open	DISPENSOR LEAK FOUND DURING TANK REMOVAL. SOME SOIL EXCAVATION COMPLETED. EXTENT OF REMAINING SOIL & GROUNDWATER CONTAMINATION UNDEFINED. RWQCB lead agency Nov 99. Four of six monitoring well and the domestic well were located in late 2001 and sampled. TPH as gasoline and diesel were still present in two monitoring wells and diesel found in the domestic well 370 down gradient of the former tanks. Further investigation required by the CVRWQCB in Sept 2002.
CIRCLE K DAVIS (TOSCO) 1930 LAKE BLVD	Davis	UST 461 Hydrocarbons	Open	GASOLINE LEAKAGE DISCOVERED DURING UP-GRADE. EXTENT TO BE DETERMINED WORKPLAN IN PROGRESS.
City of Davis Fifth and G Streets	Davis	HM 114 A PCE & Gasoline	Closed	1991 STUDY CONDUCTED BY CITY PARTIALLY DEFINED COMMINGLED SOLVENT & GASOLINE GROUNDWATER PLUMES. CITY DIRECTED BY RWQCB TO SUBMIT QUARTERLY REPORTS & DEFINE THE PLUMES.
City of Davis Fifth and G Streets	Davis	HM 114 E HVOC'S	Closed	H 114E: 1997 - 1998 Data
City of Davis Fifth and G Streets	Davis	HM 114 H HVOC'S	Closed	H 114H: 2001 - 2002 Data
City of Davis Fifth and G Streets	Davis	HM 114 D TPH, BTEX, TCE, PCE	Closed	FILE D 1995 -1997 Data. INTERIM REMEDIAL ACTION REPORT. PROPOSED ADDITIONAL INVESTIGATION & SVE SYSTEMS FOR BOTH PLUMES. File E & F 1997 - 1999 data. File G - 2000 data: Investigation and site monitoring continues, extraction wells have been installed and pretreatment carbon units are removing HVOCs from purge water prior to discharge to the City of Davis sanitary sewer. System operated except for some down time for technical difficulties through 2001.
City of Davis Fifth and G Streets	Davis	HM 114 F HVOC'S	Closed	H114F: 1998 - 1999 Data - HVOC'S DETECTED IN DEEP WELLS. TREATMENT CONTINUES. CVRWQCB raised several questions about the groundwater extration and treatment system based on the results obtained during the 1st Qtr 2002 monitoring event.
City of Davis Fifth and G Streets	Davis	HM 114 C Petroleum, Chlorinated Hydroca	Closed	FILE C: 1995 DATA - TPH & BTEX SOURCE IDENTIFIED AS FORMER UST AT CORNER OF 5TH & G. PCE & TCE SOURCE APPEARS TO BE DRY CLEANERS AT 404 G ST.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
City of Davis Fifth and G Streets	HM Davis	114 G HVOC'S	Closed H114G 2000 - 2001 Data
City of Davis Fifth and G Streets	HM Davis	114 B Petroleum & Chlorinated Hydroc	Closed FILE B: 1994 DATA - PAR SUBMITTED WHICH DEFINES LATERAL EXTENT OF SOIL & GW CONTAMINATION. WORKPLAN TO DEFINE VERTICAL CONTAMINATION REQUESTED.
City of Davis Fifth and G Streets	HM Davis	114 I HVOC'S	Open H 114I: 2003 Data
CITY OF DAVIS PARKS	HM Davis	439 Arsenic	Closed
CLARK'S TRUCKING 2000 South River Road	UST W. Sac.	105 Diesel	Closed File L 105 - During routine tank removal diesel contamination was detected in soils. These were excavation and contamination removed. Case closed in November 1991. File archived in January 2004 to 00105UTH.
CLEDA MACDONALD TRUST 1271 W CAPITOL AVE	HM WEST SAC	463 PCE, TCE, PETROLEUM	OPEN Redevelopment property. Phase II assessment reveals solvent contamination in soil and groundwater. See related file H-440.
CLIFF'S AUTO CENTER & WRECKERS 3400 CR 99W	HM Dunnigan	150 Waste Oil, Gas, Diesel	Open INSPECTION FOUND SOIL CONTAMINATION & SEVERAL POSSIBLE DISPOSAL & FIRE CODE VIOLATIONS. HAZARDOUS WASTE STORAGE & SOIL CLEAN-UP COMPLETED. FILE CLOSED TO PUBLIC REVIEW BY DISTRICT ATTORNEY.
CLOUGH EQUIP CO 3202 W Capitol Ave	HM W. Sac.	15 Hydrocarbons	Closed File HM 15 - HYDROCARBON CONTAMINATED SOIL CLEAN-UP DURING PROPERTY SALE. COMPLETED DEC 1988. File archived as 4013HWG in December 2003.
CN Power Systems 1201 Churchill Downs	HM Woodland	471 Oil	Closed Pressure washer discharge.
COAST OIL COMPANY 801 South River Road	HM W. Sac.	16 e Hydrocarbons, Benzene	Closed GROUNDWATER CONTAMINATION DECREASED SINCE 1989 TO LOW OR MONDETECTABLE IN WELLS. SITE CLOSED.
COEN COMPANY 1510 TANFORAN	HM WOODLAND	501 e CHROMIUM	OPEN
COE'S TRUCKING 2266 Jefferson Blvd	HM W. Sac.	98 Motor Oil	Closed SOILS CONTAMINATED WITH WASTE MOTOR OIL & STEAM CLEANING WASTE EXCAVATED & TREATED ONSITE. FILE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
COLDWELL BANKER PROPERTY 938 North St Apt C	HM Woodland	299 Indoor Air Quality	Closed INDOOR AIR QUALITY COMPLAINT BY TENANT. COULD NOT FIND A PROBLEM.
COMMERCIAL I LTD 3020-40 Duluth St	HM W. Sac.	335 Waste Oil (Automotive Fluids)	Open REFERRAL BY W. SAC. CODE ENFORCEMENT OF A DISCHARGE OF CHEMICALS.
COMMUNITY DIALYSIS CENTER 520 Cottonwood St	HM Woodland	108 Hydrogen Peroxide	Closed FEB 22, 1991 SPILL OF 20 GALS OCCURRED. DURING INCIDENT, IT WAS NOTED AN EMERGENCY RESPONSE PLAN WAS NOT DEVELOPED. FACILITY WROTE RESPONSE PROCEDURES FOR CHEMICAL SPILLS. FILE CLOSED.
CONAWAY CONSERVANCY GROUP 45332 CR 25	HM Woodland	14 Be Gasoline	Open SUNNARY IF SOIL EXCAVATION AND TREATMENT. See SIRE FA0002702
CONAWAY CONSERVANCY GROUP 45332 CR 25	HM Woodland	14 Ae Gasoline	Open CONTAMINATION DISCOVERED. WORK PLAN FOR DEFINING CONTAMINATION APPROVED. See SIRE FA0002702
CONAWAY CONSERVANCY GROUP 45332 CR 25	UST Woodland	2702 e Gasoline	Closed ALL INFORMATION IN FILE H 14. See SIRE FA 2702
CONCRETE PRODUCTS, INC 665 N CR 101	HM Woodland	13 e No Release	Closed PROPOSAL FOR INSTALLATION OF 7,800 GAL ABOVE GROUND TANK FOR FORM OIL. SECONDARY CONTAINMENT REQUIRED.
CONRAD PROPERTY 400 DREVER STREET	HM WEST SACRA	486 DIESEL	OPEN DIESEL CONTAMINATED SOIL STOCKPILE. SEE RELATED FILE L-452 FOR 800 DELTA LANE.
CONRAD PROPERTY 400 DREVER STREET	HM WEST SACRA	486 DIESEL	CLOSED NFAIR ISSUED JANUARY 2005. CONTAMINATED SOIL REMAINS IN PLACE.
CONSOLIDATED FREIGHTWAYS 900 F ST	UST W. Sac.	111	Closed File L 111 - Minor soil contamination found in spoils from 1998 tank removal. Soils were removal for offsite disposal, no ground water impact was observed. Case closed in January 1999. Groundwater monitoring continued through the end of 2001 associated with previous tank a removal in 1996. File archived to 00111UTH in January 2004.
CONTECH CONSTRUCTION PRODUCTS CR 32A	HM Davis	85 Zinc, Oil, Grease	Closed CLEAN-UP OF METALS & DITCH ALONG CR 32A BY CONTECH, CITY OF DAVIS, & SPRR. FILE CLOSED.

Facility	File/Number	Status	Comments	
CONTECH CONSTRUCTION PRODUCTS CR 32A	UST Davis	455 Gasoline	Closed	1989-1990: soil & groundwater contamination found during ust removal. Soils excavated to 80 ft, treated on-site, soil remediation completed. Groundwater extraction & treatment in progress. 1991 to 1994 - all constituents reduced in gw to less than mcl. Rp requested site closure from CVRWQCB. Regional board required further remediation. 1995-97 data: Dec. '95 groundwater monitoring & intermittent pumping & treatment by air stripping continues. Wells have had non-detectable levels since Sept '96. An estimated 0.7 gallons of hydrocarbons remain in the soils and does not pose a threat to groundwater. CASE CLOSED 5/5/97 BY RWQCB.
CONTECH CONSTRUCTION PRODUCTS, I 2525 Second St	HM Davis	438 TAR	Open	LARGE TAR TANK SET ON FIRE WHILE ATTEMPTING DISPOSAL
CONTINENTAL HELLER 4521 W Capitol Ave	UST W. Sac.	114 Gasoline, Diesel	Closed	Files L 114 - Five USTs and respective piping and dispensers were removed in 1988 and 1995. Investigations have defined the lateral and vertical limits of gasoline and diesel hydrocarbons in soil and ground water. Results showed hydrocarbons in soil around the former tank cavities and a plume of hydrocarbons in ground water centered at well MW-1. Monitoring of ground water since 1989 shows the plume of hydrocarbons is stable, hydrocarbon concentrations decreased to non-detect, and MTBE and the other gasoline oxygenates are non-detect. This shows that hydrocarbons do not desorb during the rise and fall of ground water. A Tier II RBCA shows there are no health hazards with hydrocarbons beneath the site, and laboratory analytical results show concentrations are decreasing in ground water. Therefore, hydrocarbons remaining do not appear to be a significant threat to ground water and a No Further Action letter was issued by the Central Valley Regional Water Quality Control Board for this site on August 30, 2000. File archived to 00114UTH in January 2004.
CONWAY DEHYDR STATION/PG&E CR 103 & CR 25A	HM Davis	176 Production Fluid, Glycol	Closed	File H 176 - PG&E conducted a voluntary clean up in 1993 of the dehydration station hydrocarbon contaminated soils. File archived as 04458HWG in January 2003.

<i>Facility</i>	<i>File/Number</i>		<i>Status</i>	<i>Comments</i>
COTTONWOOD CLEANERS 628 Cottonwood St	HM	210	Open	H 210 - FILE A 1993-1995 DATA: Perchloroethylene discharged to ground & into sanitary sewer. Initial investigation found both soil & groundwater contamination. DA prosecuted criminal case. FILE B 1992/1993 - Environmental investigation reports: bankruptcy declared. Court appointed trustee initiates contract with DTSC for oversight of investigation and cleanup. FILE C: United States Bankruptcy documents through 2/96. FILE D 1996 DATA: Investigation continues to define extent of soil & surface aquifer contamination. Lead agency is DTSC. FILE E: Remedial investigation report. Soil & groundwater extent nearly defined in upper aquifer. Preliminary information indicates little or no impact to lower aquifers. FILE F: BANKRUPTCY COURT DOCUMENTS MARCH 1996 and other data through 1999. FILE G: 2000 Data File. March 28, 2000 quarterly sampling indicates PCE plume in upper zone is estimated to be 550 feet long by 29 feet wide with concentrations up to 8,100 ppb. Second water bearing zone is also impacted with up to 7 ppb. Upper plume is moving NW about 55 feet per year during this sampling event. Additional assessment in progress. Lead agency is now the RWQCB. FILE H: 2001 Data File. Final 2000 Quarterly indicates PCE plume in upper zone (27 to 52 feet below ground surface) is estimated to be 620 feet long by 320 feet wide with concentrations up to 5,700 ppb. The plume (December 2000) is moving northwest with the groundwater at about 55 feet per year. Second water bearing zone (65 to 78 feet below ground surface) has up to 2 ppb. The nearest municipal well (Woodland Well 11) is approximately 1000 feet up-gradient. The nearest down-gradient city well is # 20 located approximately 2,500 feet to the NW. A permit has been applied for from the YSAPCD to install and startup vapor extraction and treatment. Additional GW monitoring wells are planned to further access the lower aquifer. A study to determine if enhanced biodegradation is feasible at this site is planned to be completed during 2001. As April 2001 Soil vapor extraction is being conducted from 4 slant drilled wells near the former dry cleaners building. The CVRWQCB concerned with the rapidly spreading plume of PCE to the Northeast issued an order to submit a plan for an interim remedial action plan to prevent further plume migration and a workplan and schedule for submittal of a remedial action plan to clean up the first aquifer by June 2002.
COURT ST INVESTMENTS 204 College St	UST	119	Closed	FILE L 119 – Two 550 gallon gasoline USTs used since the 1940s were removed in 1988. Extensive soil and groundwater contamination with gasoline and benzene and low levels of MTBE were observed. Soils were excavated during events, ground water pump and treatment was implemented. Case was closed in August 2000. File was archived as 00119UTH in January 2004.
CRAIN INDUSTRIES 1465 Tanforan	HM	201	Closed	FILE CONTAINS COPY OF CVRWQCB INSPECTION OF FACILITY FOLLOWING COMPLAINT. REPORT STATES NO FURTHER INVESTIGATION WARRANTED. INSPECTION WITH DTSC FOUND VIOLATIONS. WORKER EXPOSED TO TDI PREPOLYMER, TREATED AT HOSPITAL & RELEASED. FILE CLOSED.
CRARY & HARPER RESIDENCE 611 Bartlette Ave	UST	601	Closed	SOIL CONTAMINATION FOUND DURING UST REMOVAL. SOIL EXCAVATED TO 17 FT. FILE CLOSED.
CROSSROAD CENTER Covell & Poleline Rd	HM	84	Closed	WELL PERMITS ISSUED FOR ENVIRONMENTAL INVESTIGATION PRIOR TO PROPERTY DEVELOPMENT. CONTENTS OF FILE COMBINES WITH H214.
CROSSROAD PLACE Poleline & Covell NW Corner	HM	214	Closed	WORKPLAN SUBMITTED TO DO AN INVESTIGATION FOR METHANE, VOLATILE ORGANICS & TOTAL PETROLEUM HYDROCARBONS. CASE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
CROSSWOOD APARTMENTS 646 Third St #42	HM Woodland	300 Asbestos	Closed TENANT RIPS UP FLOORING IN KITCHEN, DUST EVERYWHERE. FLOORING TESTED FOR ASBESTOS, RESULTS ARE NONDETECT. CASE CLOSED.
CUMMINS WEST 2661 Evergreen Ave	UST W. Sac.	125 Diesel/gasoline	Closed File L 125 - Two underground tanks removed 1992; contaminated soils were excavated and disposed offsite. Very small quantities of hydrocarbons remaining were judged to be of low risk and would naturally degrade without offsite impact. Yolo County issued a no further action required letter in October 97 following removal of monitoring wells, RWQCB had previously concurred with closure. File archived to 00125UTH in January 2004.
CUMMINS WEST 2661 Evergreen Ave	HM W. Sac.	143 Waste Oil	Closed File H 143 - Contaminated soil excavated along oil water separator line. Bioremediation of the soil completed. Case closed in October 1991. File archived to 00125HWG in January 2004.
D & D ROOFING 39967 Sharon Ave	HM Davis	179 Diesel	Closed OWNER REQUIRED TO CLEAN-UP SOIL CONTAMINATED BY DIESEL SPILLAGE FROM ABOVE GROUND TANK. SOILS EXCAVATED & TREATED ON-SITE. FILE CLOSED.
D B COMPANY 3939 W Capitol Ave	HM W. Sac.	219 PHENOL	Closed SOIL EXCAVATED TO A DEPTH OF ONE FOOT. SAMPLES COLLECTED. CLEANUP COMPLETED. CASE CLOSED.
D Q UNIVERSITY CR 31, One Mi W Of CR 95	HM Davis	110 A Hydrocarbons/PCB	Open SIX UNPERMITTED UST WITH POSSIBLE DIESEL CONTAMINATION & OTHER ENVIRONMENTAL PROBLEMS TO BE ADDRESSED BY U S ARMY CORP OF ENGINEERS AT THIS FORMER MILITARY FACILITY.
D Q UNIVERSITY 33250 CR 31	HM Davis	110 B Hydrocarbons/Chlorinated Solve	Open FILE B - SEE ALSO FILE RU2581 FOR ADDITIONAL INFORMATION. November 2002 the CVRWQCB issued a Draft Monitoring and Reporting Program due to the slow progress of the investigation.
DANIEL RADIATOR CORP 655 N CR 101	HM Woodland	17 e Unknown	Closed RECEIVED TRUCK WITH STRONG ODOR. CONTENTS REMOVED, NO SPILL FOUND, SHIPPER & TRUCK OWNER NOTIFIED. TRUCK RETURNED TO OWNER FOR CLEANING.
DAN'S TOWING 716 Houston St	UST W. Sac.	126 Petroleum Hydrocarbons	Open AKA DANMAR ENTERPRISES: SOIL CONTAMINATION OBSERVED DURING APRIL 1999 REMOVALS OF A GASOLINE AND DIESEL UNDERGROUND TANK.
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 G Gasoline	Open File G - 2001 Data. The lateral extent of soil contamination has been defined, and the vertical extent is primarily limited to 10 feet below ground surface. Additional work required to determine the extent of gasoline and oxygenates in groundwater. Once completed a final Remediation Plan will be required. Site access to adjacent property was denied in 2002.
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 F Gasoline	Closed FILE F-2000 CVRWQCB is now the lead agency. Additional assessment plan approve in March by the CVRWCB.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 C Gasoline	Closed FILE C 1996/1997: QUARTERLY MONITORING CONTINUED & SOME ADDITIONAL SITE ASSESSMENT COMPLETED. GROUNDWATER IS IMPACTED BOTH EAST & SOUTH OF SITE.
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 A Gasoline	Closed FILE A: PRE 1994. THREE 10,000 GALLON GAS TANKS REMOVED JAN 29, 1993. SOIL CONTAMINATION PRESENT. PRELIMINARY SITE INVESTIGATION ORDERED. GROUNDWATER MONITORING WELL HAVE BEEN INSTALLED.
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 B Gasoline	Closed FILE B 1994-1995 DATA: SITE ASSESSMENT FOUND GROUNDWATER CONTAMINATION. PROBLEM ASSESSMENT ORDERED. PROP 65 ISSUED. CASE REFERRED TO REGIONAL BOARD IN FEB '94.
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 E Gasoline	Closed FILE E-1999 CVRWQCB is now the lead agency. Additional assessment in progress under the CVRWQCB direction.
DARPETRO 2434 W Capitol Ave	UST W. Sac.	127 D Gasoline	Closed FILE D-1998: CONCENTRATIONS OF HYDROCARBONS INCREASED DRAMATICALLY IN WELLS WHERE SOILS ARE MOST IMPACTED, APPARENTLY DUE TO RISE IN GROUNDWATER TABLE.
DaVinci Court 1666 DaVinci Court	HM Davis	467 Nitrates	Closed H 467 Phase II Environmental Site Assessment found elevated levels of nitrates in first seven feet of soil decreasing in depth below seven feet. Site is proposed for residential apartment development, was formerly a portion of the City of Davis wastewater treatment plant. No further action required, file closed.
DAVIS CINEMA ELEVATOR 101 F ST	HM Davis	209 Hydraulic Oil	Closed APPROXIMATELY 10 GALS DISCHARGED UNDER 3-STORY STRUCTURE FROM RUPTURED PIPE. NO REMEDIATION REQUIRED. CASE CLOSED.
DAVIS CITY CLEAN-UP 860 Fifth St	HM Davis	136 Waste Oil, Batteries	Closed WASTE OIL & CAR BATTERIES ON THIS SITE. CITY OF DAVIS IS CONTRACTING CLEAN-UP. CASE CLOSED.
DAVIS CITY CORP ABOVE GD TANK 1717 Fifth St	HM Davis	109 Hydrocarbons	Closed During 1991 installation of above ground Convault tank soils observed to be contaminated TPH motor oil and diesel. Contamination was limited to the soil surface and excavated. Case closed July 1991. File archived to 04887HWG in January 2004.
DAVIS CITY CORP YARD PAINT DSP 1717 Fifth St	HM Davis	126 Paint (Latex)	Closed File H 126 - The City of Davis investigated a 1991 complaint regarding a paint disposal pit. Paint is non-hazardous. Pit is lined with plastic and filled with gravel. County suggested city look at waste minimization. File archived to 04887HWG in January 2004.
DAVIS CITY CORP YARD TANK #4 1717 Fifth St	UST Davis	508 Waste Oil	Closed WASTE OIL CONTAMINATION DISCOVERED DURING TANK REMOVAL. SOILS EXCAVATED & DISPOSED. FILE CLOSED.
DAVIS CITY CORP YARD TANK #5 1717 Fifth St	UST Davis	508 Chromium	Closed SOIL SAMPLE COLLECTED BELOW SOLVENT TANK DURING REMOVAL IN JUNE 1989 FOUND 84 PPM CHROMIUM. YC HAS REQUESTED CITY OBTAIN SECOND SAMPLE 2 FT DEEPER TO DETERMINE IF SIGNIFICANT LEAK OCCURRED.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
DAVIS CITY WASTEWATER PLANT CR 105 & CR 284	HM Davis	10 General File	Closed	H 10 - This file was moved November 2002 to the Water Program files.
DAVIS CREEK RESEVIOR Lake County	HM Davis	18 e MERCURY	Closed	SEE ECOTOXICITY STUDY FILE H403.
DAVIS ENTERPRISE 302 G ST	HM Davis	383 e Chlorinated Solvents	Open	INVESTIGATION IN PROGRESS.
DAVIS FUEL STOP CAR WASH 504 L STREET	HM DAVIS	478 e CAR WASH SUMP SLUDGE	CLOSED	THE FACILITY DISPOSED OF HYDROCARBOUN CONTAMINATED CAR WASH SUMP SLUDGE TO SOIL IN BACK OF PROPERTY. THE PROPERTY IS LOCATED AT 1411 5TH STREET, DAVIS CA.
DAVIS FUEL STOP CAR WASH 504 L STREET	HM DAVIS	478 e CAR WASH SUMP SLUDGE	CLOSED	
DAVIS GOLF COURSE 24439 FAIRWAY DR	HM Davis	402 Lubricating Oil	Closed	A LARGE QUANTITY OF LUBRICATING OIL WAS DISCHARGED INTO TWO PONDS FROM PUMPS LOCATED IN WELLS.. SPILL CLEANED UP - CASE CLOSED -
DAVIS GOLF COURSE 24439 FAIRWAY DRIVE	HM DAVIS	487 e DIESEL	CLOSED	06/11/03- CONCRETE MIXER TRUCK ROLLED OVER INTO POND BETWEEN 7TH GREEN AND 8TH TEE. DIESEL FUEL IMPACTED POND. SITE WAS CLEANED AND SAMPLES TAKEN. RESIDUAL MATERIAL REMOVED FROM SURFACE ON 06/13/03. CASE CLOSED.
DAVIS HONDA YAMAHA 975 Olive Dr	UST Davis	627 Gasoline	Closed	DURING ROUTINE TANK REMOVAL MINOR SOIL CONTAMINATION FOUND. SOIL EXCAVATED & AERATED ON-SITE. SITE CLOSED. File archived as 627UTH in December 2003.
DAVIS LUMBER & HARDWARE 240 G St	UST Davis	131 Kerosene	Closed	LEAK DISCOVERED IN APRIL 1986, SOIL REMEDIATION COMPLETED IN MAY 1986. FILE CLOSED.
DAVIS SUBURU 1015 OLIVE DRIVE	HM Davis	413 UST Removal	Closed	1985 Removal of 550 gallon UST. No significant contamination observed.
DAVIS TEXACO 2002 LYNDELL TERRACE	UST Davis	3064 Gasoline and Diesel	Open	FUEL OXYGENATES WERE FOUND IN A GROUNDWATER SAMPLE, AND DIESEL AND FUEL OXYGENATES WERE FOUND IN SOIL SAMPLES TAKEN AROUND THE UST SYSTEM.
DAVIS TRUCK PAINTING 1550 South River Road	HM W. Sac.	227 PAINT, OIL SOLVENTS	Closed	REPORT TO DTSC OF IMPROPER PAINT WASTE STORAGE (NOV '93). NO INVESTIGATION CONDUCTED DUE TO STAFF SHORTAGE.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
DELP PROPERTY 18655 CR 71	HM Brooks	366 Petroleum Products & Solvents	Closed EVIDENCE OF DUMPING CHEMICALS-FAMILY MEMBERS FEUDING.
DELTA HIGH SCHOOL Netherland Rd	UST Clarksburg	134 Gasoline	Closed File L 134 - Leak discovered during August 1988 tank removal, tank not used since 1978 had several holes. Soil remediation completed September 1988. File closed. File archived as 00134uth.
DELTA VALLEY INVESTMENT 4891 W Capitol Ave	HM W. Sac.	377 Gasoline	Open
DEMURCE, ZITA	HM Davis	359 Indoor Air Quality	Closed AIR MONITORING DONE. NO CONTAMINANTS FOUND.
DENNY'S EAST STREET 590 East St (North)	HM Woodland	315 Hydrocarbons	Closed PHASE SITE ASSESSMENT CONDUCTED TO ESTABLISH BASELINE ENVIRONMENTAL CONDITIONS FOR SITE. ONLY TRACE LEVELS OF TOLUENE DETECTED IN GROUND WATER. CASE CLOSED.
Dialysis Clinic, Inc 95691 W. Capital Ave.	LUST West Sacrame	9591 e Gasoline and motor oil	Open Strong odor of gasoline and green soil encountered at tank pull. Investigation pending.
DOBS TIRE CENTER 151 Main St (West)	HM Woodland	19 e Antifreeze	Closed DISPOSAL OF WASTE ANTIFREEZE TO CITY STORM SEWER. DISCHARGE ORDERED STOPPED, PERMIT FROM CITY FOR SANITARY SEWER SYSTEM DISCHARGE REQUIRED.
DOLLAR TOW COMPANY 2221 Rice Ave	HM W. Sac.	230 e Automotive Fluids	Closed DISPOSAL OF OIL, GAS, TRANSMISSION FLUID, ANTIFREEZE TO GROUND. FILE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.
DOLORES, JOSE & GLORIA 42214 Daniel St	HM Knights Landin	329 Waste Oil	Closed WASTE ENGINE OIL DUMPED NEXT TO PROPERTY LINE. WATE ENGINE OIL STORED IN OPEN CONTAINERS NEXT TO PROPERTY LINE (APPROXIMATELY 20 GALS).
DON GOODNER/MOTRONI PROPERTY 1038 Beamer St	UST Woodland	241 Solvents/Gasoline	Open SOLVENT, GASOLINE SOIL CONTAMINATION FOUND DURING PHASE II.
DONNER WAY DRUG LAB 1730 DONNER WAY	HM WOODLAND	479 CLANDESTINE DRUG LAB CONTA	OPEN CLANDESTINE DRUG LAB CONTAMINATION WAS FOUND IN THE DETACHED GARAGE. THE RESPONSIBLE PARTY AND PROPERTY OWNER IS ALFANSO VASQUEZ.
DORADO RESIDENCE 1827 Madrone Ave	HM W. Sac.	208 Automotive Fluids/Waste Oil	Closed COMPLAINT FROM W SAC FIRE DEPT OF RESIDENT DISPOSING WASTE FLUIDS INTO STORM DRAIN. INVESTIGATION CONFIRMED TENNANT ACTIVITY. OWNER CLEANED UP, TENNANT HAS SINCE MOVED. FILE CLOSED.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
DOS PINOS 37880 Russell Blvd	Davis	HM 357 Gasoline	Closed	THE PROPERTY OWNER REMOVED AN EXEMPT FARM TANK, SOIL BORINGS SHOWED NO CONTAMINATION.
DOW CHEMICAL Mace Blvd	Davis	HM 20 Ae Pesticides	Closed	FILE A TECHNICAL REPORTS: PESTICIDES FOUND IN SOIL & GROUNDWATER. SITE REMEDIATION COMPLETED. POST-REMEDIATION MONITORING COMPLETED. CASE CLOSED.
DOW CHEMICAL Mace at Montgomery	Davis	HM 20 Be Pesticides	Closed	FILE B CORRESPONDENCE FILE: CASE CLOSED. SEE #L-140 FOR RELATED LEAKING UNDERGROUND TANK ASSESSMENT & REMEDIATION. See FA 140
DOW ELANCO RESEARCH FARM MACE AT MONTGOMERY DAVIS		UST 140 B GASOLINE	CLOSED	CASE CLOSED BY REGIONAL WATER BOARD FEBRUARY 26, 2004.
DOW ENLANCO RESEARCH FARM Mace At Montgomery	Davis	UST 140 A Gasoline	Closed	FILE A PRE-1996 DATA: SOIL CONTAMINATION FOUND DURING 1985 TANK REMOVAL. CLEAN-UP DELAYED TO ADDRESS UNRELATED PESTICIDES (H2O). SOME SOILS EXCAVATED. RAP APPROVED.
DOW ENLANCO RESEARCH FARM Mace at Montgomery	Davis	UST 140 B Gasoline	Open	FILE B:1996-1998 REMEDIAL SYSTEM OPERATED FROM 1995 THROUGH LATE 1997. when cleanup objective were reached. HRC was applied in December of 1999. No further action was requested based on low risk to groundwater from remaining contaminants in December 2000. The cleanup goal for 1,2-DCP established for this site is 0.56 ppb. 1,2-DCP has dropped to below cleanup goals in two of the four remaining monitoring wells as of Sept 2002. Cleanup goals have been reached (January 2004) and this case will be closed upon abandonment of the monitoring wells.
DUNNIGAN TRUCK SERVICE (PILOT) 30335 CR 8	Dunnigan	UST 143 Gasoline, Diesel	Open	L 143 File A 1995 to 1998, File B 1999, File C 2000, Formerly known as the Dunnigan Truck Stop, now as the Pilot Travel Center. Free product was recovered from this site as early as 1981, a diesel leak was discovered in piping in 1995, underground tanks were removed and replaced in 1999. The lateral extent of hydrocarbons in shallow groundwater (approx 27 feet bgs) is defined but not in the next aquifer at 35 to 65 feet, and neither later or vertical definition has been defined below 65 feet. Shallow GW remediation has been initiated. FILE D - 2001 Data - Additional investigation in progress to investigate deeper aquifer. 2002 - Soil Vapor Extraction and quarterly monitoring continues. Investigation, assessment, and SVE continues in 2003. RWQCB (lead agency) contact is David Stavarek, (916) 255-7073. See FA 143
EAST STREET COURT PARTNERS East St & Court	Woodland	HM 128 Diesel, Motor Oil	Closed	DURING DEMOLITION OF CONCRETE, VAULT DISCOVERED CONTAINING OIL. WORK PLAN SUBMITTED FOR DESTRUCTION OF VAULT & VERIFICATION OF ANY CONTAMINATION. SEE FILE 596UTH.
EAST STREET COURT PARTNERS 1059 Court St	Woodland	UST 596 Diesel, Motor Oil	Closed	DURING DEMOLITION AT FACILITY, VAULT DISCOVERED CONTAINING DIESEL & OIL. VAULT AND CONTAMINATED SOILS REMOVED. ALSO REFERENCED AS HM 128. FILE CLOSED. Files HM 128 and UST 596 combined and archived to 596UTH in November 2003.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
EATON DRILLING COMPANY 20 Kentucky Ave (West)	HM Woodland	89 Petroleum	Open
ECO WATER-SERVICOFT 49 WEST MAIN STREET	HM Woodland	419 Salt	Closed
EL MACERO COUNTRY CLUB 44571 Country Club Dr	HM Davis	107 Petroleum	Closed
EL MIRADOR APT 1032 ELLIOT	HM Woodland	375 Waste Automotive Fluids	Closed
EL RANCHO CLEANERS 1331 MERKLEY AVE	HM W. Sac.	440 Perchloroethylene	Open
ELECTRIC GARAGE COMPANY 801 Main St (East)	UST Woodland	152 Gasoline	Open
ELECTRO-COATINGS INC 2904 Duluth St	HM W. Sac.	100 CHROMIC ACID	Closed
ELKHORN SPILL SR 16 & I-5 N Bound Ramp	HM Woodland	193 Hydraulic Oil	Closed
Elliot Service Center 1421 Sacramento Ave	HM W. Sac.	331 Waste Drums	Closed

HYDROCARBON CONTAMINATED SOILS OBSERVED DURING UST INSPECTION RESULTED IN SITE ASSESSMENT REQUIREMENT. HYDROCARBONS FROM SPILLAGE & STEAM CLEANING AREA DISPOSED. LEAD & TIN FROM FORMER RADIATOR SHOP ON-SITE NOW BEING ASSESSED.

COMPLAINT OF DISPOSAL OF SALT INTO THE PIT. REFERRAL TO CVRWQCB. CVRWQCB WROTE REPORT REQUIRING A LINER FOR THE PIT AND WEEKLY MONITORING OF WATER. CASE CLOSED.

File H 107 - Waste oil drums and a 550-gallon above ground diesel tank (AST) were removed in May 1991 (at the same time as two under ground tanks were removed). Oil stained soil associated with the drums and AST were excavated and bioremediated on site. Case closed in December 1994. File archived to 00151UTH in January 2004.

POTENTIAL CONTAMINATION BEING ASSESSED.

L 152; FILE A: PRE 1994 DATA - Contamination discovered during 1990 tank removal. Both soil & groundwater impacted. Excavation unfeasible due to structures and street location. FILE B: 1994/95 DATA - Site approved for state cleanup funds. Qtr monitoring continues. PAR in progress. FILE C 1996/1997 DATA. Site characterized FRP approved by Yolo Co, implementation pending state cleanup fund approval as of Aug 1997. FILE D-1998/99- RWQCB requests investigation of VOA's found beneath the site. Soil and Assessment workplan submitted July, 1999. FILE E 2000 DATA - Quarterly monitoring continues.

File H 100 - Chromic acid air discharges resulted in contaminated soils on-site & adjacent SPRR site. Chromic acid use has ceased. Plant (interior) & soils have been remediated. . File closed September 1992. File archived to 00153HWG in January 2004.

VEHICLE ACCIDENT RELEASED ESTIMATED 5 GALS DIESEL & OTHER VEHICLE FLUIDS. SOILS EXCAVATED, SHIPPED OFFSITE FOR TREATMENT. FILE CLOSED.

Inspection found tenant had abandoned drums and containers of hazardous waste associated with an automotive shop and welding. Waste drums and containers and their contents were removed.

Facility	File/Number	Status	Comments	
ELM FORD 346 Main St	UST Woodland	154 Gasoline	Closed	File L 154 - Soil and groundwater hydrocarbon contamination was discovered following a 1985 waste oil tank removal and closure in place of four gasoline underground tanks. Soil vapor extraction and air sparging were utilized to reduce concentrations. The groundwater plume is relatively stable and decreasing in size due to the natural biodegradation that is occurring. The trend analysis indicates benzene should reach its MCL in approximately 7.4 years. The sensitive receptor survey indicates the nearest water supply well is approximately 1,900 feet up gradient of the site. The shrinking plume poses no threat to that well and is not a threat to human health, water quality or beneficial uses. A 'No Further Action Required' letter was issue by the RWQCB letter on January 8, 2004. File archived to 00194UTH in January 2004.
English Nut Processing Plant 29195 CR 28	HM Winters	461 Tannin & Lignin as Tanic Acid	Open	See Envision complaint number CO 6624. RWQCB found elevated BOD, Total Dissolved Solids, specific conductance and Tannic Acid in waste water ditch. Facility required to sample nearest domestic well, cease discharge, and file a report if future discharges are proposed.
ENRON OIL & GAS CO CR 18A & CR 100B	HM Woodland	182 Petroleum Condensate	Closed	Petroleum condensate found at site. 9000 cubic yards of soil excavated. Side wall & bottom samples non-detect. Soil treated on-site. Liner placed in excavation & treated soil placed in hole. File closed.
EPOCH EXXON 4790 W Capitol Ave	UST W. Sac.	180 Gasoline, Diesel	Open	FILE A: WORKPLAN & REPORT. Gasoline & diesel contamination detected along piping trench & around tank excavations. FILE B: CORRESPONDENCE FILE. FILE C: QUARTERLY REPORTS FOR 1993. FILE D: QUARTERLY REPORTS FOR 1994. FILE E: QUARTERLY REPORTS FOR 1995. FILE F: 1998 & 1999 DATA. FILE G 2000 & 2001 DATA - Quarterly groundwater monitoring continues to find gasoline and related components in several wells. MTBE also present in at least 2 wells. The consultant indicates the Hydro geological Assessment will be completed in early 2001.
EPOCH/EXXON 4790 W Capitol Ave	HM W. Sac.	191 Diesel	Closed	H 191 - Fifty to seventy gallons of diesel spilled on asphalt & entered storm drain October 1992. Clean up occurred & YCDA investigated. Case closed. File archived as 00180HWG in February 2004.
EPSTEIN FACILITY 236 Main St (West)	UST Woodland	2670 Gasoline	Closed	CLOSURE REPORT-RBCA DONE. SOIL CONTAMINATION REMAINING NOT SIGNIFICANT RISK. File closed in 1998. File archived to 2670UTH in December 2003.
Equilon dba Shell 4900 W Capitol Ave	UST W. Sac.	352 Petroleum	Open	Site assessment found MTBE, TBA, and TPH as diesel in groundwater
EQUILON OIL BULK PLANT (Shell) 1509 South River Road	HM W. Sac.	59 C Petroleum	Closed	FILE C: 1995 - 1997 DATA

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
EQUILON OIL BULK PLANT (Shell) 1509 South River Road	HM W. Sac.	59 F Petroleum	Open File F: 2001 Data - Quarterly Monitoring Continues. RWQCB is the lead agency. The site is an operating petroleum product distribution terminal. Groundwater monitoring has been performed since 1987. Site remediation previously consisted of groundwater extraction and soil vapor extraction until Dec 1998. During 1999 and 2000, natural attenuation and biodegrading were the remediation processes being implemented. The existing groundwater extraction system is being retrofitted and groundwater extraction will be resumed in 2002. The estimated site remediation will require approximately 21 to reach site cleanup goals. The best estimate for a completion date of cleanup activities is in the year 2015. Maximum concentrations in groundwater as of late 2001 was 12,000 ppb TPH, 680,000 ppb TEPH, 1,800 ppb Benzene and 1,600 ppb MtBE. The ground water treatment was started on August 10, 2002.
EQUILON OIL BULK PLANT (Shell) 1509 South River Road	HM W. Sac.	59 E Petroleum	Closed FILE E: 2001 Data - Quarterly monitoring continues. RWQCB is the lead agency
EQUILON OIL BULK PLANT (Shell) 1509 South River Road	HM W. Sac.	59 Ae Petroleum	Closed FILE A 1986-1992: JUNE 11, 1993 SEMI-ANNUAL GROUNDWATER MONITORING REPORT PREPARED BY HLA. DUE TO HLA ERROR, NO LAB DATA INCLUDED FOR DEC SAMPLING EVENT. GROUNDWATER CHEMISTRY AT SITE SIMILAR TO SEPT 1992. See SIRE FA 345
EQUILON OIL BULK PLANT (Shell) 1509 South River Road	HM W. Sac.	59 D Petroleum	Closed FILE D: 1998 - 2000 DATA - Groundwater beneath this facility is contaminated with TPH, TEPH, BTEX and MTBE. Monitoring has been conducted since 1987. The lead agency (CVRWQCB directing facility to institute interim remedial measures including skimmer or SPH-sorbent material).
EQUILON OIL BULK PLANT (Shell) 1509 South River Road	HM W. Sac.	59 B Petroleum	Closed FILE B: 1993 SHELL DIRECTED TO SUBMIT WORKPLAN TO COMPLETE PLUME DEFINITION.
ESPARTO BLACKSMITH SHOP	HM Esparto	423 Hazardous Waste Clean-up	Closed PESTICIDES, DRUMS AND UNKNOWN HAZARDOUS MATERIALS HAVE BEEN REMOVED FROM THE BLACKSMITH SHOP. THE PROPERTY OWNERS HIRED A LICENSED HAZMAT WASTE HAULER TO REMOVE AND PROPERLY DISPOSE OF WASTE. SEE FILE FOR MORE INFORMATION.
ESPARTO HIGH SCHOOL 16558 CR 85B	He ESPARTO	489 ARSENIC	OPEN ARSENIC CLEANUP REQUIRED AS A CONDITION OF APPROVAL FOR THE PROPOSED ESPARTO HIGH SCHOOL ON CR 85B ESPARTO.
ESPARTO UNIFIED SCHOOL DIST. 26555 PLAINFIELD	UST Esparto	158 Gasoline & Diesel	Closed In 1997 two USTs were removed from the site. Soil is not affected by petroleum hydrocarbons beyond the former USTs cavity, and petroleum hydrocarbons, including MTBE, do not affect groundwater. Because petroleum hydrocarbons detected in soil beneath the former USTs do not affect groundwater the CVRWQCB issued a no further action letter related to the tank release on January 26, 2000. Case closed. All information incorporated into the 158UTP file and scanned into Adobe January 2002.
EUROPEAN AUTO 1800 Olive Dr	HM Davis	409 Various Auto Waste Fluids	Closed COMPLAINT FROM CITY OF DAVIS, VIOLATIONS FOUND, ORDER WRITTEN AND CORRECTED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Evergreen Arborists Inc 40250 CR 27	HM Woodland	455 Closed	A Phase I Environmental Site Investigation found diesel and motor oil in at the drain location from a containment that last held two aboveground storage tanks and may have been a storage area for hydraulic oil for past site occupants. Soils were excavated and final samples taken. Case closed. File archived to 455UTH in November 2003.
EXXON 1401 W CAPITOL	UST W. Sac.	310 Benzene ,MTBE Closed	1998 pre sale investigation found gw inoculated with benzene and MTBE. CVRWQCB is the lead agency. Three wells were constructed and nine soil borings installed finding below reporting levels or very low levels (MTBE was detected at 5 ppb). Monitoring wells have been destroyed, facility has requested case closure from the RWQCB. No Further Action Required letter issued by RWQCB November 2001
Exxon (2816 W Capitol Ave) 2816 W Capitol Ave	UST W. Sac.	3654 Gasoline Open	From 1958 to 1990 the station was operated as a Regal Station. Exxon operated until January 1999 when it was sold to Nella Oil, the current operator. Soil and groundwater contamination was discovered during the sale to Exxon and subsequently during a waste oil tank removal. As of July 2002 the later extent of TPHd, the lateral and vertical extent of MtBE in groundwater remains undefined. The lateral and vertical extent of TPGg and BTEX in shallow groundwater may be defined. A groundwater extraction system has operated from Feb 2001 through March 2002, it is being upgraded. A vapor extraction system and air sparging system have also been installed but are not operating as of October 2002. They plan to restart in groundwater extraction system only.
EXXON (J R SERVICE) 1400 Main St (East)	UST Woodland	217 Gasoline Closed	SOIL CONTAMINATION FOUND DURING SEPT 1987 SALE INVESTIGATION, TANKS REMOVED FEB 1988, SOIL REMEDIATION COMPLETED AUG 1988. FILE CLOSED. File scanned - See File 217UTH.
EXXON (MAIN ST) #7-0123 5 Main St (West)	UST Woodland	311 Gasoline Closed	Files A, B & C - Groundwater & soil contamination found during 1988 purchase of former Wickland station by Exxon. The four original tanks were installed in 1984 (10,000-gallon single wall fiberglass) were removed and replaced with double walled tanks by Exxon in 1994). The purchase investigation revealed soil and groundwater impact. In-situ Soil vapor extraction was conducted from 1991 to 1993. Groundwater extraction and treatment by an air stripper from 3 recovery wells was conducted from 1991 to 1993. Soils were excavated during the tank upgrade project in 1994. A RBCA analysis was conducted with site-specific parameters to evaluate if current BTEX level meet the criteria established in the Tier 1 standard. The analysis concluded that none of the parameters exceeded the criteria. Mass balance calculations estimated that 4.4 pounds of TPHg and 0.142 pounds benzene remain in soil. The water contains less than 0.425 pounds TPHG and less than 0.00435 pounds benzene. The site was declared a low risk site and No Further Action letter was issued by the CVRWQCB in July 1997.
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 D Gasoline Closed	FILE D: MAY 1989 PRELIMINARY REPORT.
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 F Gasoline Closed	FILE F: APR 1990 SOIL & GROUNDWATER INVESTIGATION & OCT 1990 FINAL REMEDIATION PLAN. NOTE UPDATED SOILS EXCAVATION WORK PLAN AUG 1991 (FILE B).
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 E Gasoline Closed	FILE E: DEC 1989 PROBLEM ASSESSMENT REPORT.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 B Gasoline	Closed FILE B 1991 & 1992 CORRESPONDENCE FILE: SEVERAL ASSESSMENTS & INVESTIGATIONS DONE. GROUNDWATER REMEDIATION IN PROGRESS, EXTRACTION, AREATION & DISCHARGE TO SANITARY SEWER. FILE CONTINUES IN 436C.
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 A Gasoline (REG & UNL)	Closed FILE A 1984-1990 CORRESPONDENCE FILE: GASOLINE DISCOVERED IN STORM DRAIN (MARCH 1984). 2 TANKS LOST UP TO 1,500 GALS. THIRD TANK FAILED TEST IN 1987. CONTINUED TO FILE B. FILE CLOSED.
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 C Gasoline	Closed FILE C MAY 1986 PROJECT STATUS REPORT: TANKS REMOVED IN OCT 1991. ALL SOILS FEASIBLE WERE EXCAVATED & TRANSPORTED OVER I-80 TO AERATION SITE.
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 G Gasoline	Closed JAN 1993 QUARTERLY REPORTS & SOIL TREATMENT CLOSURE REQUEST HAVE BEEN GRANTED.
EXXON (YATES) DAVIS 400 Mace Blvd	UST Davis	436 H Gasoline	Open FILE H: 1999 DATA
EXXON STATION 901 Park Blvd. (Park & Jefferson)	UST W. Sac.	7 e Gasoline	Closed LEAK DISCOVERED DURING 1986 TANK REMOVAL. SOIL & GROUNDWATER CLEAN-UP COMPLETED. A MONITORING WELL LEFT ON-SITE FOR FUTURE CONFIRMATION. FILE CLOSED.
EXXON STATION 7-3485 1150 Halyard Dr	UST W. Sac.	159 Gasoline	Closed A 1988 site Investigation of low level groundwater contamination by diesel. The tanks were removed in April 1989 including one 10,000 gallon unleaded, one 8,000 regular, one 8,000 gallon extra unleaded gasoline tanks and one 1,000 waste oil tank. Some soil and groundwater contamination was observed at low levels. Additional investigation detected only spotty contaminates. A Tier 1 RBCA analysis indicated that the current representative concentrations in groundwater and soil do not exceed the RBSLx calculated for the Tier 1 analysis. It appears that this site has never had a significant problem with contamination from petroleum hydrocarbons. A No Further Action required letter was issued for this site effective October 2, 1997. File has been incorporated into file number 159UTH. Case closed.
F A A SACRAMENTO VORTAC Pumphouse Rd & Field	UST W. Sac.	163 Gasoline	Closed LEAK DISCOVERED DURING UST REMOVAL. SOILS EXCAVATED & TREATED ONSITE. SEVERAL SOIL BORINGS & MW'S DETECTED NO ADDITIONAL CONTAMINATION. CASE CLOSED. File electronically scanned January 2002, now found in 163UTH electronic file.
F F SMITH CO 3120 Coke St	UST W. Sac.	161 Diesel	Closed TANK FAILED NOV 1985 TESTING, TANK REMOVED 1988, ASSESSMENT COMPLETED, NO REMEDIATION REQUIRED, FILE CLOSED APR 1989. See scanned file 161UTH.
F STREET COMMERCE CENTER F STREET	HM W. Sac.	418 Environmental Investigation	Closed PRE DEVELOPMENT INVESTIGATION

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
FAIRGROUNDS PLAZA 825 Gum Ave	HM Woodland	174 Gasoline	Closed File H 174 - Subsurface investigation discovered gasoline contamination possibly from an off-site source. Investigation suspended pending results of sigma gas investigation. See L 373. File archived as 00373UTH in January 2004.
FARIA PROPERTY 875 Southwood Dr	UST Woodland	619 Diesel & Lead	Closed DURING TANK REMOVAL, SOIL SAMPLES SHOWED DIESEL & LEAD CONTAMINATION. LEAD CONTAMINATION AT 1200 MG/KG IN EXCESS OF STATE LIMIT OF 1000 MG/KG. SITE INVESTIGATION ORDERED. TANK PIT OVER-EXCAVATED. SOIL TRANSPORTED & DISPOSED. File closed May 1993. File archived to 619UTH in December 2003.
FARMER'S RICE COOPERATIVE 2224 Industrial Blvd	UST W. Sac.	628 Gasoline	Closed DURING REMOVAL OF GAS TANK, SOIL CONTAMINATION OBSERVED AT 9 & 16 FT DURING OCT '93 REMOVAL. PIER REQUESTED. NO EVIDENCE OF GROUNDWATER CONTAMINATION. CASE CLOSED
FESSLER FACILITY -	HM W. Sac.	246 Abandoned UST	Closed OWNER PURCHASED PROPERTY & DISCOVERED UST & POSSIBLE CONTAMINATION. CONTENTS HE IS NOT RESPONSIBLE. COUNTY REQUIRED HE OBTAIN PERMIT TO CLOSE TANK. SOLD, NEW OWNER REMOVED TANK UNDER COUNTY PERMIT. CASE CLOSED.
Food & Liquor Customer Company 731 Poplar	UST W. Sac.	170 A Gasoline	Closed L 170 File A: 1986 to 1999 Data: LEAK FOUND DURING MARCH 1986 TANK REMOVALS, SITE ASSESSMENT COMPLETED SEPT 1986. CASE REFERRED TO CVRWQCB JUNE 8, 1990. GROUNDWATER MONITORING IN PROGRESS. Site investigation continues through 2002
Food & Liquor Customer Company 731 Poplar	UST W. Sac.	170 B Gasoline	Open L 170 File B: 1999 to Present Data: CVRWQCB is lead agency. Monitoring continues on 4 wells, 780 ppm of TPHG in one well, no BTEX in any well, MTBE has not been found to be present. Cleanup fund commitment issued in March 2003.
FORMER DAILY DEMOCRAT BUILDING 702 Court St	HM Woodland	376 Printing & Photograph	Closed PHASE I: SITE ASSESSMENT REPORT REVIEW FOR YOLO COUNTY GENERAL SERVICES. MEMO & FILE NOTES ONLY.
FORMER HUNT WESSON PLANT 1111 COVELL BLVD	e DAVIS	3327	OPEN PHASE II ENVIRONMENTAL ASSESSMENT.
FORMER RAILROAD LOCOMOTIVE FAC South River Road	HM W. Sac.	378 PHASE II	Open PHASE II ASSESSMENT SUBMITTED BY WKA.
Fosroc, In. Facility 655 CR 101 North (Pioneer Rd)	HM Woodland	430	Closed H 430 - February 1998 Environmental Investigation found no items of significant environmental concern at the property. Notes groundwater contamination at the adjacent California Cascade Industry facility but did not identify an impact or threat to this property.
FOWLER PAINT CO 80 Main St (West)	USTL Woodland	2 e Gasoline	Closed TANK LEAK DISCOVERED IN NOV 1985. SOIL REMEDIATION COMPLETED IN MARCH 1986. FILE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 G Diesel	Closed FILE H: 1999 DATA
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 A Diesel	Closed FILE A PRE 1989: SOIL & GROUNDWATER CONTAMINATION FOUND DURING UST REMOVAL. LEAKING ABOVE GROUND PIPE ALSO FOUND. INITIAL INVESTIGATION INDICATES GROUNDWATER IS IMPACTED. FILE CONTINUES TO 175B.
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 J Diesel	Open FILE J: 2000 - 2002 DATA - The CVRWQCB determined that remediation efforts have been ineffective and requires a new feasibility study to determine an effective remedial alternative. In 2002 TPH as gasoline and diesel, benzene and MTBE were still being detected in ground water. The groundwater air sparge injection wells continues to operate (startup was August 1998). Quarterly monitoring continues. Plume extends east of property onto the form Roadway Delta site.q
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 F Diesel & Gasoline	Closed FILE F: 1994-1996 DATA. CORRECTIVE ACTION PLAN PROPOSING PUMP & TREAT & IN-SITU BIOREMEDIATION.
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 C Diesel	Closed FILE C 1991-1992: FURTHER INVESTIGATION TO DETERMINE SITE CONDITIONS IN PROGRESS. FREE PRODUCT RECOVERY WAS CONDUCTED.
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 B Diesel	Closed FILE B 1989-1990: SITE INVESTIGATION CONFIRMS SOIL & GROUNDWATER CONTAMINATION WHICH EXTENDS OFF-SITE TO ADJACENT ROADWAY EXPRESS PROPERTY (SEE L452). FILE CONTINUES TO L175C.
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 H Diesel	Closed FILE G: 1997/1998 DATA
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 E Diesel	Closed FILE E: 1993 CORRESPONDENCE
FREDRICKSEN TANK LINES 850 Delta Lane	UST W. Sac.	175 D Diesel	Closed FILE D:SITE INVESTIGATION & CORRECTIVE ACTION REPORTS (1991 & 1992).
FREEMAN SCHOOL 121 West St	HM Woodland	337 Asbestos	Open ILLEGAL ABATEMENT & DISPOSAL OF ASBESTOS. REFERRED TO DA & Y/S AQMD.
FREEWAY FORD 5080 Chiles Rd	UST Davis	176 Gasoline	Closed MINOR SOIL CONTAMINATION DISCOVERED AND EXCAVATED DURING NOVEMBER 1989 REMOVAL OF 1,000 GALLON GASOLINE TANK. SOILS ARE AERATING ONSITE. CLEAN-UP COMPLETED. SITE CLOSED 7/20/90. Data from this file has been scanned and incorporated in the following file: 176 UTH

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
FREEWAY FORD 5080 CHILES ROAD	Davis	HM 404 Petroleum Contamination	Open	REMOVAL OF OIL/WATER SEPERATOR EXCAVATON PF SPOIL. Transportation OF SOIL AS HAZORDOUS WASTE
Frontier Fertilizer CR 32A	Davis	HM 22 Ee EDB, DBCP, 1,2-Dischloropropane	Closed	FILE 22E: FINAL FOCUSED REMEDIAL INVESTIGATION & FEASIBILITY STUDY WORK PLAN (DEC 1991) See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 Ge EDB, DBCP, 1,2-Dischloropropane	Closed	FILE 22G: SITE SELECTED BY EPA AS A PILOT SITE FOR SUPERFUND ACCELERATED CLEAN-UP MODEL. STATE TO DESIGN, INSTALL, OPERATE GROUNDWATER EXTRACTION & MONITORING SYSTEM. EPA WILL DO REST. See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 Je EOB, DBCP, 1,2-Dichloro Propane	Closed	FILE J-1998 DATA See FA 3866
Frontier Fertilizer CR 32 A	Davis	HM 22 Be EDB, DBCP, 1,2-Dischloropropane	Closed	FILE 22B 1985: FILE INCLUDES SITE CHARACTERIZATION REPORT, GROUNDWATER INVESTIGATION REPORT, US DISTRICT COURT ACTIONS. See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 Ce EDB, DBCP, 1,2-Dischloropropane	Closed	FILE 22C: PRELIMINARY RISK ASSESSMENT REPORT & PRELIMINARY ASSESSMENT & R1/FS WORK PLAN. See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 De EDB, DBCP, 1,2-Dischloropropane	Closed	FILE 22D 1986-1990: INCLUDES REMEDIAL ACTION ORDER & IMMINENT & SUBSTANTIAL ENDANGERMENT ORDER. See FA 3866
FRONTIER FERTILIZER CR 32A	DAVIS	HM 22 Oe EDB, DBCP, 1, 2-DICHBROPROPAN	OPEN	FILE O- 2003 DATA
Frontier Fertilizer CR 32A	Davis	HM 22 Fe EDB, DBCP, 1,2-Dischloropropane	Closed	FILE 22F 1991-1992: US COURT COMPLAINT FOR COST RECOVERY, HAZARDOUS WASTE SITE BORDER ZONE DETERMINATION. See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 Ae EDB, DBCP, 1,2-Dichloropropane	Closed	FILE 22A PRE-1985: INVESTIGATION & BACKGROUND OF PESTICIDE DISPOSAL PRACTICES. FILE INCLUDES PRELIMINARY INJUNCTION DOCUMENTS. See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 Ke EDB, DBCP, 1,2-Dichloropropane	Closed	FILE K - 1999 DATA See FA 3866
Frontier Fertilizer CR 32A	Davis	HM 22 Le EDB, DBCP, 1,2-Dichloropropane	Closed	FILE L 2000 REPORT & CORRESPONDENCE. EXTRACTION AND TREATMENT CONTINUES

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Frontier Fertilizer CR 32A	Davis	HM 22 Ne EDB, DBCP, 1, 2, Dichloropropa	Closed	FILE# N, 2002 DATA
Frontier Fertilizer CR 32A	Davis	HM 22 He EDB, DBCP, 1,2-Dichloropropane	Closed	FILE H 1994-1997 DATA: DTSC OPERATING INTERIM GW EXTRACTION SYSTEM. USPA IS CONDUCTING QUARTERLY MONITORING. GROUNDWATER EXTRACTION TREATMENT AND BOTH DISCHARGE TO CITY SEWER AND REINJECTED INTO ACQUIFER. See FA 3866
FRUEHAUF TRAIL CORP 3600 W Capitol Ave	W. Sac.	HM 187 Solvents, Gasoline, Diesel	Open	SITE ASSESSMENT REVEALED GAS, DIESEL, & CHLORINATED SOLVENT CONTAMINATION.
GARCIA ECHO PLACE FACILITY 1362 Echo Place	Woodland	HM 125 Petroleum Hydrocarbons	Closed	AUTOMOTIVE FLUIDS & CLEANING AGENTS DISPOSED BY WASHING INTO STREET & FRONT YARD. OWNER ORDERED TO CEASE DISCHARGE, REMOVE CONTAMINATED SOILS. CASE REFERRED TO DISTRICT ATTORNEY. FILE CLOSED.
GARCIA RESIDENCE 34904 Paintridge Rd	Woodland	HM 269 Medical Waste	Closed	INVESTIGATION OF REPORTED ILLEGAL DISPOSAL OF MEDICAL WASTE. FOUND TO BE REGULAR REFUSE IN REDISH/PINK BAGS.
GARDEN GALLERY 2531 Del Monte St	W. Sac.	HM 253 Spray Paint	Closed	COMPLAINANT SAID FACILITY HAS COMMERCIAL SPRAY PAINTING OPERATION WITHOUT PAINT BOOTH. REFERRED TO AIR POLLUTION CONTROL DISTRICT.
GARY'S MOHAWK 427 C ST	W. Sac.	UST 178 Gasoline	Closed	CONTAMINATION DISCOVERED DURING AUG 3, 1990 TANK REMOVAL INSPECTION. CONTAMINATION APPEARS TO BE RESULT OF LEAKING TANK. File Closed. File was scanned and incorporated into file 178UTH.
GARY'S MOHAWK 427 C STREET	WEST SACRA	UST 178 PETROLEUM HYDROCARBONS	OPEN	PETROLEUM HYDROCARBONS AS GAS, DIESEL AND OIL. BTEX COMPOUND AND ETHANOL. PLEASE OPEN THE FILE.
GAS N SAVE (ARMOR OIL) Fifth & L St	Davis	UST 179 Gasoline	Closed	File L 179 - Inventory discrepancies in 1984 lead to the discovery of a release of up to a 30,000-gallons of gasoline and finding extensive soil & groundwater contamination. In 1985 remedial actions included a foundation vapor abatement system for the structure east of site and installation of a carbon treatment system for groundwater and (later) soil vapor. In 1986 to 1988 a City of Davis municipal was reconstructed to protect from potential upper aquifer groundwater contamination and a soil vapor extraction system was installed. As cleanup progressed the treatment systems were reconfigured in 1994 with minor medications during the next two years. Routine monitoring and annual reporting ceased in 1995. Wells associated with the site have been closed including 26 wells in 1993/1994, fifteen wells on the PG&E property in 1998 and two wells on City of Davis property in 2003. Site contamination persists but has been determined not to pose a threat to the adjacent City of Davis well (Number 14) or other wells used for domestic or municipal purposes. The plume appears to be stable and shrinking over time. File documents through 2002 were archived as 00179UTH in January 2003.
GE CAPITAL/TIP 601 Harbor Blvd	W. Sac.	HM 330 CHLORINATED SOLVENTS	Open	CHLORINATED SOLVENTS DISCOVERED. PART OF REGIONAL PLUME.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
GEORGE AOKI FARMS 37899 HWY 16	UST Woodland	550 Gasoline	Closed SOIL CONTAMINATION FOUND DURING UST REMOVAL. SOILS EXCAVATED & TREATED ON-SITE. FILE CLOSED. File archived to 550UTH in November 2003.
GEORGE HAMATANI RESIDENCE 49960 Central Ave	UST Clarksburg	2407 Gasoline	Closed File 2407 A hole was observed in a 550 gallon UST removed in August 1994. Gasoline was detected at concentrations up to 1,300 mg/kg in soil samples collected 9 feet below the tank. Soils were excavated with minor residues left in the soil at the edges of the excavation at depths of 7 to 12 feet below ground surface. Four consecutive quarters of groundwater monitoring indicated generally no detectable concentrations of gasoline, MTBE and BTEX constituents. File closed September 1997. File archived to 2407UTH in December 2003.
GILMORE, MARY 659 Sunset Circle	HM Davis	131 DDT, Sulfuric Acid, Others	Closed File H 131 - Contractor hired by trustee of estate (security pacific) in 1991 to remove small UST noticed hazardous materials in shed. County Hazmat notified. Chemicals located in back yard & garage packed in DOT drums & transported as hazardous waste. File archived to 00590HWG in January 2004.
GILMORE, MARY 659 Sunset Circle	UST Davis	590 Gasoline	Closed SOIL CONTAMINATION DISCOVERED DURING UST REMOVAL. SOILS EXCAVATED TO 22 FT. GROUNDWATER NOT IMPACTED. FILE CLOSED. File archived to 590UTH in December 2003.
GOLDEN STATE FLORA 2200 Del Monte	HM W. Sac.	229 Silver	Closed REPORT TO DTSC OF FACILITY DUMPING SOLUTION CONTAINING SILVER IN BACK LOT ONTO GROUND & INTO SEWER. NO INVESTIGATION CONDUCTED DUE TO STAFF SHORTAGE. CITY, DA OR DTSC MAY HAVE INVESTIGATED.
GOLDEN STATE FLORA 2200 Del Monte	HM Woodland	407 Citric Acid	Closed CITRIC ACID DISCHARGE TO GUTTER, PH-4 AT STREET. ORDER WRITTEN, DISCHARGE STOPPED, CASE CLOSED.
GOODYEAR TIRE 1641 Merkley St	HM W. Sac.	266 Hydraulic Oil	Closed SOIL FOUND TO BE CONTAMINATED DURING REMOVAL OF AUTOMOTIVE HOIST. SOILS EXCAVATED. CASE CLOSED.
GRAYS HEAD & BLOCK/BRUNCH SITE Jefferson Blvd	HM W. Sac.	265 Waste Oil	Closed WASTE OIL APPARENTLY DUMPED FROM GRAY'S SIDE OF FENCE FLOWS ONTO BRUNCH VACANT LOT. GRAY IS EXCAVATING SOIL FOR DISPOSAL. RP FILED TO PROVIDE EVIDENCE OF APPROVED DISPOSAL OF SOILS. CASE CLOSED.
GREEN RESIDENCE 2506 Lafayette Lane	HM Davis	262 Waste Oil	Closed AUTO LEAKING WASTE OIL ONTO DRIVEWAY, STREET, AND MAYBE INTO SOILS ALONG DRIVEWAY. NOTICE TO ABATE ISSUED TO RESIDENT. CASE CLOSED.
GREYHOUND LINES 1874 South River Road	HM W. Sac.	166 Diesel	Closed File H 166 - March 1992 spill at the dispensers resulted in a 200-gallon diesel release. Contaminated soils were excavated. File archived to 00192HWG in January 2004.
GREYHOUND LINES 1874 South River Road	UST W. Sac.	192 A Diesel	Open DURING REMOVAL & REPLACEMENT OF UNDERGROUND TANKS IN MAY 1995, SOIL CONTAMINATION OBSERVED AT ONE END OF THE DIESEL TANK EXCAVATION.

Facility	File/Number	Status	Comments	
GREYHOUND LINES 1874 South River Road	UST W. Sac.	192 B Gasoline & Diesel	Open	QUARTERLY GROUNDWATER MONITORING REPORTS. No MTBE has been found at this site
GROWERS AIR SERVICE CR 27	HM Davis	27 Pesticides, Gasoline	Closed	File H 27 - Complaint received in 1985 of rinse water disposal to ground after pre-treatment. YC Ag Dept issued a cease & desist order, Environmental Health referred case to RWQCB. No action taken by board. File archived to 2314HWG in December 2003.
GROWERS AIR SERVICE 41167 CR 27	UST Woodland	2314 Gasoline	Open	: SOIL CONTAMINATION OBSERVED DURING OCT '97 UST REMOVAL. Investigation indicates soil and ground have been impacted beneath the two former USTs at this site, but the source(s) of contaminants and hydrogeology have not been determined. There are also above ground fuel tanks at the facility which need to be investigation to determine if they have leaked. Facility directed by the CVRWQCB to submit a workplan for further investigation March 2000.
H & H CLEANERS 1228 MERKLEY	HM WEST SAC	464 UNDETERMINED	OPEN	PERCHLOROETHENE INVESTIGATION SEE ALSO RELATED FILES H440 AND H463
HALBACH RESIDENCE 711 Mckinley	HM Woodland	237 Waste Oil	Closed	TENANT REPORTED LANDLORD REFUSES TO REMOVE BUCKET OF WASTE OIL IN FRONT OF PROPERTY. CASE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.
Half Moon Produce CR 29A Noth side of barn	HM Winters	448 Diesel	Closed	Diesel leak from AST reported July 13, 2001. Tank emptied and moved out of the way. Contaminated soil removed soil samples taken. Very low levels detected by analytical lab methods on 9-5-01. No further action required based on these results(9-19-01).
Hamilton Engine Sales 885 Stillwater Rd	HM W. Sac.	127 Waste Oil	Closed	File H 127 - Soil contamination from steam cleaning discharge excavated & disposed. File closed August 1991. File archived to 04253uth in January 2004.
HARBOR BLVD EXPANSION PROJECT Harbor Blvd, W Capitol to Reed	HM W. Sac.	247 Petroleum Hydrocarbons	Closed	FILE A: SOIL & GROUNDWATER INVESTIGATION REPORT COMPLETED PRIOR TO INITIATION PROJECT TO WIDEN ROAD IN 1995. ADDITIONAL INVESTIGATION, LETTERS & DATA REGARDING GROUNDWATER TREATMENT & SOIL DISPOSAL DURING PROJECT. CASE CLOSED AS PROJECT HAS COMPLETED THE EXCAVATION PHASE.
HARBOR BLVD. WATER MAIN PROJECT HARBOR BLVD.	HM WEST SACRA	454 Pphse II Site Assessment	Closed	PHASE II SITE ASSESSMENT ALONG HARBOR BLVD. AND INDUSTRIAL BLVD. PRIOR TO A WATER MAIN PROJECT.
HARTMAN BROTHERS 104 Matmor	UST Woodland	198 Diesel, Gasoline	Closed	DURING TANK REMOVAL CONTAMINATION DETECTED. SOIL EXCAVATED & SAMPLING DONE. FURTHER WORK NOT REQUIRED. SITE CLOSED. File scanned - see 198UTH.
HARVEY LYMAN AG SERVICE Route 1 Box 115A	HM Clarksburg	111 TPH, Benzene	Closed	FILE CLOSED.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
HAYES RANCH BIOSOLIDS Hungry Hollow Region	HM Esparto	298 Biosolids	Closed	DISCHARGE TO AGRICULTURAL & RANGE LANDS OF BIOSOLIDS. SITE CONTAINS 4,320 ACRES. LOCATION IS SOUTH AND WEST OF DUNNIGAN, NORTH OF ESPARTO. CASE CLOSE.
HAYNES, MELVIN CR 90 1/2 Mile N Of CR 12A	HM Dunnigan	28 No Release	Closed	DRUM, OPEN OF UNKNOWN SOLID & DRUM OF UNKNOWN LIQUID APPARENTLY ABANDONED. DRUMS REMOVED BY OWNER. FILE CLOSED.
HAYSHIDA/BUFFALO MACHINERY 4101 W Capitol Ave	UST W. Sac.	201 Diesel	Closed	SOIL CONTAMINATION DISCOVERED DURING REMOVAL OF A 2,000 & 4,000 GAL PREVIOUSLY UNTESTED GASOLINE TANKS. SOIL EXCAVATION TO GROUNDWATER (13 FT) FURTHER ASSESSMENT FOUND VERY LOW LEVEL OF HYDROCARBONS. FILE CLOSED. File scanned - see electronic file 201UTH.
Heco 255-A Industrial	HM Woodland	368	Closed	
HEIDRICK FARMS CR 27 & I-505	HM Woodland	113 Miscellaneous	Closed	WASTE OIL & SOLVENT CONTAINERS ABANDONED ON PROPERTY NOV 21, 1990. REMOVED BY HAZ WASTE HAULER DEC 10, 1990. FILE CLOSED.
HEIDRICK FARMS MAINTENANCE HDQ 18284 CR 97	HM Woodland	292 4, 4' - DDE, Metals	Closed	MAINTENANCE YARDS' EVAPORATION DITCH FROM STEAM CLEANER DISCHARGES TO AN IRRIGATION CANAL. INSTALLATION OF OIL/WATER SEPARATOR AND SOIL REMEDIATION OCCURRING IN 1989 AND 1990. CURRENT SITUATION UNKNOWN.
Heidrick Farms, Conaway Yard CR 25	HM Woodland	293 Petroleum	Closed	Petroleum and pesticide investigation in drainage ditch. No pesticides found, low levels of TPH found, REQCB required no further action.
HELLOF, DOROTHY DBA POST OIL 3633 Seaport Blvd	HM W. Sac.	328 Diesel, Oil	Closed	DURING PHASE II ASSESSMENT SOIL SAMPLES COLLECTED. DIESEL CONTAMINATION FOUND. SOIL EXCAVATED & TRANSPORTED TO DISPOSAL SITE. SITE CLOSED.
HELVETIA PARK 20500 HWY 16	HM W. Sac.	254 Garbage, Tires, Paint	Closed	INFORMANT SAID FACILITY OPERATES LANDFILL WITHOUT PERMIT. REFERRED TO SOLID WASTE PROGRAM.
HERNANDEZ TRUCKING CR 89 1/4 Mi S Of Hwy 16	HM Madison	102 Petroleum	Closed	CLEANUP PARTIALLY COMPLETED AND SOME STEPS TAKEN TO PREVENT DISCHARGE OF HYDROCARBONS (OIL AND DIESEL) TO SURFACE SOILS. CASE CLOSED.
HEXYDINE DRILLING CO Deaner Ave	HM Woodland	31 Vehicle Wash Waste	Closed	File H 31 - Environmental investigation conducted at the request of the RWQCB following an inspection found that a discharge from a steam cleaning sump and leach line contaminated shallow soils with volatile aromatic and chlorinated organics, and petroleum hydrocarbons. Neither the discharged material or the soils were found to meet hazardous waste levels nor contamination was limited in aerial extent. No heavy metal or PCB contamination was identified. No follow up investigation was required by the RWQCB. File archived to 00208HWG in December 2003.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
HILDEBRAND AUTO ELECTRIC 480 College St	HM Woodland	32 e Waste Oil	Closed WASTE OIL DRUM SPILLED CONTENTS ON FENCE, ASPHALT PARKING LOT, & SOIL. CONTAMINATES REMOVED BY HILDEBRAND AUTO ELECTRIC. See FA 5814
HOLT FACILITY 5200 Chiles Rd	UST Davis	210 Gasoline, Waste Oil	Closed SOIL CONTAMINATION FOUND DURING TANK REMOVAL. ASSESSMENT & REMEDIATION COMPLETED. NO GROUNDWATER IMPACTED. ENFORCEMENT ACTION TAKEN FOR ILLEGAL TANK & CONTAMINATED SOIL DISPOSAL. FILE CLOSED. File documents scanned - See file 210UTH.
Home Depot Gibson & HWY 113	HM Woodland	415 Geotechnical Investigation	Open Permits issued for Geotechnical soil boring investigation for proposed facility.
HOTEL WOODLAND 436 Main St	HM Woodland	256 Asbestos	Closed RECEIVED COMPLAINT FROM CALIFORNIA DEPARTMENT OF TOXIC SUBSTANCE CONTROL. COMPLAINT WAS INVESTIGATED & VIOLATIONS WERE NOT FOUND.
HUDSON STATION 500 C ST	UST W. Sac.	250 Gasoline	Closed LEAK DISCOVERED DURING AUGUST 1987 TANK REMOVAL, SOIL REMEDIATION COMPLETED AUG 1987. FILE CLOSED.
HUNT-WESSON FOODS 1111 Covell Blvd	UST Davis	36 Diesel	Closed File H 36 - Leak discovered in July 1986, soil remediation completed may 1986. File closed January 1989. Plant closed. This plant may have discharged copper exceeding EPA Recommended Continuous Water Quality Criteria. File archived to 36UTH in December 2003.
HYDRA RELOAD CENTER INC 1497 TANFORAN	H WOODLAND	4281 e ARSENIC, CHROMIUM, COPPER	OPEN
I ST DEVELOP CO (DON MILLER) 920 Third St	UST Davis	528 Gasoline, Chlorinated Solvents	Open INVESTIGATION UNDERWAY - SEE ALSO FILES H383, L74, AND H324.
INJECTION SYSTEMS MARTIN WELL CR 25A W Of CR 97	HM Woodland	96 e Condensate Oil	Closed SOILS CONTAMINATED BY SPILL OF 1,000 GALS OF 5% BRINE CONDENSATE EXCAVATED & AERATED ON-SITE. FILE CLOSED. See SIRE File FA0010472.
INK COMPANY 1871 Enterprise Ave	HM W. Sac.	33 e Ink & Solvent Waste	Closed SEVERAL SPILLS OR IMPROPER DISPOSAL INCIDENTS ONTO THE GROUND, IN STORM SEWERS, AND DISPOSAL TO THE YOLO CENTRAL LANDFILL OF INK AND SOLVENT WASTES. ALSO VIOLATION OF CAL HAZ WASTE REGULATIONS NOTED.
INK COMPANY 1115 Shore St	HM W. Sac.	99 C Mineral Seal Oil	Closed FILE C 1993 - 1999: INITIAL REMEDIATION RESULTED IN STRUCTURAL DAMAGE. SOIL EXCAVATION HAULTED. RAIL SPUR TO BE REPLACED. ALTERNATIVE REMEDIATION (IN-SITU) TO BE EVALUATED.
INK COMPANY 1115 Shore St	HM W. Sac.	99 A Mineral Seal Oil	Closed FILE A 1990-1991: ASSESSMENT OF 100 GAL RAIL OFFLOAD SPILL FOUND SUBSTANTIAL SOIL CONTAMINATION. INITIAL REMEDIATION COMPLETED. FILE CONTINUES.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
INK COMPANY 1115 Shore St	HM W. Sac.	99 B Mineral Seal Oil	Closed FILE B 1992: GROUNDWATER CONTAMINATION IDENTIFIED. PHASE II REMEDIATION TO ADDRESS BOTH SOIL & GROUNDWATER. SEE ALSO #HM-8933 FOR RELATED INFORMATION ON THIS SITE.
INTERSTATE OIL 3022 EVERGREEN AVE	L WEST SAC	269 E GAS, DIESEL, BTEX, MtBE, TBA	OPEN SOIL AND GROUNDWATER CONTAMINATION FOUND DURING TANK REMOVAL. SOILS WERE OVEREXCAVATED.
INTERSTATE OIL 3022 EVERGREEN	UST WEST SACRA	269 e GASOLINE/DIESEL	OPEN ROUTINE SAMPLING DURING TANK RENEWAL INDICATED ELEVATED LEVELS OF PETROLEUM CONTAMINATION IN SOIL AND GROUNDWATER. 1100 CUBIC YARDS OF MATERIAL WAS REMOVED. CASE REFERRED TO RWQCB.
INTERSTATE OIL CARDLOCK 3022 EVERGREEN	UST WEST SACRA	269 GAS & DIESEL	OPEN MAY 2004- SOIL AND GROUNDWATER CONTAMINATION FOUND IN THE GAS AND DIESEL HYDROCARBON RANGES. JUNE 2004 CONTAMINATED SOIL (APPROX 800 CUBIC YARDS) REMOVED.
Interstate Oil Co - Main St (Norcal) 183 Main St (West)	UST Woodland	267 A Petroleum Hydrocarbons	Open This site has been used for the wholesale and retail sales of petroleum-based fuels and products since 1940. A total of 5 USTs were installed sometime prior to 1980. Elevated levels of hydrocarbons were observed in soils following tank removal in 1999. Diesel has been identified in groundwater, as well as low levels of gasoline, xylene and MtBE. A workplan to delineate soil and groundwater conditions was submitted in July 2002. Quarterly ground water monitoring required in October 2002.
J B J AUTO 1032 CLOVER	HM Woodland	408 Various Auto Waste Fluids	Closed INSPECTION DONE, VIOLATIONS FOUND AND CORRECTED.
JACKPOT OIL/FOOD MART 615 East St	UST Woodland	218 Gasoline, BTEX, MTBE	Closed Pre tank upgrade assessment found soil & GW hydrocarbon impact, tanks replaced, site investigated. No active remediation was required. There was no significant offsite impact, study indicates plume is stable and can be naturally attenuated. Closure granted by RWQCB Dec 99. Wells abandoned in January 2000. File scanned January 2002, see electronic file 218UTH Leaky Tank Cleanup section to view documents.
Jandera Mobil - former Dearborn 1600 Eighth St (East)	UST Davis	220 E Gasoline, Waste Oil	Closed FILE E 1996/1997- WELLS 5 THROUGH 9 INSTALLED. MONITORING INDICATES GASOLINE IS NOT DEFINED AND MAY BE OFF SITE SOUTH AND WEST OF SITE.
Jandera Mobil - former Dearborn 1600 Eighth St (East)	UST Davis	220 C Gasoline, Waste Oil	Closed FILE C: 1994 (FORMERLY GEORGE JANDERA MOBIL) COUNTY REQUESTS ADDITIONAL ASSESSMENT TO DEFINE GROUNDWATER CONDITIONS.
Jandera Mobil - former Dearborn 1600 Eighth St (East)	UST Davis	220 A Gasoline, Waste Oil	Closed FILE A 1991-1992: SOIL CONTAMINATION FOUND DURING TANK REMOVAL. INVESTIGATION BEGAN IN 1992.
Jandera Mobil - former Dearborn 1600 Eighth St (East)	UST Davis	220 G Gasoline	Open FILE G- Neither the lateral or vertical extent of contamination has been delineated. Groundwater monitoring continues and a workplan for further investigation is being prepared in mid 2002. RWQCB is lead agency.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Jandera Mobil - former Dearborn 1600 Eighth St (East)	Davis	UST 220 F Gasoline	Closed	FILE F-1998 DATA
Jandera Mobil - former Dearborn 1600 Eighth St (East)	Davis	UST 220 D Gasoline	Closed	FILE D-1995-QUARTERLY MONITORING. ASSESSMENT REMAINS INCOMPLETE. COUNTY REQUESTS ADDITIONAL ASSESSMENT.
Jandera Mobil - former Dearborn 1600 Eighth St (East)	Davis	UST 220 B Gasoline, Waste Oil	Closed	FILE B 1993: (FORMERLY GEORGE JANDERA MOBIL). INITIAL INVESTIGATION FOUND GASOLINE AND WASTE OIL IN GROUND WATER.
JDL CORPORATION 832 F ST	W. Sac.	UST 77 Diesel	Closed	File L 77 - Soil & groundwater contamination observed during 1990 removal of 2 diesel underground storage tanks. Soils excavated for offsite disposal. Groundwater TPH levels dropped from 92,000 ppb in 1990 to 240 ppb in Sept 1997. BTEX is non-detect. Case closed October 1997. File archived to 00077UTH in January 2004.
JEFFERSON BLVD HYDROCARBONS Jefferson From 17th To 19th St	W. Sac.	HM 57 Gasoline	Closed	EXTENSIVE GASOLINE FOUND IN GROUNDWATER AT SHALLOW DEPTH RESULTED IN INVESTIGATION TO DETERMINE RESPONSIBLE PARTY BY RWQCB. THE RWQCB DETERMINED IN MARCH 1992 THAT TESORO PETROLEUM WAS RESPONSIBLE. SEE FILE HW 9083 FOR FOLLOW-UP. FILE CLOSED.
JEHOVAH WITNESS KINGDOM HALL CR 99 & CR 17	Yolo	HM 122 Petro Hydrocarbons and Lead	Closed	ENVIRONMENTAL INVESTIGATION OF PROPOSED CHURCH SITE FOUND NO SIGNIFICANT HAZARDS. SEE ALSO UST 91-1-0583 FOR TANK CLOSURE ON ADJACENT SITE. FILE CLOSED.
JEREMIAH POOLS & SPAS HWY 99W & I-5	ZAMORA	HM 139 Solvents	Closed	BUSINESS OPERATING WITHOUT PERMITS. NO APPARENT PLAN FOR DISPOSAL OF HAZARDOUS WASTES. SEVERAL AGENCIES INVESTIGATING. FACILITY CLOSED NOV 1991. COULD NOT MEET COUNTY HEALTH, PLANNING, OES, & AIR BOARD REQUIREMENTS.
JOE HEIDRICK ENT, CONAWAY EQUIP 450 NE Corner Of CR103 & CR27	Woodland	HM 29 e Steam Cleaner Discharge, Diese	Open	STEAM CLEANER WASHDOWN PAD DISCHARGES INTO A DRAINAGE DITCH. SOIL & GROUNDWATER DIESEL CONTAMINATION DUE TO AST AND UST. RWQCB IS LEAD. FILE INCOMPLETE.
JOHN F WILSON ASSOCIATES 203 J ST	Davis	HM 369 e TCE	Open	THIS SITE IS CURRENTLY NOT BEING INVESTIGATED, NOR HAS CONTAMINATION BEEN CONFIRMED. THIS FILE CONTAINS HISTORICAL INFORMATION REGARDING PAST COMPLAINTS AT THIS FACILITY.
JOHN PEREZ & SONS Clarksburg & School Rd	Clarksburg	UST 287 Gasoline, Unleaded	Open	UST REMOVED IN 1987. SOILS EXCAVATED TO 9 PPM. EXCAVATED SOILS STOCKPILED ON SITE. YCEH REQUESTING PROPOSAL FOR REMEDIATION OR DISPOSAL OF EXCAVATED SOILS. CVRWQCB now handling case. Further investigation required by CVRWQCB July 2002. File has been scanned. See Adobe Acrobat file 287 UTH
JOHN'S HAULING 1313 Camphor Lane	Davis	HM 274 Gasoline	Closed	GASOLINE VAPORS FROM LEAKY TANK IN BOAT PARKED ON STREET IMPACTING NEIGHBORS. OWNER ORDERED TO REMOVE/REPAIR TANK.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
JORRIN, ALFONSO 325 FOURTH ST.	HM W. Sac.	447 Waste Oil	Closed WASTE OIL CONTAMINATION ON SOIL DUE TO AUTO REPAIRS BY A TENANT.
JTP INC CR 31 & CR 89	HM Winters	291 Tomatoe Waste	Closed ESTIMATED 25,000 GAL OF WASTE DICED TOMATOES FROM CAMPBELLS DISCED INTO APPROX 10 ACRES OF FARMLAND.
KAROLTON ENVELOPE CO 2660 Pprt St	HM W. Sac.	36 e No Release	Closed VARIANCE FROM HAZ WASTE PERMIT REQUIREMENTS ISSUED BY DEPT OF HEALTH SERVICES AS FIRM INDICATED IT PRODUCED LESS THAN 100 KILOGRAMS OF HAZARDOUS WASTE PER MONTH. See FA 9857
KEITH PACE TRUCKING CR 99W & CR 97	HM Yolo	168 Diesel	Closed ON AUG 18, 1991 TWO TRACTOR TRAILERS HAULING TOMATOES COLLIDED & 35 GALS OF DIESEL SPILLED ONTO ROAD & SHOULDER. SOIL EXCAVATED TO DEPTH OF 7 FT. FILE CLOSED.
KEITH VOLKERTS CR 105 & CR 32A	HM Davis	138 UST	Closed MR. VOLKERTS RECEIVED TWO OLD UNDERGROUND TANKS TO USE ABOVE GROUND. DAVIS FIRE REFUSED TO ALLOW THE TANKS TO BE USED ABOVE GROUND. THE TANK OWNER IS CONTRACTING WITH A HAZARDOUS WASTE HAULER FOR TRANSPORTATION TO A DISPOSAL SITE.
Kinder Morgan - 1991 Causeway Release Causway (NW of W Sac)	HM W. Sac.	88 Gasoline	Closed FILE A TECHNICAL REPORTS: PIPELINE RUPTURE RELEASED 84,000 GALS GASOLINE. ESTIMATED 25,000 GALS RECOVERED. 35,000 CU YDS SOIL EXCAVATED & TREATED ON-SITE. FILE CONTINUES TO 88B. FOLLOWING SOIL REMEDIATION COMPLETED IN JAN 1991 GROUNDWATER MONITORING CONDUCTED THROUGH MID 1992 WITH NO SUBSTANTIAL CONTAMINATION OBSERVED. FILE CLOSED.
Kinder Morgan - W Sac Station 1570 South River Road	HM W. Sac.	58 e Diesel	Open GROUNDWATER & SITE ASSESSMENT SOIL RESULTS SHOW HIGH CONCENTRATIONS PETROLEUM HYDROCARBONS. Further investigation continues during 2001. A soil vapor extraction system is in operation and feasibility studies were completed to assess options for groundwater treatment. Free product was observed in a recovery well in early 2002. A feasibility study for further remediation is due in Feb 2003. Currently a granular activated carbon system is use for the soil vapor extraction and treatment system. RWQCB contact is Devra Lewis at (916) 255-3119. See SIRE file FA0004510
Kinder Morgan - W Sac Station 1540 South River Road	HM W. Sac.	244 Diesel	Closed PIPELINE VALVE FAILURE RESULTED IN 400 GAL DIESEL FUEL SPILL TO SOILS. See H 58 for related investigation and cleanup at this site.
Kinder Morgan East Yolo Causeway Rupt Causway (NW of W Sac)	HM W. Sac.	425 Petroleum	Closed Files A - B: In May 2000, a small split in the pipeline released petroleum fuel at the site, which degrades soil, groundwater, and a seasonal pond. Kinder Morgan Energy Partners (DEMP) completed emergency response actions to repair the pipeline and remove contaminated soil from the site. Kemp performed an additional investigation to determine the extent of contaminants in soil, groundwater, and pond sediments completed in Oct 2000. The CVRWQC requested a workplan in Dec 2000 based on their review of this report requesting a work plan for further assessment of soil and groundwater contamination at the site. Additional assessment continue through 2001

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
KINGS TRUCK STOP 1056 Harbor Blvd	UST 225 W. Sac. Diesel	Closed	FILE A 1985-1986: LEAKY UST REMOVED, SOILS EXCAVATED EXCEPT LIMITED AREA UNDER HARBOR BLVD. GROUNDWATER PUMPED FROM THE PIT REMOVED TO REFINERY FOR TREATMENT. FILE CONTINUES TO 225B. FILE B 1987-1989: GROUNDWATER MONITORED THROUGH JUNE 1989. RWQCB NOTED SOME SOIL CONTAMINATION REMAINS BUT NO THREAT TO GROUNDWATER. FILE C TECHNICAL REPORTS. CASE CLOSED. Information in this file was scanned. See 225UTH.
KLOSS PROPERTY 36397 N CENTER STREET	L 6138 e CLARKSBURG DIESEL AND MOTOR OIL	OPEN	
K-MART Main St (East)	HM 236 Woodland Unknown	Closed	REPORTED SPILL IN MENS/BOYS SHOE & CLOTHING DEPARTMENT MADE CUSTOMER SICK. INVESTIGATION FOUND NO EVIDENCE OF SPILL.
Knights Landing Boat Ramp in Drain Colusa Basin Drain	HM 470 Knights Landin Unknown Foam	Closed	Unknown foam on the water at the weir. No hazardous constituents found.
K'S EXPRESS LUBE 116 Lincoln Ave (West)	HM 336 Woodland Antifreeze	Open	ILLEGAL DISPOSAL OF ANTIFREEZE. REFERRED TO DA.
LANE FACILITY South River Road	HM 288 W. Sac. Motor Oil	Closed	SEVERAL DRUMS OF USED OIL, INCLUDING ONE FULL WITH NO LID STORED ON PROPERTY. OIL WAS REMOVED FOR RECYCLING. CASE CLOSED.
LAYNE-WESTERN 276 CR 98	HM 116 Woodland Waste Oil	Closed	RUN-OFF FROM STEAM CLEANING PAD CONTAMINATED SOIL WITH WASTE OIL. SITE CLEAN ON MAR 26, 1991. File Scanned. See 229UTH.
LAYNE-WESTERN 275 CR 98	UST 229 Woodland Gasoline	Closed	MINOR OVERFILL SPILLS DISCOVERED DURING NOV 1986 TANK REMOVAL, SOIL REMEDIATION COMPLETED NOV 1986. GROUNDWATER TO BE MONITORED EVERY SIX MONTHS. FILE CLOSED 1988. Formal closure letter written in November 2001. File Scanned. See 229UTH. This file is incorrectly referenced in some material as H119. Information from that file is included in the 229UTH file.
LEE STABILIZATION 2086 E MAIN STREET	HM 484 WOODLAND MOTOR OIL	OPEN	PHASE II REPORT COMPLETED 9/2003. MOTOR OIL CONTAMINATION OF GROUNDWATER. CASE REFERRED TO SLIC UNIT OF CVRWQCB.
LEEPER, SHIRLEY (PROPERTY) 26 Kern St	HM 137 Woodland Waste Oil	Closed	WASTE OIL SPILLED ONTO SOIL NEXT TO DRIVEWAY. SOIL EXCAVATED & MIXED INTO CONCRETE.
LEND LEASE 3610. W Capitol Ave	UST 257 W. Sac. Diesel	Closed	FILE A GENERAL FILE: SOIL CONTAMINATION FOUND DURING DEC 1987 DIESEL 12,000 GAL UST REMOVAL. SITE INVESTIGATION COMPLETED DEC 1992. FINAL INVESTIGATION FOUND NON-DETECTABLE LEVELS IN BOTH SOIL & GROUNDWATER. FILE CLOSED Feb 1997.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Level III Communicatiaons 1075 Triangle Court	H W Sac	475 Ethylene Glycol	Closed Facility plumbing allowed cross connection between potable water system and equipment cooling system. Ethylene glycol and related substances entered potable water supply. Plumbing cross connection eliminated, potable water system cleaned removing all contaminates. Case cosed.
Lewis Cleaners 670 G ST	HM Davis	389 e Volatile Organic Compounds	Open 389 - Studies at an adjacent site indicated this facility is the source for VOC's found in soil and groundwater. Investigation has not yet determined the lateral or vertical extent of contamination. An indoor Air Quality Assessment is underway. A Screening Health Risk Assessment will be conducted upon completion of the Air Quality assessment. A pilot study for soil vapor recovery has also been proposed but not initiated as of Feb 2003. The CVRWQCB is the lead agency. See FA 6141
LIEBHART PROPERTY 34191 CR 12	HM ZAMORA	333 Illegal Drug Lab	Closed LETTER SENT TO OWNER TO CONDUCT INVESTIGATION. CASE CLOSED.
LIFT ALL INC 2399 Sellers Way	UST W. Sac.	231 Gasoline	Closed SOIL CONTAMINATION FOUND DURING JAN 1990 REMOVAL OF 550 GAL GASOLINE TANK. SOILS EXCAVATED TO 14 FT DEPTH, FINAL SAMPLES WERE NON-DETECTABLE FOR HYDROCARBONS. SITE CLOSED. File scanned January 2002, please see electronic file UTH231 Leaky Tank Cleanup section to view documents.0
LIGHTHOUSE 7TH & E ST PROJECT Between E/F/ 6TH & 7TH STS	HM W. Sac.	175 Asphalt	Closed 1989 environmental assessment found hydrocarbons & asphalt in top one foot of soil. YCEH found site acceptable for development after asphalt removal.
LINDEMAN TRUCKING 800 E St	HM W. Sac.	242 Hydrocarbons	Closed REPORT OF STEAM CLEANING OPERATIONS IMPACTING SURFACE SOILS. TIMELY INVESTIGATION COULD NOT BE CONDUCTED. CASE CLOSED.
LIQUOR AND FOOD - MUNDY 4810 Chiles Rd	UST Davis	172 A Gasoline, Diesel	Open Petroleum hydrocarbons and MTBE found in soils during April 1999 removal gasoline and diesel underground storage tanks.
LIQUOR AND FOOD MUNDY 4810 CHILES ROAD	UST DAVIS	172 B FILE B : 2003 DATA	OPEN FILE B : 2003 DATA
LONG, DALE (WATER SYSTEM) First & Hays St	HM Dunnigan	35 e Solvents	Closed MAY/JUNE 1988 WATER TESTING OF DRINKING WATER WELLS FOUND TETRACHLOROETHENE, CARBOM TETRACHLORIDE, CHLOROFORM, 1,1-DICHLOROETHENE. NOVEMBER 1988 FOUND ALL TO BE AT LEVELS BELOW STATE ACTION LEVELS. See FA 96 file dated 7/2/87 "Press Release"
LOPEZ AUTO BODY 1575 Case Place	HM Woodland	289 e Waste Oil	Closed SEVERAL DRUMS OF WASTE WAS LEFT ON PROPERTY AFTER CLOSURE OF BUSINESS. OWNER DIRECTED TO HAVE WASTE PROPERLY DISPOSED. CASE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
LOS RIOS FARMS CR 32A & Mace Blvd	HM Davis	37 e Waste Oil	Closed WASTE OIL & OTHER VEHICULAR WASTE FLUIDS DISPOSED DURING PAST YEARS TO SOIL SURFACE. FIRM ORDERED TO STOP DISPOSAL TO GROUND & TO REMOVE & DISPOSE AS HAZARDOUS WASTE ALL OBVIOUSLY CONTAMINATED (STAINED) SOILS. See FA 5703
Los Rios Farms - Hays Lane Fac Hay's Lane at CR 102 & I-5	HM Woodland	446 Hydrocarbons	Open Old UST removal site and pressure truck wash facility resulted in diesel, oil and grease contamination at former fueling area and sump associated with car wash.
LOWER N W SEWER INTERCAP PROJ South River Road	HM W. Sac.	397 Study	Closed Study to assess existing subsurface conditions for possible Sacramento River crossings for pipeline alignments
LOWRIE TRUCKING 9 Main St	HM Winters	38 Waste Oil	Closed File H 38 - 1987 complaint investigation revealed spills around fill to above ground waste oil tank to ground surface. Firm ordered to stop spills, take measures as needed to prevent future accidental releases & to excavate & dispose contaminated soils as hazardous waste. File closed 1987, file archived to 235HWG in December 2003.
LOWRIE TRUCKING 9 Main St	UST Winters	235 Diesel	Closed TANK FAILED TESTING DEC 1985, REMOVED MAY 1987, SOIL REMEDIATION COMPLETED JUNE 1987. FILE CLOSED.
LUCAS, JOHN & SALLY 38600 JEFFERSON BL	UST Clarksburg	3296 Diesel	Closed File 3296 - Soil contamination was observed during the 1997 removal of a home heating oil UST. Twenty cubic yards of soil was excavated and disposed off-site. Low levels of hydrocarbons were left in the soil. Groundwater was also minimally impacted. Risk assessment found no sensitive receptors with a completed exposure pathway. File closed November 1998, file archived to 3296UTH in December 2003.
LUCERO/NORFORK RESIDENCE 1013 Adams ST	HM Winters	270 Waste Oil	Closed DISPOSAL OF WASTE OIL TO GROUND ALONG FENCELINE.
LUCKY FRUIT & PRODUCE CO 1520 South River Road	HM W. Sac.	39 e Petroleum Products	Closed File 39 H - 1988 Complaint investigation revealed discharge from oil/water separator from steam cleaning operation to street & diesel spillage from fueling operation to street observed on separate occasions. Contaminated soils removed, operational practices & plumbing changes eliminated discharge. File archived to 00236HWG in December 2003.
M & M MARINE SALVAGE 2050 E MAIN ST STE K	HM Woodland	405 Flammable Solvents - Paints	Closed INSPECTION DONE, NO VIOLATIONS FOUND. FILE CLOSED.
M & M MINI MART 1085 East St	UST Woodland	39 Gasoline	Open GASOLINE CONTAMINATION FOUND DURING TANK REMOVAL. LETTER SENT REQUIRING MORE WORK. SECOND ORDER WRITTEN 6/28/99. RWQCB taking the lead May 2000. Requesting MTBE Data.
M & M SALVAGE 0 CR 25 WOODLAND	H WOODLAND	493 e TPHd, tPHmo, tPhg, MTBE, TAME,	OPEN SOIL AND GROUNDWATER IMPACTED WITH HYDROCARBONS.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
M G TRUCK SERVICE 520 Galveston St	HM W. Sac.	117 Dielol and Waste Oil	Open Contaminated soil discovered during 1991 UST inspection. Soil was excavated and put at back of property, left for natural degradation. TPH in soil had not fully biodegraded in 1999. Need proper disposal before issuing no further action letter. File archived as 00237HWG in January 2004.
M H S TRUCKING West St & Bernard Ct	HM Woodland	40 e Diesel	Closed RUPTURED TRUCK CROSS-OVER LINE RELEASED 10 GALS TO STREET & SOILS. PRIVATE CONTRACTOR FOR CITY CONDUCTED CLEANUP.
MACLAUGHLIN & COMPANY 1401 Shore St	UST W. Sac.	588 Gasoline	Closed SOIL CONTAMINATION FOUND DURING ROUTINE TANK REMOVAL. SOIL AERATED & NONDETECT. AERATED SOIL PLACED IN EXCAVATION. File closed April 1994. File archived to 588UTH in December 2003.
MACMILLAN BLOEDEL Port of Sacramento	HM W. Sac.	163	Closed Environmental review of proposed newspaper recycling plant. Project was not completed and the plant was not constructed. File archived as 00299HWG (Port of Sacramento) in January 2004.
Madding Air Conditioning 17 F Arboretum Drive	UST Davis	2275 Hydrocarbens	Closed File transfer from Solano County. Cleanup by over excavation of former UST pit. File closed. File archived to 2275UTH.
MADDING AIR CONDITIONING 17 Arboretum Dr	UST Davis	2275 Gasoline	Closed HOLES IN TANK FOUND DURING 1992 TANK REMOVAL. SOIL RESULTS SHOWED CONTAMINATION AT 10,000 MG/KG AS GASOLINE. SITE ORIGINALLY IN SOLANO COUNTY NOW IN YOLO COUNTY. SOIL EXCAVATED. NO FURTHER WORK REQUIRED. File archived as 629UTH in December 2003.
MALNAR 9690 CR 93B	HM ZAMORA	432 MOTOR OIL	CLOSED
MALNAR PROPERTY 9690 CR 93 B	HM ZAMORA	432 Motor Oil	Open WASTE MOTOR OIL LEFT ON PROPERTY BY A PREVIOUS TENANT. OWNER ASKED TO CLEAN UP OIL AND CONTAMINATED SOIL.
MARIANI NUT COMPANY 709 Dutton St	HM Winters	149 Chlorine	Closed RECEIVED COMPLAINT OF CHLORINE & OIL IN GUTTER ON EDWARDS STREET. FOUND GARBAGE ALONG SIDEWALK (SOILED DIAPERS, MCDONALD'S BAGS, PAPERS). CRYSLIZED SUBSTANCE IN GUTTER (INCONCLUSIVE ON CHLORINE TEST) TRACES OF OIL IN GUTTER & STREET.
MARIE'S QUALITY FOODS 1244 Beamer St (East)	HM Woodland	142 Petroleum Hydrocarbons	Closed File H 141 - An investigation to a 1991 complaint revealed hydrocarbon contamination is soils beneath a graveled parking lot. All contaminated soils were removed & impermeable cap put down to stop further problems. Case closed Feb 1992. File archived as 00239HWG January 2004.
MARTHA BUTTON 44205 Greenview Dr, El Macero	HM Davis	385 Chlorodane	Closed SOIL REMOVED, FICUS TREE CUT DOWN. CASE CLOSED. MAY 1999 MARTH BUTTON SPILLED CHLORDANE IN THE TRUNK OF HER AUTOMOBILE. AUTOMOBILE BEING DECONTAMINATED WITH TSP (FILE CLOSED).

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
MATEO ANGULO GALVAN RESIDENCE 53 Yolano St	HM Woodland	272 Waste Oil	Closed WASTE ENGINE OIL WAS DUMPED ON ASPHALT AND THE GROUND. CLEANED UP BY YOLO HOUSING AUTHORITY.
MAYER EQUIPMENT 4235 WEST CAPITOL AVE	HM WEST SACRA	485 HYDROLIC OIL SPILL	OPEN FACILITY HAD 30 GALLON HYDROLIC OIL SPILL. FACILITY CLEANED UP SPILL AND REMOVED CONTAMINATED SOIL.
MAYFIELD 3130 Duluth St	UST W. Sac.	365 Gasoline & Diesel	Open FILE A: 1997/1998 DATA. GASOLINE & DIESEL SOIL IMPACT FOUND DURING MARCH 1997 TANK REMOVAL. INVESTIGATION REQUESTED.
McAravy, Patrick	*-++ Dunnigan	457 Iodine, Red Phosphorous, Sodi	Open Iodine, Red Phosphorous, Sodium Hydroxide. Drug lab waste, containers of materials at the site were identified and removed by YCHD and DTSC.
MCCARTHY/MOONEY RESIDENCE 1631 La Habra Ct	HM Davis	200 Asbestos	Closed RESIDENT CONCERNED ABOUT ASBESTOS CONTENT OF SERPENTINE ROCK USED IN LANDSCAPING.
MCCLEARY FACILITY 2205 Rice Ave	HM W. Sac.	115 Solvents	Closed SOILS FOUND CONTAMINATED AT THREE LOCATIONS DURING PRE-SALE SITE ASSESSMENT. SITES MAY HAVE BEEN THE LOCATION OF UST. ALL SOILS EXCEEDING 100 PPM TPH EXCAVATED, TREATED, & DISPOSED. FILE CLOSED.
MCI TELECOMMUNICATIONS 2802 KOVR Dr	HM W. Sac.	287 Hydraulic Oil	Closed CASE CLOSED BY COUNTY WITH CVRWQCB CONCURRENCE.
MCKESSON DRUG 3775 Seaport Blvd	UST W. Sac.	242 Diesel	Closed NO CONTAMINATION FOUND. SITE CLOSED APR 6, 1993. Please see scanned file number 242UTH for all documents related to this file.
MCLAUGHLIN MINE NW Corner Of County	HM Rumsey	207 Mine Wastes	Closed WASTE DISCHARGE PERMITS, CLOSURE AND OTHER INFORMATION FOR OPEN PIT GOLD MINE OPERATION LOCATED IN NAPA COUNTY. MONITORING FOR ARSENIC, CYANIDE, & MERCURY. RWQCB IS LEAD AGENCY. MINE DISCHARGES INTO STREAMS INCLCUDING CACHE CREEK THAT FLOW THROUGH YOLO COUNTY. MINE OPERATIONS CEASED IN 2001. FILE SUBMITTED FOR SCANNING IN NOVEMBER 2005 AS FACILITY NUMBER 6578. ALL DOCUMENTS MOVED TO ELECTRONIC FILES.
MEDLOCK FIELD, GROWERS AIR CR 27 W Of CR 102	HM Woodland	121 AG Chemicals	Closed File H 121 - RWQCB ordered halt to discharge of aircraft exterior wash waters to subsurface leach line, stake out system & provide the board with plans for disposal system by may 17, 1991. File archived as 02314 in January 2004.
MELCO INC 1038 Beamer St	HM Woodland	105 Floor Polish/Stripper	Closed MELCO EMPLOYEES WERE DISPOSING OF FLOOR CLEANING CHEMICALS TO CITY SEWER. CASE REFERRED TO DISTRICT ATTORNEY'S OFFICE & CITY OF WOODLAND. SITE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
MERCHANTS TRUCKING 1745 Cebrian St	UST W. Sac.	289 Hydrocarbon	Closed In 1995 five USTs and contaminated soil and ground water were removed from the site. Soil sampling shows that hydrocarbons do not affect soil beyond the former UST cavity. Ground water sampling shows that MTBE and TPMmo (Hydraulic oil) are present in ground water near the center of the southern property boundary, but data indicates this plume is stable, and mass of dissolved MTBE to be less than 0.01 gallons. The primary and secondary sources of hydrocarbons have been removed, and gasoline hydrocarbons detected in ground water beneath the site poses no significant threat to ground water quality. All monitoring wells on this site have been removed. This site was closed by the RWQCB January 6, 2000. File has been scanned - See Adobe Acrobat File 288UTH.
MERRITT RANCH CR 27	HM Woodland	469 Diesel/Motor Oil	Closed FARM FUEL TANK REMOVED APRIL 2003-NO CONTAMINATION FOUND. TANK PIT SHOWED VISUAL SIGNS OF CONTAMINATION. SITE WAS OVEREXCAVATED AND SAMPLED. LOW LEVELS FOUND. ISSUED A NO FURTHER ACTION LETTER
METRO AUTO DISMANTLING 19389 CR 102	HM Woodland	367 Waste Engine Oil Auto Fluids	Closed WASTE ENGINE OIL IMPROPERLY HANDLED. ANTIFREEZE DISCARDED AND IMPROPER DISPOSAL OF TIRES.
METRO AUTO DISMANTLING 19389 CR 102	He WOODLAND	495 GASOLINE, DIESEL, LEAD, MTBE	OPEN
MILLER, GILDA (PROPERTY) 605 Cottonwood St	HM Woodland	221 Diesel, Industrial Solvents	Closed ILLEGAL DISPOSAL/EMERGENCY RESPONSE TO DIESEL SPILL. SOIL CONTAMINATED. CLEAN-UP IN PROGRESS. REFERRED TO DISTRICT ATTORNEY. FILE CLOSED.
MILNE TRUCKING CO 830 E St	UST W. Sac.	245 Gasoline, Diesel	Open FILE A: TANKS FAILED TEST AFTER 1986 INSTALLATION. REMOVED MARCH 1987, REPLACED. SOIL VAPOR & SOIL BORING FOUND SLIGHT CONTAMINATION. WATER BEING MONITORED PENDING REVIEW BY RWQCB. REMEDIATION PLAN APPROVED BY RWQCB JAN 24, 1990. NOT IMPLEMENTED YET. FILE B: 1988 to 1995 DATA. FILE C: 1995 to 2000 DATA. Case assumed by the CVRWQCB
MINOR ROAD SPILLS W Sac	HM W. Sac.	41 e Diesel	Closed MINOR ROAD SPILLS REPORTED CLEANED UP BY YC PUBLIC WORKS MAY 15, 1987 AT 806 BRYTE AVE & MAY 17, 1987 AT W CAPITOL & JEFFERSON BLVD. See FA 9860
MOBIL CHEMICAL COMPANY 1351 Beamer St (East)	HM Woodland	162 Naptha, Isopropanol	Closed Naphtha & Isopropanol discovered through soil investigation. Proposal for further site assessment approved. Determined to be from underground storage tanks. File combined with L 246. SEE FILE L 246.
MOBIL CHEMICAL COMPANY 1351 Beamer St (East)	UST Woodland	246 B Thinner	Closed File B: 1993/1994 - SOIL & GROUNDWATER INVESTIGATION FOUND THINNER IN GROUNDWATER. A SMALL CONCENTRATION OF BENZENE WAS NOTED. INVESTIGATION CONTINUING.
MOBIL CHEMICAL COMPANY 1351 Beamer St (East)	UST Woodland	246 A Isopropanol, Solvent, Thinner	Closed INITIAL SITE ASSESSMENT.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
MOBILE CHEMICAL COMPANY 1351 Beamer St (East)	UST Woodland	246 E Isopropanol, Solvent, Thinner	Open Quarterly groundwater monitoring continues.
MOBILE CHEMICAL COMPANY 1351 Beamer St (East)	UST Woodland	246 D Isopropanol, Solvent, Thinner	Closed FILE D: 1995-96 QUARTERLY REPORTS.
MOBILE CHEMICAL COMPANY 1351 Beamer St (East)	UST Woodland	246 C Isopropanol, Solvent, Thinner	Closed FILE C: GROUNDWATER INVESTIGATION & SPARGING REPORTS.
MOBILE HYDRAULIC 724 Harbor Blvd	UST W. Sac.	604 Gasoline	Closed SOIL SAMPLES TAKEN DURING TANK REMOVAL REVEALED GASOLINE CONTAMINATION. FURTHER ASSESSMENT BEING REQUIRED BY THE COUNTY. CASE CLOSED. WELLS PROPERLY ABANDONED. File archived to 604UTH in December 2003.
MOBILE OIL 950 Sacramento Ave	HM W. Sac.	94 Gasoline	Closed USTS WERE REMOVED & PRELIMINARY SITE INVESTIGATION WAS DONE OCT 12, 1990. RESULTS SHOWED SITE TO BE CLEAN.
MOLLER CORP 1222 Research Park Dr	HM Davis	75 e 1,1,1-Trichlorethane	Closed File 75: An investigation conducted in 1987 indicated that 1,1,1 trichloroethane (TCA) and other solvents were disposed to the storm sewer system. TCA and halogenated volatiles were found in the water supply of an adjacent mobile home park. Investigation in 1989 including two monitoring wells, found no solvents in either soil or groundwater. File closed in 1998. File archived in December 2003 as 3473HWG.
MONTGOMERY WARDS 3689 Industrial Ave	UST W. Sac.	251 Gasoline	Closed LEAK DISCOVERED NOV 1986, TANK REPLACED AND SOIL REMEDIATION COMPLETED MARCH 1987. FILE CLOSED.
MOORE PROPERTY 9975-79 Main Street	HM ZAMORA	316 Diesel	Open DIESEL CONTAMINATION UNDER ABOVE GROUND STORAGE TANKS.
MORTGAGE COMPANY OF CALIFORNIA 37371 CR 144	HM Clarksburg	351 Diesel, Motor Oil, Gasoline	Closed RESIDENTIAL HOME HEATING OIL TANK REMOVED ON RURAL PROPERTY. HOME HEATING OIL TANK IS IN PROXIMITY TO DOMESTIC WELL. CONTAMINATION FOUND. RBCA FOUND NO THREAT DUE TO MINOR CONTAMINATION. CASE CLOSED.
Munich Court Galvanizing CR 32A	HM Davis	24 Qe Metals	Open FILE Q 1993 TO PRESENT: Court Galvanizing, now owned by MACE, LLC, continues to violate its Monitoring and Reporting Order. One well is being used for groundwater extraction and a second extraction well is to be installed. Monitoring, reporting, and soil flushing continues to fail to meet the Order. Recent sampling indicates increases in sulfate & nitrate concentrations. Monitoring & Reporting Program No. 5-01872X proposed May 20, 2001 would reduce the number of wells for which monitoring is required. See FA 118
Munich Court Galvanizing CR 32A	HM Davis	24 Pe Metals	Closed FILE P 1992 DATA: REMEDIATION PROGRAM CONSITING OF INSITU LEACHING OF SOILS, GROUNDWATER EXTRACTION FROM THE B AQUIFER. A ZONE WATER TO BE RECYCLED IN PRODUCTION PROCESS. B ZONE WATER TO BE TRETED & DISCHARGED TO SANITARY SEWER. See FA 118

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Munich Court Galvanizing CR 32A	Davis	HM 24 Ne Metals	Closed	FILE N 1991 DATA: PILOT SOIL LEACHING PROGRAM INDICATES THIS MAY A SUCCESSFUL SOIL REMEDIAL ALTERNATIVE. DROUGHT CONDITIONS HAMPER GROUNDWATER EXTRACTION & PILOT STUDY. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Me Metals	Closed	FILE M FURTELL & MASK INVESTIGATION: RESIDENTS OF ADJACENT RANCHO YOLO MOBILE HOME PARK BECAME ALARMED THAT DISCHARGES FROM CG WAS IMPACTING THEIR HEALTH. INVESTIGATION FAILED TO CONFIRM ALLEGATIONS. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Le Metals	Closed	FILE L 1990 DATA: INVESTIGATION OF REMEDIAL ALTERNATIVES IN PROGRESS. DTSC ISSUED AN IMMINENT OR SUBSTANTIAL ENDANGERMENT ORDER MAY 4. THE RWQCB ISSUED WASTE DISCHARGE REQUIREMENTS IN OCT. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Ke Metals	Closed	FILE K 1989 DATA: CONTAMINATION IS DEFINED IN THE A & B ZONES. 25 GROUNDWATER MONITORING WELLS ARE MONITORED QUARTERLY. RECOVERY OF GROUNDWATER FROM A AQUIFER BEGINS IN MARCH. EXTRACTED WATER RECYCLEDTHROUGH PROCESS. PONDS HAVE BEEN CLEANED UP. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Je Metals	Closed	FILE J 1988 JULY TO DEC DATA: GROUNDWATER MONITORING BEGINS DEFINITION OF PLUME CONTAINING SULFATE, ZINC, NICKEL, & CHROMIUM IN "A" ZONE. LOW PH, SULFATE, ZINC, NICKEL, CHROMIUM & NITRATES FOUND IN "B" ZONE. SOIL FEASIBILITY STUDY SUBMITTED. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 He Metals	Closed	FILE H 1988 JAN TO JUNE DATA: INVESTIGATION OF GROUNDWATER (QUARTERLY MONITORING INITIATED) & SOIL CONDITIONS CONTINUES. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Fe Metals	Closed	FILE F 1986 DATA: CG SUBMITTED REVISED INVESTIGATION WORKPLAN. DTSC CONDUCTED GENERATOR INSPECTION. COUNTY & CG WORKED OUT PERMIT FOR UST REMOVED W/O PERMIT IN 1985. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Ee Metals	Closed	FILE E 1985 DATA: INSPECTION OF DISCHARGE BY COUNTY RESULTED IN FOLLOW-UP INSPECTION BY RWQCB & ISSUANCE OF ORDER TO INVESTIGATE UNLINED PONDS, DISCHARGES, & NEW WASTE HANDLING PLAN. ALSO CONTAINS UST DATA. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 De Metals	Closed	FILE D 1980 TO 1984 DATA: 1983 VOA WASTEWATER ANALYSIS. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Ce Metals	Closed	FILE C: RESERVED FOR FUTURE USE (SEVERAL HISTORICAL DOCUMENTS EXPECTED). See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Be Metals	Closed	FILE B: RESERVED FOR FUTURE USE (SEVERAL HISTORICAL DOCUMENTS EXPENCTED). See FA 118

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Munich Court Galvanizing CR 32A	Davis	HM 24 Ge Metals	Closed	FILE G 1987 DATA: INITIAL INVESTIGATION FINDS METALS PRESENT IN SOIL & GROUNDWATER. DTSC ISSUED REMEDIAL ACTION ORDER. See FA 118
Munich Court Galvanizing CR 32A	Davis	HM 24 Ae Metals	Closed	FILE A PRE-1980 DATA:1975 WASTE DISCHARGE & MONITORING REQUIREMENTS. See FA 118
MURRAY, JAMES 16475 Cleveland	GUINDA	HM 347 Waste Engine, Batteries, Scrap	Open	COMPLAINT BY NEIGHBOR OF BURYING GARBAGE & JUNK IN TWO MOUNDS. WASTE ENGINE OIL & DIESEL SPILLED ON GROUND.
NACHTMANN LAB 720 Olive Dr	Davis	HM 147 Dumping of Waste	Closed	INVESTIGATION ON ARP 17, 1991 BY YCEH REVEALED LIQUID WASTE DUMPED INTO DUMPSTER & HAZARDOUS WASTE BEING INCINERATED. FILE SEALED & REFERRED TO DISTRICT ATTORNEY'S OFFICE.
Nakel & Orak Property 1580 Case Place	Woodland	HM 414 Investigation - No Release	Closed	Limited investigation at purchase of existing warehouse of oil/water separator. No hydrocarbons found at 10 feet below ground surface.
NEILSON NURSERY 617 West St	Woodland	UST 263 Gasoline	Closed	LEAK DISCOVERED DURING JULY 1987 TANK REMOVAL, SOILREMEDICATION COMPLETED JULY 1987. FILE CLOSED.
NELLA BRAND X STATION SIX 400 Main St	Woodland	UST 259 Gasoline	Closed	SOIL CONTAMINATION DISCOVERED DURING REMOVAL OF THREE TANKS 12,000 GALS ALL 20 PLUS YRS OLD. SOVER EXCAVATION REMOVED CONTAMINATED SOILS TO 15 PARTS PPM OR LESS. EXCAVATED SOILS AERATED & DISPOSED. FILE CLOSED. File scanned, see Adobe file 259UTH for documents.
NEO CORP/MINNESOTA METHANE Yolo County Landfill CR 104 & 28H	Woodland	HM 356 Motor Oil/Molybdenum	Closed	SOIL STAINING FOUND AROUND GAS SITE.CONSULTANT HIRED TO OVERSEE CLEANUP.
NEWHALL DEHYDRATOR Willow Point & S River Rd	Clarksburg	UST 260 Gasoline	Closed	LEAK DISCOVERED DURING OCT 1986 TANK REMOVAL, SOIL REMEDIATION COMPLETED DEC 1986. FILE CLOSED.
NEWPORT ESTATES N Side Linden Rd E Of Jefferson	W. Sac.	HM 396 Arsenic	Closed	ARSENIC LEVELS ELEVATED IN SOIL. HUMAN HEALTH RISK ASSESSMENT DONE. CASE CLOSED.
NICHOL'S REST STOP 7624 HWY 16	GUINDA	UST 262 Gasoline	Closed	SOIL BENEATH WEST END OF FORMER UST #1 HAD BEEN IMPACTED BY GASOLINEALL CONTAMINATED SOIL REMOVED. SITE CLOSED. This file has been scanned. See electronic file 262UTH for the documents.

Facility	File/Number	Status	Comments	
NOBEL RANCH CR 31 W Of CR 95	HM Davis	87 Gasoline	Closed	SOIL CONTAMINATION DURING 1989 TANK REMOVAL. SOIL EXCAVATED. NO GROUNDWATER IMPACTED. FILE CLOSED.
NOR-CAL BEVERAGE CO 2286 Stone Blvd	UST W. Sac.	265 B Gasoline & Diesel	Open	FILE B: SOILS FOUND TO BE IMPACTED WITH GASOLINE & DIESEL DURING NOV 97 TANK REMOVAL.
NOR-CAL BEVERAGE CO 2286 Stone Blvd	UST W. Sac.	265 A Waste Oil	Closed	FILE A: CONTAMINATION DISCOVERED DURING 1989 REMOVAL OF TWO USTS. SOILS EXCAVATED, NO GROUNDWATER IMPACT OBSERVED. SOILS REMEDIATED ONSITE, APPROVAL ISSUED FOR USE AS BUILDING OR ROAD BASE ONSITE. FILE CLOSED OCT 1990.
NORCAL PETROLEUM 801 East St	UST Woodland	268 A Gas, Oil, Diesel	Closed	Tanks: See H 334 - all data has been consolidated into this file. Two 20,000 gal unleaded gasoline, one 20,000 gal Diesel and one 15,000 gallon oil. RWQCB is the lead agency. Site Contamination Work Plan for 3 MW's approved June 2000.
NORCAL PETROLEUM 801 East St	HM Woodland	334 Diesel & Gasoline	Open	UNDERGROUND PIPING & DISPENSER REMVAL REVEALED GAS & DIESEL CONTAMINATION WORKPLAN SUBMITTED FOR FUTURE WORK. RWQCB is lead agency. File B contains 1999 data, File C contains 2000 data and File D contains 2001 data.
NORTH AMERICAN FOODS 3969 Industrial Blvd	UST W. Sac.	480 Diesel	Closed	GROUND WATER CONTAMINATION FOUND DURING 5/23/95 TANK REMOVAL. OVER-EXCAVATION & ADDITIONAL WATER & SOIL SAMPLES WERE NON-DETECTABLE FOR HYDROCARBONS. SITE CLOSED. File archived to 480UTH in November 2003.
NORTH KENTUCKY PARTNERS 39492-3 KENTUCKY AVE	UST WOODLAND	2023 VOC'S, DIESEL	OPEN	NOV 26, 2002, WASTE OIL TANK FOUND AND REMOVED VERY LOW LEVELS OF OIL WAS FOUND. TANK PIT SAMPLES WERE TAKEN, ELEVATED LEVELS OF DIESEL, OIL AND GREASE AND VOC'S WERE FOUND. FEBRUARY 11, 2003, FURTHER SAMPLING SHOWED LOWER LEVELS OF DIESEL. MARCH 12, 2004, WORK PLAN AND BORING PERMIT APPROVED TO ANALYZE GROUND WATER AND DETERMINE IF EXISTING PIPING IS PRESENT.
NORTH KENTUCKY PARTNERS 39492-3 KENTUCKY AVE	UST WOODLAND	2023 DIESEL, OIL AND GREASE, UOC	OPEN	11/25/02- 1 TANK FOUND NW CORNER OF SMOG SHOP FULL OF WASTE PRODUCT. SAMPLES TAKEN. NO FURTHER ACTION ISSUED FOR THIS TANK LOCATION. NO TANK FOUND DIRECTLY NORTH OF CROCODELI. PIPING FOUND, BUT NOT TANK ON SOUTH SIDE OF SMOG SHOP. OBVIOUS SIGNS OF CONTAMINATION WERE CONFIRMED BY SOIL SAMPLES. SOILS WERE OVER EXCAVATED AND RESAMPLED. YCEH ADDITIONALLY REQUIRED GROUND WATER GRAB SAMPLE.
NORTH KENTUCKY PARTNERS 39492-3 KENTUCKY AVE	UST WOODLAND	2023 TPHD	OPEN	ONE UST, FULL OF WAST OIL WAS REMOVED ON 11/25/02. FORMER TANK PIT FOUND ALONG WITH PIPING. CONTAMINATION FOUND. CONTAMINATED SOIL REMOVED. GROUND WATER SLIGHTLY IMPACTED.
NORTH PARK NE Corner Kentucky & Ashley	HM Woodland	220 Petroleum	Closed	PETROLEUM CONTAMINATED SOIL FOUND BENEATH CURRENT ROAD BED. SOIL STOCKPILED ON NE CORNER OF KENTUCKY AND ASHLEY.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
NOSS BROTHERS 52210 Willow Point Rd	HM Clarksburg	152 Diesel	Closed
			REMEDATION REPORT. INCORPORATED INTO FILE L-271A.
NOSS BROTHERS/FOOD EXPRESS 52210 Willow Point Rd	UST Clarksburg	271 Diesel	Closed
			MINOR SOIL & GW CONTAMINATION FOUND AFTER UST FAILED TESTS. SOILS EXCAVATED, FILE CLOSED AFTER GW ASSESSMENT. DIESEL CONTAMINATION FOUND LATER BY WASH AREA. CONTAMINATION EXCAVATED TO 6 FT. SOIL SAMPLES OBTAINED SHOWED CONTAMINATION REMOVED ACCEPTABLE LEVEL. GROUNDWATER CONTAMINATION FOUND IN EXCAVATION AFTER UST WAS REMOVED. WORKPLAN TO ASSESS CONTAMINATION SUBMITTED JUNE 1994. SITE CLOSED FEBRUARY 1996. File scanned, see electronic file 271UTH for documents.
NW WOODLAND AIR COMPLAINT Kentucky & Cottonwood	HM Woodland	255 Air Quality	Closed
			OWNER OF DEAD DOG EXPERIENCED BURNING IN LUNGS. AREA BETWEEN BEAMER & KENTUCKY & COTTONWOOD & WEST STREETS. REFERRED TO COUNTY AG DEPT FOR INVESTIGATION. CASE CLOSED.
OAKLAND BEAN COMPANY CR 116 & Railroad	UST Knights Landin	273 Gasoline	Closed
			TANK FAILED TESTING IN JAN 1986, REMOVED MAY 1987, SOIL REMEDIATION COMPLETED JUNE 1987. FILE CLOSED.
O'DELL RANCH 26407 Buckeye Rd	UST Winters	614 Diesel	Open
			DURING REMOVAL TWO DIESEL TANKS HAD HOLES. SOIL SAMPLES REVEALED CONTAMINATION. SITE INVESTIGATION ORDERED.
OKINO & CRAIG 40250 CR 27	HM Woodland	290 Phostoxin	Closed
OLD PENROSE RANCH 27170 HWY 16	HM Esparto	285 Motor Oil	Closed
			8-11-94 - PROPERTY OWNER REPORTS THAT TENANT IS DUMPING WASTE MOTOR OIL ON PROPERTY. CONFIRMED AND SERVICE ACTIVITY REPORT ISSUED.
OLIN JONES SAND CO Port of Sacramento	HM W. Sac.	303 Sand Reclamation	Closed
			WDR FOR DISHCARGE TO DEEP WATER CHANNEL.
OLSEN, AILEEN(LABOR CAMP WELL) CR 106A & CR 34A	HM Davis	43 Alachlor, EDB	Closed
			File H 43 - Alachlor and EDB found in drinking water well in 1987. Water system will provide alternative water supply to residents. Case referred to drinking water program. File closed. File closed. File archived to 00043HWG in December 2003.
ONE-HOUR MARTINIZING 837 JEFFERSON BLVD	HM WEST SAC	465 UNDETERMINED	OPEN
			PCE INVESTIGATION. SEE ALSO FILES H440, H463 AND H464
P I E NATIONWIDE/POZAS 520 Houston St	UST W. Sac.	300 Diesel	Closed
			SOIL CONTAMINATION EXCAVATED IN 1990. EAST SAMPLE CONTAINING 490 PPM DIESEL LEFT. 3 WELLS INSTALLED. ALL GROUNDWATER RESULTS ARE NONDETECT. FILE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
PAC INTR RICE (DETTING FAC) HWY 113 & CR 13	USTL 6 Knights Landin Gasoline	Closed	TANK WITH HOLES REMOVED 1986. SOIL & GW CONTAMINATION CONFIRMED 1987. PRELIMINARY INVEST. CONDUCTED 1987. GW INVEST CONDUCTED 1988-1991. GW CHARACTERIZATION COMPLETED 1992. QUARTERLY MONITORING & REPORTING INITIATED 1993. NO OFF SITE MIGRATION. MODELING SHOWS THAT CONTAMINANTS REMAINING ON SITE WILL NOT BE A RISK TO FURTHER CONTAMINATION. CASE CLOSED DEC 1998. File archived to 4450UTH December 2003..
PACE TRUCKING CR 99W & CR 97	HM 145 Yolo Diesel	Closed	TRAFFIC COLLISION RESULTED IN DIESEL BEING SPILLED ONTO ROAD & INTO DITCH. SOIL EXCAVATED TO DEPTH OF 7 FT. SOIL STOCKPILED & COVERED WITH PLASTIC. CLOSED. SEE FILE H92168.
PACIFIC BELL 1777 Cebrian St	UST 276 W. Sac. Hydrocarbons, Hydraulic Oil	Closed	SOILS OVER EXCAVATED & GW PUMPED TO LESS THAN MCL'S FOLLOWING 1996 TANK REMOVAL. CASE CLOSED.
PACIFIC BELL 1777 CEBRIAN ST	UST 276 WEST SAC DIESEL, GASOLINE, BTEX, HO	Closed	THE FILE IS ALREADY EXISTING, EXCEPT IT IS CLOSED. PLEASE OPEN IT FOR THE NEW CASE THERE. CLOSURE LETTER ISSUED BY CRWQCB 7/30/07. SEE SIRE FA 276 UST CABINET LUST CORRESPONDENCE 7/30/07. CASE CLOSED.
PACIFIC BELL 1777 CEBRIAN ST	UST 276 WEST SACRA DIESEL, GASOLINE, BTEX, HO	Closed	CLOSURE LETTER ISSUED BY CRWQCB 7/30/07. SEE SIRE FA 276 UST CABINET LUST CORRESPONDENCE 7/30/07. CASE CLOSED.
Pacific Coast Producers Main Street (East)	HM 411 Woodland Process Water	Closed	Formerly Del Monte (Contidina) Cannery. August 1999Facility discharged 2,000 gallons of process wastewater due to leak form outfall pipe into storm drain. Groundwater monitoring, vadose zone monitoring, ranch cropping plan information for 203
Pacific Grain Products Merritt Station	HM 309 Woodland TOC Investigation	Closed	Letter from RWQCB approving a workplan. This is probably part of another file, but we are unable to associate the site with any existing files.
PACIFIC LUMBER & PALLET 225 Industrial Way	HM 305 Woodland Solvents, Paint, Exposy Activ	Closed	ABANDONED HAZARDOUS WASTE LEFT BY FORMER TENENT (FILE SEALED PENDING DA INVESTIGATION).
PACIFIC RICE MILL 845 Kentucky Ave	UST 468 Woodland Gasoline	Closed	TANK LEAK DISCOVERED IN SEPT 1985, SOIL REMEDIATION COMPLETED IN NOV 1985. FILE CLOSED. File archived as 468UTH in November 2003.
PACIFIC UTILITES 3120 Coke St	HM 216 W. Sac. Petroleum WasteE	Closed	INVESTIGATION OF ALLEGATION THAT FACILITY DISPOSES CONTAMINATED ABSORBANT MATERIAL TO DUMPSTER. CASE DROPPED FOR LACK OF EVIDENCE. CASE CLOSED.

Facility	File/Number	Status	Comments	
Paul's Service (Bechtold) Former Station 16811 Yolo Ave	UST Esparto	283 Petroleum	Open	Soil contamination observed during May 2000 tank removal. Preliminary Evaluation and Investigation Report dated March 8, 2002 indicates that soils beneath the former gasoline & diesel UST cluster are impacted with residual gasoline and diesel hydrocarbons at concentrations up to 3,700 and 1,100 mg/kg respectively. The lateral extent of hydrocarbon impact is unknown. Increased soil density below 40 feet appears to act as an aquitard limiting groundwater transmission vertically. Groundwater also appears to be impacted. BTEX and MTBE was also detected in the groundwater samples. CVRWQCB took lead agency status Feb 2003, contact is David Stavarek at (916) 255-3073.
PAULY HUDSON'S PROPERTY 40478 SOUTH RIVER ROAD	H CLARKSBURG	483 ABANDONED CHEMICALS	CLOSED	PHASE I SITE ASSESSMENT
PAYNE RANCH CR 17 & CR 103	HM Woodland	44 Diesel	Closed	VANDELS SHOT HOLE IN ABOVEGROUND TANK RELEASING 14,637 GALS DIESEL. SOILS EXCAVATED-BIOREMEDIATION ATTEMPTS IN 1990 FAILED. PROPERTY SOLD TO SPRECKLES. SOILS ENCAPSULATED FOR LATER TREATMENT UPON SITE DEVELOPMENT. In 1995 approximately 500 cubic yards of soil was blended with approximately 890 cubicyards of limestone spall fill,and compacted and covered with reinforced concrete used in the construction of a loading dock. File closed in November 1995. File archived to 357HWG (Spreckles file) in December 2003.
PAYNE, NEVA 173 Main St	UST Woodland	598 Diesel	Closed	CONTAMINATION FOUND DURING TANK REMOVAL EXCAVATED & REMOVED TO DEPTH OF 16 FT. SOIL TRANSPORTED AS SPECIAL WASTE. CLOSURE LETTER WRITTEN. FILE CLOSED. File archived to 598UTH in December 2003.
PEART/CHEVRON WEST CLUSTER 613 East St	USTL Woodland	12 e Diesel, Gasoline	Closed	This site is the western group, one of three former leaky tank groups under this owner. Chevron operated a service station on the property from 1943 to 1973. Four underground tanks were removed in 1973. Investigation and site assessment was conducted between July 1989 through January of 1993. The majority of soil contamination was excavated was removed. Most soil contamination remaining is located between 20 and 40 feet below ground surface. Mass balance calculations for contaminants remaining on the site (worst case estimates) indicated that a maximum of 21,000 pounds of TPHd and 900 pounds of TPHg remain in the soils beneath the site. The last sampling, October 1996 indicates that the highest levels present in groundwater were 150 ppb TPHg, 2,100 ppb THGd, 4.9 ppb benzene and 1.6 ppb xylene. MW 10 located 150 feet down gradient was non-detect for all constituents. The contamination plume appears to be limited to the property and has moved no more than 150 feet down gradient from the former tank site in 23 years. A no further action required letter was issued by the RWQCB March 31, 1997 and the case closed by Yolo County.
PEART/EAST CLUSTER East & Oak St, NE Corner	HM Woodland	86 A Diesel, Gasoline	Closed	FILE A - PRE 1994 - SOIL CONTAMINATION FOUND AT THIS FORMER UNDERGROUND TANK SITE. SOILS EXCAVATED FOR OFF SITE DISPOSAL. GROUNDWATER CONTAM PRESENT ON WESTERN PORTION OF PARCEL FROM OFFSITE SOURCE, SEEL12, L272.
PEART/EAST CLUSTER East & Oak St, NE Corner	HM Woodland	86 B Diesel, Gasoline	Closed	FILE B-199:4-1997 MAY INVESTIGATION FOUND NO FURTHER SOIL OR GROUNDWATER IMPACT FROM FORMER TANKS LOCATED IN THIS PARCEL. CLOSURE EXPECTED BUT INVEST & REMEDIATION IF ADJACENT PARCELS MAY IMPACT THIS PARCEL. CASE CLOSED JULY 1997.

Facility	File/Number	Status	Comments	
PEART/NUTRIDGE 1232 Alice St	UST Woodland	272 Gasoline	Open	LEAK DISCOVERED DURING JUNE 19987 TANK REMOVAL, SOIL REMEDIATION IN PROGRESS. ONE MORE ROUND OF SAMPLING HAS BEEN VERBALLY REQUESTED. THE SITE SHOULD BE CLOSED.
PELLINI/FORMER CITIZEN CHEV 317 Main St (West)	HM Woodland	384 Waste Oil	Closed	COMPLAINT ON ILLEGAL DISPOSAL. INSPECTION DONE. CANNOT VERIFY.
PENSKE TRUCK LEASING 3009 Evergreen Ave	UST W. Sac.	206 B Gasoline, Diesel	Open	FILE B - Investigation during 2002 finds that the general trend is decreasing levels of all constituents. The lateral extent of hydrocarbons has been defined but the vertical extent has not. 1,2-DCA and MtBE were found during the 3rd Quarter 2002 monitoring event. Further investigation required by the RWQCB in Dec 2002.
PENSKE TRUCK LEASING 3009 Evergreen Ave	UST W. Sac.	206 A Gasoline, Diesel	Closed	CONTAMINATION DISCOVERED DURING TANK PULL... Tank: 1,000 gallon 15/40 motor oil. Vertical definition of ground water and plume stability studies underway in July 2002
PETERSON CLINIC 8 Cottonwood St (North)	HM Woodland	192 Transformer Oil	Closed	Transformer containing oil was found in Peterson Clinic basement. Oil was disposed after analysis. Case closed, file archived as 00599HWG in February 2004.
PETO SEED 37437 HWY 16	HM Woodland	311 Washwater	Closed	FILE 311: WASTE DISCHARGE REQUIREMENTS FOR DISPOSAL TO POND FOR SEED WASHING WASTEWATER DISPOSAL ADOPTED MAY 1996. FILE CLOSED.
PETROLEUM TANK LINE 2600 Rice Ave	UST W. Sac.	290 Diesel, Waste Oil	Open	DURING 1985 TANK REMOVAL SOILS WERE OBSERVED CONTAMINATED WITH DIESEL & WASTE OIL. INVESTIGATION IN PROGRESS.
PG&E ANODE WELLS SEVERAL SITES	HM W. Sac.	381 Anode Well Installations	Open	PERMITS FOR INSTALLATION OF ANODE WELLS.
PG&E CONWAY RANCH DEHYDRATE 2001 CR 103	HM Woodland	339 P E A For Hydrocarbons	Closed	SOIL & GROUNDWATER PRELIMINARY ENVIRONMENTAL ASSESSMENTS OVERSIGHT BY RWQCB. Low levels of diesel found in groundwater but RWQCB determined that pollutions is of limited extent and is expected naturally attenuate. No further action will be issued upon destruction of monitoring well and piezometers.
PG&E HERSEY STATION Yolo	HM Yolo	30 Gas Condensate	Closed	File H 30 - Condensate from dehydrator discharged in 1986 to soil and removed by P G & E. File archived to 4457HWG in December 2003
PG&E HERSHEY DEHYDRATOR 1998 CR 89	HM Dunnigan	338 P E A For Hydrocarbons	Open	PRELIMINARY ENVIRONMENTAL ASSESSMENT FOR HYDROCARBONS. Groundwater contains diesel and gasoline including 170 PPB of benzene. In-situ bioremediation is proposed for groundwater cleanup.
PG&E PLEASANT CREEK CR 32	UST Winters	293 Waste Oil	Closed	SOIL CONTAMINATION FOUND DURING UST (55 GAL DRUM). SOILS EXCAVATED & DISPOSED AS HAZARDOUS WASTE. FILE CLOSED. File scanned, see Adobe file 293UTH for contents.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
PG&E PLEASANT CREEK DEHYDRATOR N OF CR 32A, W OF CR 88 Winters	HM 346	Closed	VERY LOW LEVELS OF HYDROCARBONS DETECTED IN SOIL AND GROUNDWATER (BELOW APPLICABLE WATER QUALITY CRITERIA). CASE CLOSED BY CVRWQCB.
PG&E PUTAH CREEK DEHYDRATOR W Side CR 106, S Of CR 36 W. Sac.	HM 345	Open	SITE ASSESSMENT UNDERWAY. Some diesel found in both soil and groundwater in preliminary samples. Verification is required by CVRWQCB in Mar 2003. RWQCB contact is Mary Serra at (916) 255-3082.
PG&E SILVERLIGHT DEHYDRATOR E Side Mace Blvd, S Of Rd A Davis	HM 343	Closed	SITE ASSESSMENT UNDERWAY.
PG&E TODHUNTER STATION CR 30 Davis	HM 160	Open	A 15,000 GAL PRODUCTION FLUID SPILL RESULTED IN EMERGENCY CLEAN-UP. FULL SITE INVESTIGATION WORK PLAN APPROVED JULY 1992. Soil and groundwater are contaminated with total petroleum hydrocarbons as gasoline and diesel. Shallow groundwater, about 16 feet below ground surface contains up to 8,500 ppb as diesel. A groundwater monitoring program was issued by the CVRWQCB in March 2003. RWQCB contact is Mary Serra (916) 255-3082.
PG&E WINCHESTER LAKE DEHYDRATR BURROWS AVE W. Sac.	UST 295 A	Closed	State Inspection dated 9/3/1999 documents that all aboveground tanks at this facility have been removed. I could not find this file as of 6/19/2002, JBS.
PG&E WINCHESTER LAKE DEHYDRATR 3521 Burrows Ave W. Sac.	HM 344	Closed	SOIL AND GROUNDWATER CONTAMINATION PRESENT, REGIONAL BOARD-LEAD AGENCY. NO BENZENE DETECTED. PG&E conducted soil excavation in August 2002. Monitoring of groundwater following investigation found no further evidence of hydrocarbons. Post remediation groundwater monitoring continues in one well. RWQCB contact is Mary Serra at (916) 255-3082.
PG&E Winters Field Master Meter Station 32003 Russel Blvd Winters	HM 348 e	Closed	Permit application for soil borings - investigation being conducted at site. No further Action letter issued by RWQCB March 2003. Case closed.
PG&E WOODLAND 124 Walnut St Woodland	HM 42 e	Closed	TRANSFORMER OIL CONTAINING 2 PERCENT PCB LEAKED. CLEANUP CONDUCTED BY P G & E CREW. See FA 3958 correspondence 8-14-86
PG&E, WOODLAND YARD 50 Kentucky Ave Woodland	UST 294	Closed	File scanned see 204 UTH. TANK FAILED TESTING IN FEB 1986, REPLACED AND SOIL REMEDIATION COMPLETED IN MARCH 1986. FILE CLOSED. File scanned, see Adobe File 294UTH for contents.
PG&E, WOODLAND YARD 50 Kentucky Ave Woodland	UST 294	Closed	TANK FAILED TESTING IN FEB 1986, REPLACED AND SOIL REMEDIATION COMPLETED IN MARCH 1986. FILE CLOSED. File scanned, see Adobe File 294UTH for contents.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
PHASE I & II ASSESSEMENT Ashley & Kentucky	HM Woodland	352 Waste Oil	Closed MOTOR OIL FOUND ON PARCEL DUE TO PHASE I ASSESSMENT. MOTOR OIL CONTAMINATED SOIL REMOVED. CASE CLOSED.
PHASE II-III SITE ASSESSMENT 1311 Bluegrass Way	HM Woodland	198 Diesel, Motor Oil	Closed DIESEL & MOTOR OIL DISCOVERED DURING PHASE I ASSESSMENT. SOIL EXCAVATED TO NON-DETECT & TRANSPORTED OFF-SITE. FILE CLOSED.
PILOT TRAVEL CENTER 30035 CR 8	DUNNIGAN	3627 e DIESEL	OPEN TWO ON SITE MONITORING WELLS HAD APPROXIMATELY 1 FOOT OF FREE PRODUCT (DIESEL) IN THEM. LEAK APPEARED TO COME FORM A METER GASKET LEAK FROM THE DISPENSER AT ISLAND #23.
PLUG N JUG 9425 LOCUST STREET	UST KNGHTS LAN	344 GASOLINE, DIESEL, BTEX	OPEN
PMP AUTO PARTS INC 333 CR 101 North	HM Woodland	259 Waste Oil	Open DURING A PHASE I AND II SITE ASSESSMENT, SHALLOW OIL CONTAMINATION FOUND. LETTER WRITTEN REQUIRING A WORKPLAN FOR CLEANUP.
PORT OF SACRAMENTO Port of Sacramento	HM W. Sac.	45 See H 412	Closed Several files consolidated into file H 412. File H 45 no longer exists, all information contained in this file was transferred to H 412.
PORT OF SACRAMENTO Port of Sacramento	HM W. Sac.	196 See H 412	Closed Several files consolidated into file H 412. File H 196 no longer exists, all information contained in this file was transferred to H 412.
PORT OF SACRAMENTO 2895 Industrial Blvd	UST W. Sac.	299 Diesel	Open DIESEL CONTMAINATION FOUND DURING TANK REMOVAL.
PORT OF SACRAMENTO Port of Sacramento	HM W. Sac.	312 See H 412	Closed Several files consolidated into file H 412. File H 312 no longer exists, all information contained in this file was transferred to H 412.
PORT OF SACRAMENTO Port of Sacramento	HM W. Sac.	319 See H 412	Closed Several files consolidated into file H 412. File H 319 no longer exists, all information contained in this file was transferred to H 412.
Port of Sacramento Port of Sacramento	HM W. Sac.	412 A Hydrocarbons, Fertilizers, Oth	Closed H 412A - 1986 - 1995 Data. Includes 1985 EIR and info on channel dredging project, 1993 NOV for storm water discharges, 1994 request for WDR, 1995 investigation of soil conditions on two lots, nitrogen found.
Port of Sacramento Port of Sacramento	HM W. Sac.	412 B Hydrocarbons and Others	Closed H 412B - 1996 - 1997 Data: Soil investigation continued, groundwater investigation and monitoring initiated, storm water Cease & Desist and NPDES permits issued in 1996, Nov for storm water monitoring violations issued, several investigation and monitoring reports.

Facility	File/Number	Status	Comments	
PORT OF SACRAMENTO Port of Sacramento	HM W. Sac.	412 C Nitrates, Metals, Others	Open	H 412 C- 1998 - 2002: NOV issued Oct 98 for failure to monitor & implement approved work plans. Soil & GW investigations continue. Site operation improvements continue. Wetland constructed for treating storm water and groundwater in 2001. Additional wells and other projects proposed for 2003. A work plan for installation of groundwater extraction pilot study wells approved in March 2003. RWQCB contact is Devra Lewis (916) 255-3119.
PRECISION RADIATOR 3320 Jefferson Blvd	HM W. Sac.	206 Unknown	Closed	COMPLAINT INVESTIGATION OF ALLEGED ILLEGAL DISCHARGE TO SEPTIC SYSTEM. CASE REFERRED TO RWQCB. CASE CLOSED.
PRESTAR, INC. 24390 Aviation Ave	HM Davis	317 Domestic Wastewater	Closed	WASTE DISCHARGE TO OXIDATION POND.
PRYOR, TOY Route 1 Box 369	HM Dunnigan	123 Waste Oil & Diesel	Closed	ILLEGAL STORAGE OF WASTE OIL & DIESEL CONTAMINATED SOILS. SITE HAS BEEN CLEANED-UP. FILE CLOSED.
QUALITY DIESEL MACHINES 2434 Evergreen Ave	HM W. Sac.	46 e Non Hazardous	Closed	INVESTIGATION OF COMPLAINT FOUND LIQUID (WATER) USED FOR SUBMERSING CYLINDER BLOCKS WAS DISCHARGED TO STREET. INVISTIGATOR OFFERED SEVERAL OPERATIONAL CHANGES. See FA 9856
Quick Stop Market - W Capitol 1648 W Capitol Ave	UST W. Sac.	303 Gasolene	Open	L 303 FILE A PRE 2001 DATA-Three tanks removed in 1996. Low levels of hydrocarbons observed in soil and groundwater. CVRWQCB is lead agency. Investigation determined that shallow groundwater beneath the site has been impacted by petroleum hydrocarbons. MTBE was found in all three MW's with levels up to 35 ppb. Further investigation required by the RWQCB. FILE B 2001 DATA - Quarterly monitoring continues, the RWQCB requested a workplan in Sept 2002 for further assessment and preparation of a Problem Assessment Report.
R C COLLET 2290 Main St (East)	UST Woodland	305 B Gasoline, Diesel	Open	DURING B - 2000 Data. RWQCB is the lead agency. Quarterly Monitoring in progress Sensitive receptor study requested. MTBE detected at levels up to 2.5 ppb.
R C COLLET 2290 Main St (East)	UST Woodland	305 A Gasoline, Diesel	Closed	DURING A - 1994 - 1999 Data. TANK REMOVAL, CONTAMINATION WAS DETECTED. RWQCB is the lead agency. .
R G A (W SAC FACILITY) 901 South River Road	HM W. Sac.	50 Phostoxin	Closed	File H 50 - Complaint investigation of by Yolo Environmental Health and DHS/DTSC found evidence of buried phostoxin prepacs. However no significant levels of residue were identified in soils. Burial practice of spent prepacs has been discontinued. File closed. For other information on this site see files u 315, u 318, and hm 421. File archived as 3138HWG in December 2003
R M C LONESTAR South River Road	HM W. Sac.	178 Gasoline	Closed	RWQCB ORDERED INVESTIGATION OF HYDROCARBONS BENEATH THE FACILITY. SOURCE DETERMINED TO BE SHELL OIL COMPANY. SEE H59. CASE CLOSED.
RADIAL TIRE CENTER 3111 W Capitol Ave	HM W. Sac.	47 e Waste Oil	Closed	DISCHARGE OF WASTE OIL TO GROUND ORDERED STOPPED, CONTAMINATED SOIL WAS EXCAVATED AND DISPOSED. See FA 6031

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
RADIATORS TO GO 606 Harbor Blvd	HM W. Sac.	112 Waste Oil & Ethylene Glycol Closed	File H 112 - Complaint investigation in 1991 found waste oil and ethylene glycol soil contamination. Soils were excavated and treated offsite. Case closed in November 1992.
Railroad and Grant Signal Improvements 318 First Street	HM Winters	466 Phase II Assessment CLOSED	Phase II Assessment for road widening project.
RALEY'S LANDING Second & G St	HM W. Sac.	307 Pre Develop Investigation Closed	WELL PERMITS FOR PRE DEVELOPMENT ENVIRONMENTAL SITE INVESTIGATION. CASE CLOSED.
RALEYS LANDING (PARISH ARCO) 490 W Capitol Ave	UST W. Sac.	489 Hydrocarbons Closed	SOIL CONTAMINATION DISCOVERED DURING OCT 1989 REMOVAL OF FOUR TANKS. CAUSE MAY HAVE BEEN CORRODED PRODUCT PIPE SERVING UNLEADED TANK. ASSESSMENT IN PROGRESS. ASSESSMENT SHOWED NO FURTHER CONTAMINATION. SITE CLOSED JULY 2, 1991. File archived to 489UTH in November 2003.
RALEYS LANDING (TRAILWAYS) 500 E St	UST W. Sac.	474 A Hydrocarbons Closed	FILE 474. Soil contamination found during 1989 removal of 12,000 gal ust. Soil excavated & bio-treatment initiated. 1990-1992 assessment & remediation of excavated soils completed. No groundwater remediation required. File closed. File archived to 474UTH in November 2003.
RALEY'S LANDING HQ DEVELOPMENT) AND F	H WEST SACRA	490 e LEAD, PETROLEUM OPEN	PREDEVELOPMENT PHASE II DISCOVERS SOIL AND GROUNDWATER IMPACT. ADDITIONAL INVESTIGATION UNDERWAY.
RALEYS PRODUCE WAREHOUSE 1630 Terminal Way	UST W. Sac.	307 Gasoline Closed	Two diesel and one gasoline UST's were installed in 1979. Contamination first detected in 1989. The tanks were removed in July 1992 and further investigation found additional contamination beneath the tanks, piping and pump island. Four thousand cubic yards of contaminated soil was over-excavated. A portion of this soil was aerated and a portion of subjected to thermal treatment onsite. All soil was returned to the excavation upon treatment to cleanup levels. The site was monitored for four quarters following treatment with no detectable hydrocarbons observed. The CVRWQCB issued a No Further Action Letter in November 2000. This file has been scanned to L 307UTH.
RALEY'S STADIUM South River Road	HM W. Sac.	387 Pre Construction Investigation Open	PHASE I PRE CONSTRUCTION SITE INVESTIGATION.
RAMERO FACILITY 26443 Woodland Ave	HM Esparto	169 Waste Oil Closed	OPEN DRUM OF WASTE OIL OVERFLOWED ONTO GROUND SURFACE. SPILL PROBABLY CLEANED UP BUT ADEQUATE DOCUMENTATION NOT SUBMITTED. CASE CLOSED.
RAMOS ENVIRONMENTAL 1515 South River Road	HM W. Sac.	379 PCB Contaminated Oil Closed	ANONYMOUS REPORT OF ILLEGAL DISPOSAL OF PCB CONTAMINATED OIL. INVESTIGATED BY THIS DEPT. WASTE OIL CONTAINING PCB'S WAS INADVERTANTLY SHIPPED TO DEMENNO KERDOON AS WASTE OIL FOR RECYCLING. THIS WAS CAUGHT AT DK & CORRECTIONS MADE. CASE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
RAMOS OIL 01/1515 South River Road	HM W. Sac.	148 Diesel	Closed File H 148 - Soil remediation project completed for surface soil contamination. File also contains CalEPA & RWQCB inspections, enforcement actions & correspondence regarding facility operations through 1994. File archived as 308HWG in January 2004
RANCH HOUSE 26055 CR 89	HM Winters	327 Site Assessment	Closed SITE ASSESSMENT FOR PROPERTY TRANSFER. NO CONTAMINATION FOUND AT LEVELS OF CONCERN.
Redwood Oil/Gibson/Benito 1800 South River Road	UST W. Sac.	183 e Gasoline/Diesel	Open Minor gasoline and diesel contamination observed in soils during 1996 tank removal. Yolo County requested workplan for investigation and Sierra Environmental responded to conduct an investigation of nearby sites. RWQCB taking lead agency status May 2000. Additional investigation approved by RWQCB in Nov 2001. See Sire FA 183
RELIABLE DIESEL SERVICE 536A Houston St	HM W. Sac.	48 e Steam Cleaning Waste	Closed OWNER ORDERED TO CONTAIN AND PROPERLY DISPOSE STEAM CLEANING WASTE. See FA 9861
Rellis Oil 804 South River Road	UST W. Sac.	57 MTBE, Toluene and trihalometha	Open L 57 Phase II site assessment found up to 1.4 PPB MTBE, 2.2 PPB Toluene, 24 PPB Chloroform 5.0 Bromodlchloromethane, and about 100 PPB of several Trihalomethane compounds in water. Site is near investigation of TCE release (see H 63) which may be the source of part or all of the trace findings found in this report. Facility is also or formerly known as Brighton Commercial Fuel and Pacific Pride. Case was referred to the CVRWQCB 10/30/02. See also H 180.
Rellis Oil 804 South River Road	HM W. Sac.	180 Oil	Closed H 180 - Fifty-five gallon drum of oil abandoned was analyzed for PCB & disposed as non-chlorinated oil. See also L 57. Case Closed. File archived as 00057HWG in January 2004.
RENT-ALL CENTER 2020 F ST	UST Davis	132 Gasoline, Diesel	Closed File L 132 - Pipe leak discovered during tank removal. Soils excavated and disposed off site. Minor diesel contaminated soil left under building. File closed in 1992. File archived as 00132UTH in January 2004.
RGA MERRITT STATION CR 27 (5 Mi S Of Woodland)	UST Woodland	316 Petroleum Products	Closed SOIL CONTAMINATION OBSERVED DURING DEC 1989 UST REMOVAL. ALL SOILS THAT WERE CONTAMINATED WERE EXCAVATED. SEE REGULAR UST FILE FOR REPORT. FILE CLOSED.
RGA WOODLAND FACILITY 1620 Kentucky Ave (East)	UST Woodland	317 A Gas, Halogenated Volatile ORGAN	Closed FILE A PRE 1994: LEAKY GASOLINE TANK FOUND DURING 1988 REMOVAL. SOME SOILS EXCAVATED, PAR COMPLETED IN 1989, GW CONTAMINATION LIMITED TO WITHIN 30 FT OF TANK, CASE REFERRED TO RWQCB 1989. HVO'S FOUND IN 1994 SAMPLING.
RGA WOODLAND FACILITY 1620 Kentucky Ave (East)	UST Woodland	317 B Gasoline, Chlorinated Solvents	Open FILE B: 1994 - The CVRWQB is the lead agency. Further investigation directed in December 2002. Petroleum is still present in groundwater including gasoline, BTEX, 1,2,3-trimethylbenzene and naphthalene.

Facility	File/Number	Status	Comments	
RICHARDSON RANCH-WALLACE PROPE CR 116	He KNIGHTS LAN	496 DIESEL FUEL	CLOSED	AFTER REVIEWING THE REPORTS/GROUND WATER MONITORING DATA, WHICH WERE SUBMITTED TO THE YCEHD AND AFTER CONSULTING WITH THE BOARD (MR DUNCAN AUSTIN) IT WAS DETERMINED THAT NO FURTHER ENVIRONMENTAL WORK ASSOCIATED WITH FORMER ABOVEGROUND STORAGE TANK (REPORTED ON 03/10/05) AT THE MENTIONED PROPERTY IS NECESSARY. A CASE CLOSURE WAS WARRENTED ON JUNE 12, 2006 WHICH FOLLOWED BY AN APPLICATION FOR MONITORING WELL DESTRUCTION.
RICHARDSON'S RADIATOR 1025 Drever St	HM W. Sac.	222 Lead Dust, Caustic Soda	Closed	LEAD DUST & CAUSTIC SODA CONTAMINATION. MATERIAL IN DRUMS TO BE REMOVED WITHIN 90 DAYS. SITE OTHERWISE CLEAN. CASE CLOSED.
RICK'S GAS STATION 45 Fifthteenth St	UST W. Sac.	14 Gasoline	Open	SOIL CONTAMINATION DISCOVERED DURING JULY 1998 REMOVAL OF 5 UST'S. Facility deemed out of compliance with local agency directives by the cleanup fund in October 2002.
RIDGE CUT FARMS 31495 CR 1	UST Dunnigan	602 Diesel	Closed	Soil diesel contamination discovered during 1992 removal of a 10,000 gallon UST (also removed a 10,000 gallon gasoline tank). Soils were excavated and remediated on site. Groundwater was monitored for 14 quarters with low levels of diesel observed during two quarters. Monitoring wells were destroyed and the case closed in September 1997. This file was archived as 602UTH in December 2003.
RITE AID DISTRIBUTION 503 East Street	6 Woodland	155 Transmission Oil	Closed	
RITE AID DISTRIBUTION 1755 BEAMER	L WOODLAND	458 e GASOLINE, DIESEL, BENZENE, MT	NEW	SOIL AND GROUNDWATER CONTAMINATION FOUND DURING A SUBSURFACE INVESTIGATION FOLLOWING A 2003 UST UPGRADE.
RITE AID DISTRIBUTION CENTER 1755 BEAMER	UST WOODLAND	458 DIESEL OIL	OPEN	SOILS PROFILED FOR DISPOSAL, DURING A RECENT UPGRADE, INDICATED ELEVATED LEVELS OF DIESEL AND MOTOR OIL AT CONCENTRATIONS OF 360 AND 21 PPM RESPECTIVELY. 08/18/03- WORKPLAN APPROVED TO DELINEATE THE LATERAL AND VERTICAL EXTENT OF SOIL CONTAMINATION AND TO ALSO DETERMINE IF GROUND WATER HAS BEEN IMPACTED.
RIVER FRONT DEVELOPMENT 35265 Willow Ave	HM Clarksburg	321 Variety of Haz Waste	Closed	HAZARDOUS WASTE INVESTIGATION FILE SEALED BY YC DA.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
RIVERPOINT INDUSTRIAL PARK Harbor Blvd & RXR, NW Corner	HM W. Sac.	9 Lead Contaminated Soils	Closed Battery wastes associated with the recycling process were buried on the property. In late 1989 and early 1990, the property owner remediated the lead contaminated soils by excavation and fixation. Approximately 14,000 cubic yards of soil were removed and treated by saturating the excavated soil with a sodium-potassium silicate mixture and then applying a cementing agent. The soil remediation goal was to reduce the level of soluble lead to below 5 ppm, STLC for lead. In May 1990 DHS approved a request to classify and manage the treated soil as non-hazardous based on the mitigating physical and chemical characteristics which rendered it insignificant as a hazard to human health and safety, livestock, and wildlife. Also in May 1990 the CVRWQCB approved the return of the treated material to the original excavation since test showed that onsite disposal of the treated material would "not pose a threat to water quality." Four consecutive quarters of groundwater monitoring were completed after return of the treated material to the original excavation. No lead was detected in any water sample from the site from each of the three monitoring wells or from either end of the adjacent unnamed canal. The CVRWQCB approved termination of ground water monitoring on June 29, 1995. After removal of the groundwater monitoring wells Yolo County closed this case.
RIVERVIEW INTERNATIONAL TRKING 2445 Evergreen Ave	UST W. Sac.	320 Gasoline	Closed Leak from UST resulted in soil remediation project. Post-remedial groundwater monitoring conducted through 1990. YCEH signed off Oct 1990. Case closed. File scanned to 320uth November 7,2002.
ROADWAY 4200 W Capitol Ave	HM W. Sac.	190 Dichlorvos/Pesticide	Closed H 190 - File contains emergency response and leak reports for fifteen incidents between April 18, 1989 and April 30, 1993 at this facility. Several referrals were made for prosecution to the Yolo County District Attorney. At least one incident resulted in injury to employees of the facility, and employees were placed under medical evaluation during several incidents. File archived as 00518HWG in February 2004.
ROADWAY DELTA 800 Delta Lane	HM W. Sac.	268 Diesel	Closed DURING A PROPERTY TRANSACTION, TWO SUMPS AND LINES WERE DISCOVERED AND EXCAVATED. THE SOIL WAS PLACED ONSITE GROUNDWATER IMPACTED BY SUMP. REMEDIATION WILL OCCUR WITH UST CONTAMINATION. SEE L452.
ROADWAY DELTA 800 Delta Lane	UST W. Sac.	452 Diesel	Open L 142: FILE A: PRE 1993 DATA - SITE CONTAMINATION FROM UST'S REMOVED. PRIOR TO 1988 DISCOVERED. SITE ASSMT IN 1991 INDICATES PUME MAY BE COMMINGLED WITH FREDRICKSON'S (L175). FILE B: 1993 DATA - EXCAVATION OF SOILS CONDUCTED IN 1992. JOINT QTR GW MONITORING CONDUCTED WITH FREDRICKSON'S. AQUIFER PUMP TEST PROPOSED IN OCT 93. EXTRACTION WELL CONSTRUCTED IN SEPT 93. FILE C: 1994 DATA - GROUNDWATER MONITORING CONTINUES. THE SITE WAS SOLD TO GOLDEN EAGLE EXPRESS, ROADWAY REMAINS RESPONSIBLE FOR CLEANUP. FILE D - 1999/2000 Data. File E 2000/2001 Data. Quarterly monitoring continues with diesel present detected in all wells and gasoline and benzene in some wells during the Feb 2001 sampling event. MTBE has not been detected in the wells tested for it. Project for multihousing development in progress as of October 2003. Applicant working with RWQCB re tank closure and will request Yolo County for risk assessment review for Land Use approval.
ROADWAY EXPRESS 1077 Gorge Place	HM W. Sac.	12 e Paint Waste	Closed ABANDONED 3 DRUMS. COMPANY REMOVED DRUMS & PROPERLY DISPOSED THEM. FILE CLOSED.
ROADWAY EXPRESS 4900 WEST CAPITOL AVE	L WEST SACRA	518 e DIESEL, ETHYLBENZENE, XYLENE	OPEN PETROLEUM CONSTITUENTS FOUND IN SOIL AND GROUND WATER DURING TANK SYSTEM REMOVAL.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
ROADWAY TRUCKING 800 DELTA LANE	USTL 452 G WEST SACRA DIESEL	OPEN	
ROBINSON, JOE JR 9599 Mill St	HM 320 Knights Landin Waste Oil, Batteries, Solvent	Closed	FINAL INSPECTION DONE ALL TIRES GONE - FILE CLOSED.
ROD TRANSPORT 3800 W Capitol Ave	HM 365 W. Sac. Oil	Closed	PHASE II SITE ASSESSMENT DONE. BORINGS DRILLED NEXT TO OIL WATER SEPERATOR, MINOR CONTAMINATION FOUND. FILE CLOSED.
ROGERS ST COMPLAINT 1013 Rogers St	HM 258 W. Sac. Waste Oil	Closed	REPORT WASTE OIL BEING DISPOSED TO SEWER. MET WITH OCCUPANT DIRECTING THAT THIS STOP.
ROLLINS LEASING 1781 South River Road	UST 323 W. Sac. Diesel	Closed	Soil contamination observed from possible over-spills during tank removal. Soils excavated and removed for off site treatment and disposal. As part of area wide hydrocarbon contamination problem, the CVRWQCB ordered firm to provide site history and work plan for soil investigation. File scanned to Adobe 323UTH
ROY E LAY TRUCKING 1218 Kentucky Ave	UST 326 Woodland Gasoline	Closed	LEAK DISCOVERED DURING 1986 TANK REMOVAL, SOIL REMEDIATION COMPLETED AUGUST 1986. FILE CLOSED.
ROY E LAY TRUCKING 1218 E KENTUCKY AVE.	UST 326 Woodland Diesel	Open	TANK REMOVAL 02/07/02. CONTAMINATION EVIDENT. ASSESSMENT AND LIMITED EXCAVATION IN PROGRESS. Further investigation approved in February 2003
ROY RIEGELS CHEMICAL 1785 Beamer St (East)	HM 173 Woodland VAPAM	Closed	File H 173 - John Taylor Fertilizer (formerly Roy Riegels Chemical) released approximately 500 gals of Vapam. All Vapam contamination from spill of June 2, 1992 removed & disposed of properly. File archived to 00543 in January 2004.
RUMSEY DRUG LAB Rollins Ranch	HM 51 e Rumsey Phenyl-2-Propanone	Closed	SUBSTANCE FOUND AT 700 PPB IN SOILS AT FORMER ILLEGAL DRUG LAB SITE. See FA 9864
RUMSEY ILLEGAL DUMP APN # 60-230-16	HM 49 e Rumsey Garbage	Closed	INVESTIGATION OF POSSIBLE PESTICIDE DISPOSAL IN ILLEGAL DUMP. ALL ANALYTICAL RESULTS WERE NEGATIVE. SITE CLOSED. See FA 9863
RUMSRY INDIAN RANCHERIA 14455 HWY 16	UST 577 BROOKS MTBE, TBA	OPEN	MINOR LEVELS OF CONTAMINATION FOUND DURING TANK REMOVAL. AREA OVER EXCAVATED. CONFIRMATION SOIL SAMPLES DID NOT DETECT ANDY TARGET CONSTITUENTS.
RUSSELL RANCH Russell Blvd 5 Mi W Of Davis	HM 97 Davis Petroleum	Closed	Filel H 97 - Gasoline contaminated soils from a leaky underground tank was excavated to less than 10 PPM and aerated on site. Oil, grease and diesel contaminate soils were removed from the site as designated waste for off site treatment in a land-farming bioremediation project. Case closed in October 1990. File archived in January 2004.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
RUSSELL STOVER CANDIES 500 Santa Anna Ct	UST Woodland	330 Diesel	Closed SUSPECTED LEAK DISCOVERED DURING MAY 1987 TANK REMOVAL. NO REMEDIAL ACTION REQUIRED UPON FURTHER INVESTIGATION. FILE CLOSED.
RUSSELL'S CLEANERS 62 W COURT STREET	HM WOODLAND	480 PCE	OPEN BASED ON REPORT BY EMG, PCE DETECTED IN SOIL VAPOR SAMPLES.
RYDER TRUCK RENTALS 2599 Evergreen Ave	HM W. Sac.	52 Diesel	Closed DIESEL SPILL ABSORBED AFTER CONTAINMENT AND DISPOSED AS HAZARDOUS WASTE. SEE UST LEAK FILES FOR MOTOR OIL PIPE LEAK. See 52UTH.
RYDER TRUCK RENTALS 2599 Evergreen Ave	UST W. Sac.	331 Motor Oil (New)	Closed FILE A PRE-1991 DATA: Pipe rupture released new motor oil onto ground below dispensers, pipe trenches, & tank backfill material. Pipe dispensers replaced, adjacent soils excavated. Product pumped from tank cavity. FILE B 1991: Further investigation found free product in groundwater. Assessment in progress. Approximately 200,000 gallons of contaminated water and free product were removed from the UST cavity. FILE C 1992-1997: DATA Most of the soil contamination has been removed, but gasoline hydrocarbons are present in groundwater. A total of eight USTs and soil and groundwater have been removed from this site over time. Site investigations have defined the limits of hydrocarbons in soil, but not in groundwater. FILE D: 1998-2001 DATA - A workplan for further investigation was requested by the CVRWQCB, to be submitted by March, 2000 to define groundwater conditions. Feb 2002, RWQCB finds that definition of contaminants in both soil and groundwater is complete and seems to indicate the site is nearing closure.
S M A EQUIPMENT CO 4076 Channel Dr	UST W. Sac.	253 Waste Oil	Closed In 1997 three underground storage tanks were removed and hydrocarbons were only detected beneath the former waste oil UST. YCEHS required further investigation of hydrocarbons found beneath the former waste oil UST, but not the former gasoline and diesel USTs. Soil and groundwater data show that motor oil and paint thinner range hydrocarbons from the former waste oil UST remain in shallow groundwater within the former waste oil UST cavity, and probably beneath the building. The extent of this plume of hydrocarbons in groundwater is defined, and does not pose a risk to the health of workers in the site building. No water supply wells are within 2,000 feet of the site. Hydrocarbons in groundwater beneath the site do not represent a threat to current or future beneficial uses of water; therefore, a No Further Action Required was issued by the CVRWQCB in May 2002..
S P T C/AMTRAK CR 32A & CR 105 Mile Post 78.5	HM Davis	185 e Diesel	Closed Estimated diesel spill of 500-800 gallons at CR 32A & CR 105 Mile Post 78.5. Soil and groundwater impacted with TPH as diesel. Referred to CVRWQCB Jan 1994. Assessment determined no significant threat to groundwater. Case closed Feb 1996. The Southern Pacific Transport Company (SPTC) was purchased by the Union Pacific Railroad. File archived as 03341HWG in January 2004.
S P T C/AMTRAK Railroad Mile Post 75	HM Davis	205 e Diesel	Closed Davis Amtrak Station: AMTRAK ENGINE RUPTURED DIESEL TANK RELEASING APPROX 300 GALS. SURFACE FUEL REMOVED. CONTAMINATION IMPACTS SURFACE SOILS IN LIMITED AREA. MONITORING FOUND NO MIGRATION. CASE CLOSED.
S P T C/AMTRAK Amtrak	HM Davis	249 Diesel	Closed TANK RUPTURE ON AMTRAK ENGINE RELEASED 300 GALS FUEL. SITE ASSESSMENT IN PROGRESS.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Sac/Yolo Mosquito Control District 1234 Fortna Way	UST Woodland	337 Gasoline	Closed L 337 - Soil contamination found during UST removal. Soils excavated and back-filled. Full closure report never submitted. Case closed. File scanned to 337UTH November 2002.
Sac/Yolo Mosquito Control Madison Fac 28864 Main St	HM Madison	452 Pesticides	Closed File H 452 Former Sacramento/Yolo Mosquito Control District facility currently used by Esparto Fire Department. During a pre sale investigation of sale of the facility to the Madison Fire Department, residuals of chlorinated pesticides (DDT, DDE, and DDD) and petroleum fuels (from above ground tanks) were identified in soils. Investigation found contamination limited to shallow soils with no groundwater impact. Impacted soils were excavated and disposed as hazardous waste in November 2003, and March of 2004. Sidewall samples obtain after the excavation found residual levels pose no risk to human health or the environment currently or during and future development of the site. Approximately 99 percent of the original mass of the chlorinated pesticide and petroleum-contaminated soils were removed during excavation. No detectable levels or chlorinated pesticides were present in five of the sidewall samples. DDD and DDT was reported in three samples. DDD concentrations ranged from .760 mg/Kg to 2.230 mg/kg and DDT from 0.130 to 17.2 mg/kg. Dieldrin and endrin were report in one sample at concentration of 0.130 and 0.320 mg/Kg respectively. Yolo County issued a no further action-required letter May 26, 2004. Case closed.
SACRAMENTO AUTO TRUCK 525 Galveston St	UST W. Sac.	462 Gasoline	Open LEAK DISCOVERED DURING DEC 1988 TANK REMOVAL. REMEDIATION COMPLETED. CLOSURE REPORT REQUESTED. RWQCB taking the lead (May 2000) requesting MTBE data.
SACRAMENTO GENERATOR 1725 W Capitol Ave	UST W. Sac.	504 B Gasoline, Lead	Open FILE B: EMERGENCY RECALCITRANT FUNDING INFORMATION, CORRESPONDENCE & STATE CONTRACT.
SACRAMENTO GENERATOR 1725 W Capitol Ave	UST W. Sac.	504 D Gasoline, Diesel	Open EMERGENCY ABANDONED RECALCITRANT SITE INVOICES AND BILLING INFORMATION.
SACRAMENTO GENERATOR 1725 W CAPITAL AVE.-	UST W. Sac.	504 H Gasoline, Diesel	Open CORRECTIVE ACTION PLAN - CORRESPONDENCE AND RFP
SACRAMENTO GENERATOR 1725 W Capitol Ave	UST W. Sac.	504 F Gasoline, Diesel	Open QUARTERLY EAR REPORTS FOR SWRCB.
SACRAMENTO GENERATOR 1725 W Capitol Ave	UST W. Sac.	504 E Gasoline, Diesel	Open EAR CONTRACT
SACRAMENTO GENERATOR 1725 W Capitol Ave	UST W. Sac.	504 C Gasoline, Lead	Open EAR WORKPLAN AND REPORT FILE.
SACRAMENTO GENERATOR 1725 W Capitol Ave	UST W. Sac.	504 A Gasoline, Lead	Open LEAK DISCOVERED DURING NOV 1988 REMOVAL OF 3 TANKS NOT USED FOR SEVERAL YEARS. OWNER REQUESTED TO CONDUCT SITE ASSESSMENT. ACTION AGAINST UNDER ADMINISTRATIVE REVIEW 1988 TO 1994.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Sacramento Insulation 411 Glide Ave	UST W. Sac.	332 Gasoline, Waste Oil	Closed L 332 In December 1993, three-underground storage tank and piping systems were removed from the site. The two larger tanks were used to dispense unleaded gasoline, the smaller tank for waste oil storage. Gasoline, waste and related hydrocarbons were identified in soil and/or groundwater beneath the tanks. Soils were excavated and disposed, water from the tank pit was pumped and monitoring conducted following these actions. Since 1995 concentrations of petroleum hydrocarbons fluctuated but generally decreased two to three orders of magnitude. Based on degradation and sensitive receptor studies the CVRWQCB determined that No Further Action was Required on February 3, 2002. This file was scanned to the 332UTH file in March 2003.
SACRAMENTO PLATING COMPANY 820 E St	HM W. Sac.	53 e Metal in Solution & Acids	Closed POSSIBLE WASTE STORAGE & DISPOSAL PRACTICES INCLUDING POSSIBLE UST FOR WASTE OIL. Investigation of soil contamination and sump inside structure was conducted during 2001 and 2002. The sump was cleaned out and sump filled with concrete. Soils found to exceed hazardous waste levels along the northern border of the property were excavated and appropriately disposed. File closed August 2002.
SACRAMENTO RIVER Sacramento River	HM W. Sac.	232 Unknown	Closed INVESTIGATION BY W. SAC. POLICE OF ALLEGED DUMPING OF CONTENT OF SEVERAL DRUMS INTO RIVER. CASE CLOSED DUE TO LACK OF EVIDENCE.
SACRAMENTO STUCCO 850 Riske Ln	UST W. Sac.	334 Gasoline	Closed Samples collected during tank removal indicated soil contamination at the dispenser island. Proposal submitted for over-excavation. Case closed Feb 1995 after soil excavation. File scanned to Adobe file 334UTH November 2002.
SACRAMENTO VALLEY FORD TRUCK 825 Stillwater	HM W. Sac.	217 Petroleum Waste	Closed INVESTIGATION OF ALLEGATION FACILITY PLACES FLOOR SWEEPINGS & CONTAMINATED ABSORBANT IN DUMPSTER. SITE VIST CONDUCTED. OWNER WARNED. FILE CLOSED.
SACRAMENTO VALLEY FORD TRUCK 825 Stillwater	UST W. Sac.	335 Waste Oil	Closed CLOSURE LETTER WRITTEN.
SALGADO RESIDENCE 637 Sunset	HM W. Sac.	54 e Oily Fluids	Closed DISPOSING OILY VEHICAL FLUIDS FROM WEEKEND GARAGE ACTIVITY AT HOME INTO STREET. ORDERED TO STOP FURTHER DISCHARGE TO STREET, SEWER, OR GROUND. See FA 9865
SAV MOR AUTO & RADIATOR REPAIR 737 Sacramento Ave	HM W. Sac.	202 Hydrocarbons	Closed DISCHARGE OF FLOOR DRAINS TO SEPTIC SYSTEM. SUMP SEALED TO PREVENT FURTHER DISCHARGE.
SCANVIK CORP(W.SAC RICE 20,1201 S RIVER RD	HM W. Sac.	421 Phase II Assessment	Closed H 421 - Former Rice Growers Association of California West Sacramento facility. Completion of Phase II Environmental Investigation at this property. Also data for two underground tanks removed at 920 S River Road. See also files U315, U318, and HM50. File closed.
SCHAEFFER, DENISE 163 Park Ave	UST Woodland	595 Gasoline	Closed DURING ROUTINE TANK REMOVAL, SOIL CONTAMINATION DETECTED. OVEREXCAVATION OF TANK EXCAVATION RESULTED IN CLEAN TANK PIT. SITE CLOSURE LETTER SENT. SITE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
SCHILLING RANCH 20500 RANCH RD	UST 620 BROOKS Gasoline	Closed	ONE 500 GAL TANK REMOVED. SAMPLES TAKEN AT FILL AREA OF EXCAVATION. SOIL CONTAMINATION DETECTED ONLY IN OVERBURDEN. SOIL EXCAVATED & AERATED ONSITE. CASE CLOSED 3/23/94. File archived as 620UTH in December 2003.
SCHWAB SALES INC 4101 W CAPITOL AVE	L 8616 WEST SACRA WASTE OIL	CLOSED	AST WASTE OIL TANK HAD INCIDENTAL OIL CONTAMINATION AROUND EAST SIDE OF STORAGE AREA. SOIL WAS REMEDIATED AND CONFIRMATION SAMPLES WERE BELOW DETECTION LIMITS.
SERPA RESIDENCE 53535 South River Road	HM 271 W. Sac. Solid Waste & Diesel	Closed	BURNING SOLID WASTE PILE, DIESEL FROM ABOVE GROUND STORAGE TANK IN SOIL. CLEANUP COMPLETED. CASE CLOSED.
SERVICE CLEANERS 1296 Gibson Road (East) C	HM 406 Woodland PCE	Open	PRELIMINARY RESULTS INDICATE BOTH SOIL AND GROUNDWATER ARE IMPACTED WITH TCE. RWQCB requesting site assessment workplan by Feb 2000workplan submitted. Investigation in Progress. Second Quarter 2002 report indicates contamination limited to within 200 feet of source.
SERVICE CLEANERS 1296 GIBSON ROAD EAST C	HM 406 WOODLAND PCE	OPEN	
SERVICE TRANSPORT 618 Galveston St	UST 342 W. Sac. Gasoline & Diesel	Open	GASOLINE AND DIESEL CONTAMINATION DISCOVERED DURING TANKS REMOVAL. SITE INVESTIGATION IN PROGRESS. MTBE (up to 290 ppb) and 47 ppb 1,2-dichloroethane found on site. RWQCB approved workplan for further investigation November 2000. CVRWQCB is the lead agency.
SERVISOFT 49 Main St (West)	UST 603 Woodland Gasoline	Closed	GASOLINE CONTAMINATED SOIL DISCOVERED DURING REMOVAL OF 500 GAL UST.SOILS EXCAVATED, MINOR CONTAMINATION LEFT IN PLACE. CASE CLOSED MAY 2000. File archived as 603UTH December 2003.
SEVEN ELEVEN #14093 1552 Jefferson Blvd	UST 1962 W. Sac. Gasoline	Open	1962 A - PRE 2000 DATA - Prior to a UST interior lining project an assessment was conducted in September 1996 using Geoprobe technology. It found Gas in soils and petroleum sheen on groundwater samples at all four Geoprobe sites. An investigation was initiated. The case was assumed by the CVRWQCB in Mar 2000. Facility directed to determine lateral and vertical extent of hydrocarbons in soil and groundwater and to continue quarterly monitoring. FILE B 2000 DATA - RWQCB issued a further directive in December 2000 indicating that the lateral and vertical extent of hydrocarbons still had not been defined and directed further investigation. Groundwater monitoring of four on-site wells is being conducted quarterly. FILE C 2001 DATA - Four additional wells installed per June report. Two were to first water, two to second water zone. BTEX and MTBE found in all eight wells, extremely high levels of MTBE found in one shallow well 2000 feet and cross to up-gradient from the tanks and dispensers. Investigation completed in October 2002 suggests contamination observed is from an off site source and closure was requested from the RWQCB.
SEVERAL TRUCK/AUTO REPAIR SHOP Several Locations	HM 248 W. Sac. Vehicle Fluids	Closed	REPORT OF SEVERAL FACILITIES DISPOSING CONTAMINATED ABSORBANTS INTO TRASH.CASE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
SHELL Davis Anderson Road 1944 ANDERSON RD	Davis	UST 349 Gasoline	Open	L 349 FILE A: Pre 2001 DATA. Soil contamination observed during Oct 1996 tank removal. Soils over excavated Investigation. Quarterly monitoring and site investigation to determine the lateral and vertical limits of contamination is soil and MTBE in groundwater in progress. FILE B 2001 DATA.
SHELL DOWNTOWN 435 G STREET	Davis	UST 351 Gasoline	Open	PHASE II ASSESSMENT, GROUNDWATER CONTAMINATION.
SHELL-CHILES-EQUILON 4480 CHILES ROAD	DAVIS	UST 348 B HYDROCARBONS	OPEN	CONTINUING STUDY ON LEAK FROM UNDERGROUND STORAGE TANK
SHELL-CHILES-EQUILON 4480 Chiles Rd	Davis	UST 348 A Hydrocarbons	CLOSED	SMALL AMOUNT OF GASOLINE MAY HAVE LEAKED UNDER DISPENSER/LINE. EXTENT TO BE DETERMINED.
SHORT STEP STORE 1664 E 8TH St	Davis	HM 225 Waste Oil	Closed	INVESTIGATION BY DTSC FOUND WASTE OIL DISPOSAL TO SOIL NEAR REAR OF FACILITY. OWNER DIRECTED TO CLEAN-UP. CASE CLOSED.
SHORT STOP 1840 W Capitol Ave	W. Sac.	USTL 3 e Gasoline	Closed	TANK LEAK DISCOVERED AND SOIL REMEDIATED IN MARCH 1986. FILE CLOSED.
Sierra Chemical - R K Gould 640 Harbor Blvd	W. Sac.	USTL 8 De Diesel & Chlorinated Solvents	Closed	FILE D 1993-1994 DATA: CHLORINATED SOLVENTS FOUND ON THIS & ADJACENT SITES. FURTHER INVESTIGATION INITIATED. SOURCE OF SOLVENTS HAS NOT BEEN IDENTIFIED.
Sierra Chemical - R K Gould 640 Harbor Blvd	W. Sac.	USTL 8 Ce Diesel	Closed	FILE C: SITE CLOSURE REPORT. (FILE IN BINDER IN LIBRARY.)
Sierra Chemical - R K Gould 640 Harbor Blvd	W. Sac.	USTL 8 Ee Diesel & Chlorinated Solvents	Closed	FILE E - MAY 1994 ADDITIONAL SITE ASSESSMENT & QUARTERLY REPORT. CONFIRMED GW STILL IMPACTED BY BOTH HYDROCARBONS & HALOGENATED VOLATILE ORGANICS. FOUND EARLIER PUMP & TREAT DID INFLUENCE ENTIRE SITE.
Sierra Chemical - R K Gould 640 Harbor Blvd	W. Sac.	USTL 8 Be Diesel	Closed	FILE B: CORRESPONDENCE
Sierra Chemical - R K Gould 640 Harbor Blvd	W. Sac.	USTL 8 Fe	Closed	
Sierra Chemical - R K Gould 640 Harbor Blvd	W. Sac.	USTL 8 Ae Diesel	Closed	FILE A TECHNICAL REPORTS: UST FAILED TESTING, REMOVED. SOIL & GROUNDWATER REMEDIATION COMPLETED. POST-REMEDIATION MONITORING IN PROGRESS.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Sierra Chemical - R K Gould 640 Harbor Blvd	USTL W. Sac.	8 Ge Petroleum, MTBE, PCE, TCE	Open 1998-2002 Files G & H - Several chemicals including gasoline, diesel, related petroleum products and thirteen halogenated volatile organic compounds have been identified on or associated with this site. Groundwater monitoring continues through the 2nd Qtr of 2002. Site data has been posted to Geotracker. RWQCB contact is David Starvarek (916) 255-3073.
SIERRA DETROIT DIESEL 3006 Evergreen Ave	HM W. Sac.	90 Oily Waste	Closed CONTAMINATED SOILS DISCOVERED DURING REMOVAL OF OIL/WATER SEPARATOR. SOILS HAVE BEEN EXCAVATED. RESULTS PENDING ON GROUNDWATER QUALITY. RESULTS NEVER SUBMITTED. BLD REMOVED, LOT PAVED. FILE CLOSED.
SIERRA SOD (MARTIN BROTHERS) 27991 Mace Blvd	UST Davis	585 Diesel	Closed DIESEL CONTAMINATION DISCOVERED DURING TANK REMOVAL. SOIL EXCAVATED & STOCKPILED ON-SITE. EXCAVATED SOIL WAS BIO REMEDIATED TO LESS THAN 75 PPM AND SPREAD ON ROADS ONSITE. FILE CLOSED 05/11/94. File archived to 585UTH in December 2003.
SILVER BEND Route 1 Box 9	HM Clarksburg	124 Waste Oil & Diesel	Closed ILLEGAL STORAGE OF WASTE OIL & DIESEL CONTAMINATED SOILS. ALL CLEAN-UP ORDERS COMPLETED. SITE CLOSED.
SIMPLOT SOIL BUILDERS HWY 84 & Courtland Rd	UST Clarksburg	476 Gasoline	Closed LEAK DISCOVERED DURING AUG 1987 TANK REMOVAL, SOIL REMEDIATION COMPLETED OCT 1987. FILE CLOSED.
SISKIYOU FOREST 22 N CR 101	UST Woodland	354 Diesel	Closed CLOSURE LETTER WRITTEN. FILE CLOSED. File scanned to Adobe 354UTH 1/17/03
SMUD Campus	HM Davis	325 Misc	Closed Files contains well permits and letter regarding Cooling tower Discharges.
SMUD 2900 MARSHALL RD.	HM W. Sac.	442 Lead	Closed SMUD inadvertently shipped lead contaminated soil to this site for use as fill. Contaminated soil was removed and sampling conducted.
SMUD GAS PIPELINE INTERTIC 27700 CR 29	HM WINTERS	473 HYDROSTATIC TEST WATER	CLOSED GENERAL WAIVER FROM WDR'S FOR HYDROSTATIC TEST WATER.
SOLANO CONCRETE CO HWY 16 & I-505	UST Madison	355 Diesel	Closed LEAK DISCOVERED DURING 1988 REMOVAL OF 12,000 GAL TANK, SOIL REMEDIATION COMPLETED AUGUST 1988. FILE CLOSED 9/1/88. Notice of Violation of Waste Discharge Requirements issued by CVRWQCB August 1, 2002.
SOUTHERN PACIFIC Third St	HM Davis	132 e Waste Oil	Closed WASTE OIL OBSERVED ON THE GROUND. SOIL EXCAVATED WITHOUT COUNTY OVERSIGHT. PROPOSAL FOR SAMPLING OBTAINED. SAMPLING OCCURRED IN LATE AUGUST 1991. CASE CLOSED.
SOUTHERN PACIFIC RAILROAD Yolo Bypass	HM Davis	56 Abandoned Drums, No Release	Closed H 56 - Twenty drums abandoned in November 1988 on railroad right of way. Removal and disposal handled by railroad contractor. Case closed. File archived to 00502HWG in December 2003.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
SOUTHERN PACIFIC TRANSPORT CO Harbor Blvd & SPTC ROW W. Sac.	HM 95	Open	LEAD CONTAMINATION ASSOCIATED WITH ADJACENT SITE (SEE HW 09) FOUND ON SOUTHERN PACIFIC ROW. SOUTHERN PACIFIC SUBMITTED PROPOSAL FOR PHASE II INVESTIGATION TO LEAD AGENCY CVRWQCB MAY 1991.
SOUTHPORT ELEM SCHOOL Lindon Rd	HM 306	Closed	PRE CONSTRUCTION GEOTECH INVESTIGATION
Southport Framework Plan EIR Southport	HM 296	Closed	Final Environmental Impact Report for the Southport Framework Plan. No significant hazardous waste releases identified.
SPECIAL INVESTIGATION CR 97B	HM 212	Closed	INVESTIGATION OF POSSIBLE ILLEGAL DISPOSAL OF ASBESTOS & AGRICULTURAL CHEMICALS. CASE CLOSED DUE TO LACK OF EVIDENCE.
SPRECKELS SUGAR COMPANY CR 17 & CR 103	HM 172	Closed	ON OCT 15, 1992 NINE DRUMS FOUND DUMPED ON SPRECKELS PROPERTY. YCEH & YC DA'S OFFICE INVESTIGATED INCIDENT. MATERIAL TRANSPORTED VIA HAZARDOUS WASTE MANIFEST. THE FILE IS CLOSED.
SPRECKELS SUGAR COMPANY 40600 CR 18C & CR 101	HM 322	Closed	MOLASSES SPILL, CASE CLOSED.
SPRECKELS SUGAR COMPANY CR 18C CR 18C & CR 101	UST 357	Closed	Six tanks including two tanks with 550,000 gallons of fuel oil. Phase II investigation by new owner Sugarland Farms at site of a 1987 gasoline tank. In September 2002 they found that soil and groundwater had been impacted by hydrocarbons at the site of a 1987 1,000 gasoline tank removal. The CVRWQCB required investigation be initiated in October 2002. See also the UST 357 History file. 2/25/2008 CRWQCB granted No further Action Required for this case. See No Further Action Required document dated 2/25/08 scanned under FA0000357 LUST Correspondence, Closure documentation.
SPRECKLES SUGAR CO CR 18C CR 18C	UST 357	OPEN	02/28/08: WASTE OIL UST WAS EXCAVATED AND REMOVED IN 1987. FOUR SOIL BORINGS WERE DONE IN FEBRUARY '08 IN THE VICINITY OF THE AGRICULTURAL REPAIR SHOP THAT REVEALED SOIL CONTAMINATION WITH TPHd AND GROUNDWATER CONTAMINATION WITH TPHd AND TPHmo. INSTALLATION OF GROUNDWATER MONITORING WELLS RECOMMENDED BY WALLACE KUHL.
STANLEY GUSTAFSON 1520-40 South River Road	HM 364 e	Open	DIESEL AND MOTOR OIL CONTAMINATION AT SHALLOW DEPTH OF 2-4 FEET. CONTAMINATION FOUND IN PHASE II REPORT.
STAR RADIATOR SERVICE 2 Kentucky Ave (West)	HM 55 e	Closed	DISPOSING RADIATOR COOLANT AND CLEANING RINSEATE INTO SEPTIC LEACH FIELD. ORDERED TO STOP FUTURE DISPOSAL. See FA 4524
STEAM CLEAN 2569 Lagoon lane	HM 243	Closed	REPORTED DISPOSAL OF CARPET CLEANING WASTE TO STORM DRAIN. OPERATOR WARNED REPEATED VIOLATION WOULD BE PROSECUTED. FILE CLOSED.

Facility	File/Number	Status	Comments	
STREAM ENERGY HESS WELLS CR 103	HM Woodland	453 Petroleum	Open	DIESEL AND MOTOR OIL CONTAMINATION IN THE MUD PITS AT NATURAL GAS WELL SITES.
SUNBEET CR. 89	HM Madison	78 Dried Tomato Pumice	Closed	INVESTIGATION OF SEASONAL FLY, ODOR, RUNOFF AND DRIFTING MATERIALS. SEE ALSO H94-283 FOR WOODLAND FACILITY. FACILITY CLOSED, CASE CLOSED.
SUNBEET Gibson (East) & CR 102	HM Woodland	283 Dried Tomato Pumice	Closed	INVESTIGATION OF SEASONAL FLY, ODOR, RUNOFF AND WIND-BLOWN DRIFTED PUMICE. SEE ALSO H223 FOR MADISON FACILITY. FACILITY CLOSED, CASE CLOSED.
SUNSHINE CLEANERS 120 MAIN STREET	HM WOODLAND	444 TETRACHLOROETHENE(PCE)	OPEN	Tetrachloroethene (PCE) contamination found in ground and groundwater at sunshine cleaners. Groundwater samples contained from 17.6 to 53,100 micrograms per liter per Nov 2002 report. Neither soil or groundwater plumes defined laterally or vertically.
SUNSWEEP DRYERS INC CR 27 & I-505	HM Winters	211 Treated Prune Wastewater	Closed	RECEIVED WDR FOR DISCHARGING TREATED PRUNE WASTEWATER TO OPEN FIELDS. FILE INITIATED FOR MONITORING PURPOSES ONLY.
SUPERIOR CALIFORNIA TRUCKING 604 GALVESTON	Le WEST SACRA	360 GASOLINE, DIESEL	OPEN	
SUTTER DAVIS HOSPITAL 2000 Sutter Place	HM Davis	286 File Moved To T Files	Closed	HAZ WASTE TREATMENT PERMIT. TREATMENT WAS CLOSED.
SUTTER DAVIS HOSPITAL (FORMER) CR 99	HM Davis	326 Sludge	Closed	FILE A: MARCH 1996 ASSESSMENT AND OCTOBER 1997 CLOSURE REPORT FOR WASTEWATER DETENTION PONDS.
SYAR INDUSTRIES HWY 16 & I-5	UST Madison	402 Diesel	Closed	OVERSPILL CONTAMINATION OBSERVED DURING NOV 1988 TANK REMOVAL, SOILS EXCAVATED JAN 1989, STOCKPILES REMAIN UNCHARACTERIZED. CASE CLOSED. File scanned to 402UTH June 2003.
SYCAMORE RANCH ROAD PROJECT CR 102 AT GIBSON	HM Woodland	445 Petroleum (Old Road Oil)	Closed	
T N T REDDAWAY 620 Harbor Blvd	UST W. Sac.	177 Diesel	Closed	SOIL & GW CONTAMINATION DISCOVERED DURING 1991 REMOVAL OF 2 TANKS. RWQCB CONCLUDES IN AUGUST 1997 LETTER "SITE HAS ONLY MINOR REMAINING DIESEL...AND IS LOW RISK TO WATER RESOURCES OR HUMAN HEALTH". FILE CLOSED. Documents scanned and incorporated into file 177 UTH.
T S GLIDE 28120 Pierce Ranch Rd	HM Davis	353 Drums	Closed	MANY DRUMS CONTAINING WASTES & MANY EMPTY DRUMS WERE ON SITE. TRANSPORTED AS HAZARDOUS WASTE.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
T S GLIDE RANCH 36355 Russell	UST Davis	3021 TPH Closed	One tank at each of three sites were removed in August 1997. Minor soil contamination was observed at all three sites. Contaminated soils were excavated. Case closed April 1998, file archived to 3021UTH in December 2003.
TAFOYA ENTERPRISES 145 East St	HM Woodland	93 Diesel, Motor Oil Closed	TRUCK ACCIDENT RESULTED IN 150 GALS DIESEL SPILL TO SOIL. BIO-REMEDIATION REVIEWED, APPROVED & COMPLETED.
TAFOYA, CLARA 30 Main St	HM Woodland	358 Indoor Air Quality Closed	AIR MONITORING DONE IN THE BASEMENT. NO HAZARDS FOUND.
TEICHERT AGGREGATE ESPARTO ASPH 27944 CR 19A	HM ESPARTO	472 DIESEL, HEATING OIL OPEN	
TEICHERT AGGREGATES CR 29	HM Davis	167 CEMENT, LIME Closed	REGIONAL BOARD CONDUCTED INSPECTION & FOUND CEMENT & LIME IN ROAD DITCHES. TEICHERT REQUIRED TO SUBMIT REPORTS ON DISCHARGES TO ROAD DITCHES.
TEICHERT WOODLAND AGGREGATE QU 35030 CR 20	UST WOODLAND	3893 WASTE OIL OPEN	FORMER USED OIL TANK REMOVED IN 2002. SOIL AND GROUNDWATER IMPACT DISCOVERED.
TENCO TRACTOR 2415 W Capitol Ave	HM W. Sac.	79 Lead, Hydrocarbons Closed	Morgan Equipment began site use in 1972 with a heavy equipment sales and repair facility. Tenco continued this use when in took over the site in 1978. Two 10,000 gallon gasoline underground storage tanks were removed in 1984, a waste-oil sump and associated underground piping were removed in 1985, and a 1,000 gallon waste oil tank removed in 1987. Site investigations began in 1989 and identified the following polluted areas: former gasoline USTs, former oil storage area, gravel covered area, waste oil sump/tank/pipeline, paint booth area, and steam cleaner pad. Tenco vacated the site in 1996. Investigation of the site showed contaminated soil to be generally shallow and localized to specific onsite locations. Excavation of contaminated soil, and removal of the underground storage tanks and piping has removed the source and secondary contamination. Mass calculations show that hydrocarbon constituents of concern (BTEX and VOCs) remaining in soil are below 0.05 pounds and do not appear to pose a threat to groundwater quality. Groundwater monitoring shows that hydrocarbon plumes are relatively stable and largely localized around well MW-3. MTBE has never been detected, and benzene and toluene have not been detected since December 1997. An ASTM RBCA analysis shows that health risks from potential chemicals of concern remaining beneath the site are below levels of concern. Case closed April 1999.
TERMINAL MUFFLER - KONTOS 2415 W Capitol Ave	UST W. Sac.	370 Gasoline Closed	Two underground tanks, which reportedly contained leaded gasoline, were removed in 1987. Soil impact beneath the tanks was reported and an investigation conducted between 1989 and 1992. The sources of contamination (tanks) have been removed from the site. It appears that the extent of contamination remaining at the site has been defined and is very limited.. The consultant calculated that approximately 593 pounds of TPHg remain in the soil beneath the site and 0.011 pounds remain dissolved in the groundwater. In addition, 1.64 pounds benzene and 15.1 pounds BTEX remain in the soil and 0.0001 pounds benzene and 0.001 pounds BTEX remain dissolved in the groundwater (al of sampling conducted in 1996). All monitoring and wells associated with this site have been abandoned and the CRWQCB issued a no further action letter effective August 8, 1997. File scanned to 270UTH June 2003.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
TERMINAL TRUCK SERVICE 971 F ST	UST W. Sac.	371 e Hydrocarabons	Open FILE A: DIESEL SOIL CONTAMINATION OBSERVED DURING DEC '96 REMOVAL OF 2,000 GAL UST. Soil excavation and assessment proposed in Feb 2000. Further investigation found groundwater impacted with gasoline, BTX and MTBE. Groundwater monitoring conducted quarterly. RWQCB is the lead agency.
TERPCO 1500 Case Place	HN Woodland	297 Waste Oil	Closed WASTE ENGINE OIL SPILLED AT THREE LOCATIONS. SOIL EXCAVATED AND TRANSPORTED TO FORWARD LANDFILL IN STOCKTON.
Terpco Truck Repair 1500 Case Place	HM Woodland	297 Waste Oil	Closed Waste oil from leaking drums spilled on to soil. Soil was removed from three small locations and areas resampled. Case closed.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 He Gasoline, Diesel	Closed FILE H: 1994/1995 QUARTERLY REPORTS & CORRESPONDENCE. FLOATING PRODUCT RECOVERY SYSTEM OPERATED FROM 1987 TO 1989.TANKS & PIPE SYSTEMS REPLACED IN 1991-SOILS WERE OVEREXCAVATED & REMOVED DURING PROJECT.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Le Hydrocarbons	Closed FILE L: 1998 DATA- 3RD QUARTER OBSERVED GASOLINE UP TO 4,400 PPB, DIESEL 170,000 PPB, BENZENE 160 PPB AND MTBE AT 2,500 PPB.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Je Gasoline, Diesel	Closed FILE J- 1996 DATA. QUARTERLY MONITORING CONTINUES. FACILITY REQUESTSCASE CLOSURE AS A LOW RISK SITE.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Ke Gasoline, Diesel	Closed FILE K-1997 DATA. FLOATING PRODUCT GASOLINE REAPPEARS. MAY BE A NEW RELEASE. DELETE AND REPLACE WITH WORKPLAN & ADDENDUM TO INSTALL ADDITIONAL WELLS & SOIL BORINGS APPROVED DEC 1997 TO INVESTIGATE FREE PRODUCT & FINISH INVESTIGATION.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 le Hydrocarbons	Closed FILE M:1999 DATA. MONITORING CONTINUES. DIESEL STILL UNDEFINED. Workplan for additional investigation approved Jan 2000. CVRWQCB is the lead agency.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Be Diesel, Gasoline	Closed FILE B: SITE INVESTIGATION REPORT JULY 1989, PROBLEM ASSESSMENT REPORT OCT 1989.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Ce Diesel, Gasoline	Closed FILE C: QUARTERLY REPORTS 1989-1990.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 De Diesel, Gasoline	Closed FILE D: GENERAL FILE 1989-1992
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Ee Diesel, Gasoline	Closed FILE E: QUARTERLY REPORTS 1991-1992.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Fe Diesel, Gasoline	Closed FILE F: QUARTERLY REPORTS 1993
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Ge Diesel, Gasoline	Closed FILE G: GENERAL FILE 1993.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Ae Diesel, Gasoline	Closed FILE A GENERAL FILE 1986-1988: LEAK REPORTED APR 1986. ANOTHER LEAK REPORTED DURING DEC 1988 TANK TEST. ALL TANKS & PIPING REPLACED WITH DOUBLE WALL UNITS. SOILS REMEDIATED & APPROVED FOR ROADBASE.
Tesoro # 67064 (Beacon Dunnigan) 29770 CR 8	UST Dunnigan	34 Ne Hydrocarbons	Open FILE N:2000 DATA CVRWQCB is the lead agency. Quarterly monitoring in progress, hydrologic assessment planned or in progress. Further investigation to define lateral and vertical distribution required by the CVRWQCB in October 2002. Workplan approved Feb 2003
Tesoro/ARCO 1701 South River Road	HM W. Sac.	83 Gasoline	Open File A - Pre 2001 data, File B 2001 data. RWQCB DETERMINED TESORO SOLE RESPONSIBLE PARTY FOR EXTENSIVE GASOLINE CONTAMINATION FOUND IN GROUNDWATER BELOW THEIR FACILITY & ALONG JEFFERSON BLVD. BOARD ORDERED TESORO TO INVESTIGATE & CLEAN-UP IN MARCH 1992. 1994, REGIONAL BOARD IS LEAD AGENCY. As of February 2002 there area 67 wells at or near the terminal. Plans for further investigation, expansion of the remediation system and revisions to the monitoring program were required in June 2002.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 Ae Gasoline	Closed FILE A PRE 1993 DATA: PRE-DEVELOPMENT STUDY FOUND SOIL & GROUNDWATER CONTAMINATION. LAWSUIT HALTED INVESTIGATION IN '92. LATERAL & VERTICAL EXTENT OF CONTAMINATION HAS NOT BEEN DEFINED.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 He Gasoline	Closed FILE H:2000 - 2001 DATA - CVRWQCB IS LEAD AGENCY - CONTACT DAVID STAVAREK 916-255-3073. BIO-SPARGE REMEDIATION SYSTEM INSTALLED AND OPERATIONAL MAY 1999 continues to operate through 2001.
TEXACO (FORMER DAVIS SITE) 712 G St	HM Davis	25 Ie Gasoline	Open 25 I - 2002 Data - Air Sparging system operating since 1999 has not noticeably reduced concentrations. RWQCB directed in Dec 2002 additional site evaluation and study to determine if other remedial methods could be more effective.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 Ee Gasoline	Closed FILE E:1997 DATA- THE PAR/FRP (1998) FINDS PCE TO BE ASSOCIATED WITHAN UNRELATED OFF SITE SOURCE AND RECOMMENDS AIR SPARGING FOR TREATMENT, AS MOST OF THE PETROLEUM HYDROCARBON CONTAMINATION IS TIED UP IN THE SOIL 10 TO 20 FEET BELOW THE WATER TABLE.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 Ge Gasoline	Closed FILE G:1999 DATA - CVRWQCB IS LEAD AGENCY - CONTACT DAVID STAVAREK 916-255-3073. BIO-SPARGE REMEDIATION SYSTEM INSTALLED AND OPERATIONAL MAY 1999.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 Be Gasoline	Closed FILE B 1993-1994 DATA: FEB '94 RWQCB INDICATES LAWSUIT MAY BE IMMINENT, REQUIRED QUARTERLY REPORTS, FREE PRODUCT REMOVAL & WORKPLAN TO DEFINE EXTENT OF SOIL & GROUNDWATER CONTAMINATION.

Facility	File/Number	Status	Comments	
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 De Gasoline	Closed	FILE D:1996 DATA - QUARTERLY MONITORING CONTINUES. RWQCB INITIATED ENFORCEMENT AGAINST THE FACILITY FOR FAILURE TO INVESTIGATE & REMEDIATE SITE CONTAMINATION IN MAY 1998. A COMBINED PAR & FRP WAS SUBMITTED IN OCTOBER 1998 FOR AGENCY APPROVAL.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 Ce Gasoline	Closed	FILE C: 1995 DATA - DISTRIBUTION OF GASOLINE FAIRLY WELL DEFINED. OTHER SOLVENTS INCLUDING PCE, MEK, & OTHER HAVE BEEN FOUND BUT NOT YET DEFINED.
TEXACO (FORMER DAVIS SITE) 712 G ST	HM Davis	25 Fe Gasoline	Closed	FILE F-1998 DATA
TEXACO (FORMER STATION) 831 Jefferson Blvd	UST W. Sac.	9 Gasoline	Closed	FILE L 9: Soils & groundwater contamination found at former fuel station site. The sources of the contamination have been removed from the site. The majority of the contaminated soils were excavated and remediated. The remaining petroleum hydrocarbons have been substantially reduced through groundwater pump and treat, soil vapor extraction, and air sparging. It appears that the extent of contamination remaining at the site does not pose a threat to water quality. File closed December 1997 and archived to 2882UTH in December 2003.
TEXACO SERVICE STATION 300-316 W CAPITOL AVE	UST WEST SACRA	6464 e GASOLINE, MOTOR OIL	OPEN	
THE PRUDENTIAL 405 Main St	HM Woodland	301 Indoor Air Quality	Closed	AIR SAMPLE INDICATES GASOLINE RANGE HYDROCARBONS AT ELEVATED LEVELS. PROPERTY OWNER & TENANT DISMISSES AS TRANSIENT. NO SOURCE LOCATED.
THERMO KING 855 STILLWATER ROAD	He WEST SACRA	488 DIESEL AND MOTOR OIL	OPEN	GROUNDWATER IS IMPACTED. REFERRED TO CVRWQCB.
THRONE FARMS 4451 W Capitol Ave, CR 22	HM W. Sac.	129 Petroleum	Closed	File H 129 - File contains complaint investigation reports of improper hazardous material handling procedures. Reference is made in an old database to District Attorney (sealed) and Housing (H9/H16) files that could not be located in January 2004. File archived to 04583HWG in January 2004.
TIDEWATER OIL 1021 BEAMER STREET	HM WOODLAND	481 DIESEL FUEL, MOTOR OIL	CLOSED	PHASE I AND PHASE II SITE ASSESSMENTS IDENTIFIED DIESEL FUEL AND MOTOR OIL CONTAMINATION IN SHALLOW SOIL. NO FURTHER ACTION REQUIRED. SEE RELATED FILE H 161.
TNT Bestway 1876 South River Road	HM W. Sac.	183 Propylen Glycol Methyl Ether A	Closed	H 183 - Drum punctured in tractor trailer leak into trailer. Drum removed to parking lot. Trailer allowed to volatize, material on parking lot absorbed. Estimated total released was 25 gallons. Several employees affected by fumes. File archived as 00046HWG in January 2004.
TODHUNTER LAKE FIELD WELL #2 Causeway Levee & RR Tracks	HM Davis	302 Motor Oil (New)	Closed	15 GAL MOTOR OIL SPILL. IN-SITU BIOREMEDIATION OF SOIL TO OCCUR.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
TOM'S HOUSE OF HYDRAULICS 2904 Duluth St	HM W. Sac.	213 Solvent/Hydraulic Oil Waste	Closed INVESTIGATION INTO THE STORAGE & DISPOSAL PRACTICES. NO DISCHARGES OBSERVED. FILE SEALED. CASE REFERRED TO DISTRICT ATTORNEYS.
TONY'S FINE FOODS 3575 REED AVE	Le WEST SACRA	545 DIESEL, MtBE, tBA	OPEN 05/07/03- TPhD, MtBE AND tBA FOUND IN LOW CONCENTRATIONS UNDER DISPENSERS AND PIPE.
TOSCO # 30310 (UNOCAL #0164) 208 Main St	UST Woodland	391 Waste Oil, Gasoline	Closed WASTE OIL TANK TEST DONE ON MAR 26, 1993 FAILED. TANK EMPTIED & LOCKED OFF. CONTAMINATION EXCAVATED, FILE CLOSED 12/93. \--/ Two fuel tanks removed 12/98, gasoline observed beneath dispensers, site over-excavated and soils removed. CASE & FILE CLOSED. SEE FILE U3655 FOR NEW CASE & FILE FOR DIFFERENT TANKS.
TOSCO (UNOCAL) 208 Main St	UST Woodland	3655 Gasoline	Open REMOVAL OF UST INDICATES POSSIBLE GASOLINE CONTAMINATION IN DISPENSER AREA. GASOLINE AT 2,100 PPM.
Tosco (UNOCAL) #6436 1556 Main St (East)	UST Woodland	2989 B Gasoline, Diesel	Closed FILE B-1994 DATA: DELINEATION OF SOIL & GROUNDWATER IMPACT REMAINS INCOMPLETE. BOTH DIESEL & GAS IDENTIFIED. TPHG UP TO 100,000 PPM & 2,800 PPB BENZENE PRESENT IN GROUNDWATER. GROUNDWATER FLOWS TO SOUTHEAST.
Tosco (UNOCAL) #6436 1556 Main St (East)	UST Woodland	2989 D Gasoline	Open FILE D: 1998/2000 DATA- SEMIANNUAL MONITORING CONTINUES. Very low levels of hydrocarbons reported.
Tosco (UNOCAL) #6436 1556 Main St (East)	UST Woodland	2989 C Gasoline, Diesel	Closed FILE C:1995-1997 DATA: SOIL & GROUNDWATER CONTAMINATION HAS BEEN DEFINED. PLUME IS STABLE & LIMITED TO AREA BEHIND (SOUTH) THE BUILDING WHERE THE FORMER TANKS WERE LOCATED.
Tosco (UNOCAL) #6436 1556 Main St (East)	UST Woodland	2989 A Gasoline, Diesel	Closed FILE A: 1993 DATA - DURING TANK REPLACEMENT CONTAMINATION WAS DISCOVERED. PIER FOUND BOTH SOIL & GROUNDWATER IMPACT. PHASE I SITE INVESTIGATION IN PROGRESS.
TOSCO BULK PLANT 1152 CROSS ST	HM Woodland	388 Gasoline & Diesel	Open H388 - Former Bulk Plant constructed in 1937. Groundwater and soil contamination by both gasoline and diesel observed in monitoring wells located between the Aboveground Storage Tanks and Storehouse (drum filling area). MTBE and TBA were also identified. CVRWQCB is lead agency. Groundwater is 15 to 20 feet below ground surface. Facility proposed a groundwater monitoring plan in October 2002, CVRWQCB requests Feasibility Study/Remedial Options Evaluation Report. An addendum to the Remedial Feasibility report was required in Dec 2002
Tosco Circle K 1506 Sacramento Ave	UST W. Sac.	103 Gasoline	Open TANK REMOVAL DONE , SOIL CONTAMINATION FOUND. ORDER WRITTEN. Groundwater monitoring in progress. Gasoline, BTEX and MTBE decreasing over time. In Dec 2001 TPH-G was present in concentrations up to 4,200 ppb, benzene up to 910 ppb, and MTBE up 270 ppb. The RWQCB requested in September 2002 a Final remediation Plan and schedule to use dual-phase extraction to remove secondary source from groundwater and conduct further monitoring and assessment.

Facility	File/Number	Status	Comments	
TOWER COURT W Capitol & Tower Court	Hme W. Sac.	394 Lead	Open	LEAD FOUND IN SHALLOW SOILS. CONSULTANT PROPOSES SCOOP AND RUN.
Town and Country Market 300 East and Main St	HM Winters	437 Waste Oil	Closed	Complaint of motor oil and urine being disposed at apartment complex operated by this facility. Owner requested to clean up ground and remove containers of waste oil. Cleanup completed March 28, 2001. Case closed
Towne Ranch Property 43605 Montgomery Ave	HM Davis	460 Diesel	Open	HM 460Soil contamination found during 2002 removal of a 600 gallon aboveground diesel tank. Initial excavation found diesel beyond the limits of excavation, a workplan for site assessment and further investigation was approved Dec 20, 2002
TOYOTA VLADES 2620 W CAPITOL AVE	H WEST SACRA	491 e GAS, DIESEL, POG	OPEN	SOIL AND GROUNDWATER CONTAMINATION FOUND. SOURCE UNDETERMINED. UST ABANDONED ON SITE.
TRI CAL 39985 CR 14	HM Woodland	355 Pesticides	Closed	COMPLAINT INVESTIGATION 12197 FOUND MINOR SURFACE PETROLEUM. SOIL & WATER SAMPLING FOR CONDITIONAL USE PERMIT APRIL 1998 FOUND NO PESTICIDE IN SURFACE SOIL ON DOMESTIC WELL.
TRINITY DRUG LAB 112 TRINITY STREET	HM Woodland	363 Various, See File	Closed	METHAMPHETAMINE LAB RAIDED 10/31/97, HOUSE CONDEMNED 11/4/97, SITE CONTAMINATION SURVEY PENDING.
TRUCK AND TRAILER REPAIR 555 Galveston St	UST W. Sac.	507 Gasoline	Closed	LEAK DISCOVERED DURING SEPT 1988 TANK REMOVAL. NO SOIL CLEANUP REQUIRED. GROUNDWATER BEING MONITORED. SAMPLING CONDUCTED OCTOBER 1988 FOUND NO GROUNDWATER CONTAMINATION. ADDITIONAL ROUND OF SAMPLING REQUESTED. OWNER FAILED TO COMPLY. FILE CLOSED. File archived to 507UTH in November 2003.
TRUCK/AUTO REPAIR SITES	HM W. Sac.	223 Vehicle Fluids	Closed	REPORT OF SEVERAL FACILITIES DISPOSING CONTAMINATED ABSORBANTS INTO TRASH. FILE CLOSE DUE TO LACK OF TIMELY INVESTIGATION.
TURNER LAND COMPANY VACANT LOT 800 SACRAMENTO AVE	H WEST SACRA	499 GASOLINE AND DIESEL	OPEN	INVESTIGATIVE WORK WAS DONE IN DECEMBER 2006 TO DETERMINE WHETHER SOIL AND GROUNDWATER AT THE SITE HAD BEEN IMPACTED WITH PETROLWUM HYDROCARBONS DUE TO LEAKAGE FROM UST'S THAT HAD BEEN LOCATED ON THE SITE YEARS AGO. BOTH GASOLINE AND DIESEL WERE DETECTED IN SOIL AND GROUNDWATER. UAR WAS RECEIVED ON 01/11/2007. FORWARDED CASE TO REGIONAL WATER BOARD ON 03/22/2007.
TUOLD PROPERTY CR 98B & Kentucky, NW Corner	HM Woodland	80 Hydrocarbons	Closed	FORMER AUTOMOTIVE WRECKING YARD & VARIOUS LIGHT INDUSTRIAL BUSINESS. SOIL INVESTIGATION FOUND MINOR HYDROCARBON CONTAMINATION OF SURFACE SOILS. OWNER DIRECTED TO REMOVE OBVIOUS SURFACE STAINS. FILE CLOSED JAN 1992.
TWO BAY OIL COMPANY NW Corner CR 92C & CR 20	HM Woodland	153 Diesel	Closed	SOIL AT SITE CONTAMINATED WITH 40 GALS OF DIESEL. THE CONTAMINATED SOIL EXCAVATED TO DEPTH OF 17 FT BELOW SURFACE GRADE. SITE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
U S POSTAL SERVICE 3775 Industrial Blvd	HM W. Sac.	204 Vehicle Wash Waste	Closed FACILITY VEHICLE WASH WATER WAS BEING DISCHARGED TO STORM DRAIN SYSTEM. COLLECTION SYSTEM TO BE INSTALLED. CASE CLOSED.
U S POSTAL SERVICE VEHICLE MAINT 3780 SEAPORT BLVD.	UST W. Sac.	581 Gasoline	Open File 581 A - Contamination found during removal of 3 UST's in June 2001. RWQCB is lead agency. Gasoline, diesel and MtBE identified in groundwater in vicinity of former tanks. Invest required to determine lateral and vertical extent of contamination, sensitive receptors, and quarterly monitoring initiated.
UAAF Transmitter Site CR 36 & Mace Blvd	UST Davis	255 BA Diesel, TCE PCE, EDB	Closed File BA: 2001 Groundwater sampling and analysis data summary reports
UCD UCD	HM Davis	278 Hazmat Storage & Disposal	Closed INSPECTION OF CAMPUS FACILITIES BY DTSC FOUND 17 VIOLATIONS. UNIVERSITY ORDERED TO CORRECT VIOLATIONS AND PAY CIVIL PENALTIES. CASE CLOSED.
UCD UCD E H & S, TB 30	HM Davis	340 Hydrocarbons, VOCs, Metals	Closed UNKNOWN PERSON(S) ABANDONED LEAKING WASTES ON UCD PROPERTY. DRUMS REMOVED, SOILS EXCAVATED AND REMOVED FOR OFFSITE DISPOSAL TO LEVELS LESS THAN 10 PPM TPH AS GAS & DIESEL, 1PPM VOC, AND BELOW BACKGROUND FOR METALS. CASE CLOSED
UCD AG SERVICES UCD AG Services Yard	HM Davis	71 Lead, Copper, PCB	Closed File H 71 - Soils found in 1984 to be contaminated with lead, copper and PCB's at former university salvage scrap metal operation. Estimated 24 cubic yards of soil was excavated and disposed as hazardous waste. A methylene chloride spill occurred in Nov 1990 and impacted soils were excavated. Both cases have been closed. This file was archived to 00380HWG in December 2003.
UCD AQUATIC CENTER UCD Campus	HM Davis	314 Volatile Organic Chemicals	Closed File duplicates file 261. All data combined in file H 261
UCD AQUATIC WEED CONTROL LAB S OF UCD Airport	HM Davis	261 Acetone, chloroform, cabon tet	Open Research laboratory discharged herbicide & solvent waste into several ponds. Chloroform & 1,2-dichloropropane found in groundwater. Soils with acetone excavated in 1992. Facility has installed carbon filter treatment system. CVRWQCB case. File includes studies, correspondence and waste discharge permits.
UCD CENTRAL GARAGE La Rue Rd	UST Davis	381 A Gasoline, Diesel	Closed FILE A: 1992 - 1999 DATA - A PIPING LEAK WAS INITIALLY DISCOVERED IN 1993. SOILS WERE EXCAVATED TO APPARANT CLEAN. MORE SOIL CONTAMINATION WAS DISCOVERED DURING 1987 TANK REMOVAL. ASSESSMENT REQUESTED.
UCD CENTRAL GARAGE La Rue Rd	UST Davis	381 B Gasoline, Diesel	Open FILE A: 2000 DATA - Further assessment found TPG at levels up 110 ppb, MTBE up to 5.1 ppb and 1.2-at 7.2 ppb.
UCD General File Campus	HM Davis	416 Misc File - WWTP	Open File A: Permit for geotechnical borings for proposed Science lab Bld on Hutchison Dr. Discharge requirements for Waste Water Treatment Plant.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
UCD HYDRAULICS LABORATORY UCD CAMPUS	Davis	HM 361	Closed	WASTE DISCHARGE REQUIREMENTS FROM FISH TREADMILL AND HOLDING FACILITY.
		Waste Discharge Requirements		
UCD LEHR SUPERFUND SITE South Campus/Solano County	Davis	HM 349	Open	FILE A: GENERAL INFOR STARTING 1997 BECAUSE SITE IS IN SOLANO COUNTY. WE HAVE NOT MAINTAINED FILE UNTIL PUTAH CREEK IMPACT DEMONSTRATED.
UCD MED CENTER UCD	Davis	HM 251	Closed	RADIOACTIVE MATERIAL LICENSE. MOVED TO RADIOACTIVE MATERIAL LICENSE FILES. RML.
UCD PESTICIDE APPLICATOR SITE UCD Campus	Davis	HM 203	Open	FILE A: ALDRIN & SIMAZIN DETECTED IN GROUNDWATER AT THE EVAPORATION BED RESEARCH SITE. RWQCB ISSUED C & A JUNE 93. GROUNDWATER PLUMES DEFINED JUNE 1998. REMEDIAL SYSTEM operational in December 1999.
		Pesticides		
UCD PRIMATE CENTER CR 98 DAVIS	DAVIS	H 500 e	OPEN	KEROSENE SPILL INTO GROUNDWATER, THE STATE IS THE LEAD AGENCY. THIS FILE HAS BEEN SCANNED INTO SIRE.
		KEROSENE		
UCD VET MED TEACHING HOSPITAL UCD VMTH	Davis	HM 141	Closed	GARBAGE INCLUDING MEDICAL WASTES PLACED INTO BIN FOR CARDBOARD RECYCLABLE WASTE ONLY. INVESTIGATION OF CAMPUS MEDICAL WASTE DISPOSAL PRACTICES INITIATED. File archived to 04912HWG in January 2004.
		Medical Waste		
U-HAUL #706-56 1750 W Capitol Ave	W. Sac.	UST 377 A	Closed	SOIL CONTAMINATION OBSERVED DURING 1993 TANK REMOVAL. GROUNDWATER CONTAMINATION SUSPECTED IN 1995 PIER. Problem Assessment Report in 1997 indicated very limited area of petroleum-impact soil and no impact to groundwater. Case closed March 1977, monitoring wells abandoned August 1999. File scanned June 2003 to 377UTH
		Gasoline		
UNDERWOOD, B J 1958 HAYES LN	Woodland	HM 252	Closed	COMPLAINANT STATES THAT RP DRAINS OIL & ANTIFREEZE TO GROUND. CASE CLOSED DUE TO LACK OF TIMELY INVESTIGATION.
		Vehicle Fluids		
UNDRESSER 1021 LINCOLN AVE	Woodland	HM 395	Open	INSPECTION DONE, VIOLATIONS NOTED, FILE SEALED BY YOLO COUNTY DA.
		Methylene Chloride - Stripper		
UNITED PARCEL SERVICE 1380 Shore St	W. Sac.	UST 396	Open	DIESEL CONTAMINATION FOUND IN WATER IN TANK EXCAVATION. PRELIMINARY INVESTIGATION REQUIRED. SENT CLEANUP ORDER. Investigation in progress September 2002. MTBE present in 5 GW monitoring wells.
		Diesel		
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	W. Sac.	HM 63 B	Closed	FILE B: CORRESPONDENCE
		TCA, PCE		
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	W. Sac.	HM 63 G	Closed	FILE G: OPERATIONS & MAINTENACE PLAN FOR INTERIM GROUNDWATER & SOIL VAPOR TREATMENT SYSTEMS.
		TCA, PCE, DCE		

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 F TCA, PCE	Closed FILE F 1996 DATA: GROUNDWATER EXTRACTION & TREATMENT CONTINUES. 21 MONITORING WELLS IN TWO HYDROSTIGAPHIC UNITS ARE MONITORED QUARTERLY FOR 9 VOLATILE HYDROCARBONS.
Univar/Vopak VAN WATERS & ROGERS 400 Ball Park Drive	HM W. Sac.	63 M	Open FILE M, N & O - 2001 - 2002 DATA: Quarterly monitoring continues. Waste Discharge requirements for nutrient amendment was amended and approved in November 2002. CVRWQCB contact Ms.. Karen Bessette, phone 916-255-3065.
Univar/Vopak VAN WATERS & ROGERS 800 South River Road	HM W. Sac.	63 C TCA, PCE	Closed FILE C - 1994 DATA: SOIL VAPOR & GROUNDWATER EXTRACTION SYSTEM CONSTRUCTED. START-UP PLANNED FOR FEB 1995. SYSTEM SHUT DOWN IN MAR 1995 AS WATER LEVEL ROSE ABOVE INTAKE SCREENS.
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 E TCA, PCE, DCE	Closed FILE E: 3RD QUARTER 1995 MONITORING REPORT. GROUNDWATER AIR SPARGING & SOIL VAPOR EXTRACTION SYSTEMS RE-STARTED THIS QUARTER.
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 D TCA, PCE, DCE	Closed FILE D 1995 DATA:
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 K TCA, PCE, DCE	Closed FILE K-1999 DATA: Facility is the site of a new baseball stadium. A RAP submitted in May recommends a combination of GW extraction, SVE and enhanced in-situ bioremediation including extraction, treatment and injection of treated groundwater. Extraction of up to 70,000 gallons of GW/day and injection of 28,000 gallon is proposed.
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 H TCA,PCE,DCE	Closed FILE H: 1997 DATA. GROUNDWATER EXTRACTION, AIR SPARGING AND SOIL VAPOR EXTRACTION AND TREATMENT SYSTEMS CONTINUE TO OPERATE.
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 J TCA,PCE,DCE	Closed FILE J:1998 DATA. TCE & PCE CONCENTRATIONS HAVE BEEN SIGNIFICANTLY REDUCED BY TREATMENT. PRIMARY CONCERN IS NOW FOCUSED ON CISTRANS-1, 2 DICHLOROETHYLENE (DCE).
Univar/Vopak VAN WATERS & ROGERS 400 Ball Park Drive	HM W. Sac.	63 L TCA, PCE, DCE	Closed FILE L-2000 DATA: Several ground water monitoring wells and the groundwater treatment system were destroyed during the construction of the River City Baseball stadium during Nov 99 and May 2000. The wells were replaced and a modified treatment system (SVE) was reconstructed. WDR's for the modified system was issued by the RWQCB. This agency is the lead for this case.
Univar/Vopak VAN WATERS & ROGERS 850 South River Road	HM W. Sac.	63 A TCA, PCE	Closed FILE A: PHASE I & II SITE INVESTIGATION REPORTS. SITE INVESTIGATION STOPPED DUE TO LITIGATION IN 1991. ASSESSMENT REMAINS INCOMPLETE. NO RWQCB ACTION SINCE 1990.
UNIVERSITY SHELL 1010 OLIVE DRIVE	UST DAVIS	350 GASOLINE	OPEN GASOLINE CONSTITUENTS WERE FOUND IN SOIL AND GROUNDWATER DURING A PHASE II INVESTIGATION IN DECEMBER 2006. CAMBRIA ENVIRONMENTAL NOTIFIED YCEH ON 01/04/2007. YCEH RECEIVED UAR FROM SHELL OIL PRODUCTS US IN 01/08/2007. YCEH WAITING FOR INVESTIGATIVE REPORT THAT WAS DUE 03/08/2007. REPORT RECEIVED ON 03/19/2007.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
University Shell 1010 Olive Drive	Davis	UST 350 Petroleum	Closed	L 350 - Total petroleum hydrocarbons as gasoline were detected in one soil sample at 3.9 PPM during product piping replacement. Soils were excavated and disposed. Samples at limit of excavation were non-detectable. No further action required. Case closed. File has been scanned into Adobe as FA 350 UTH.
UNOCAL #97 3961 Channel Dr	W. Sac.	HM 350 Spills	Open	FILE A: MINOR SPILLS & INCIDENT FILE. 1997 SODIUM HYDROXIDE (3 GALS)
UNOCAL (501 G ST, DAVIS) 501 G ST	Davis	UST 392 Gasoline	Closed	SOIL CONTAMINATION DISCOVERED DURING PRODUCT LINE REPLACEMENT & REMOVAL OF WASTE OIL TANK. SOILS (72 CU YDS) EXCAVATED & DISPOSED. CASE CLOSED. File scanned to 392UTH June 2003.
UNOCAL 76 501 G STREET	DAVIS	L 392 GASOLINE	OPEN	
UNOCAL STATION 5695 4825 W Capitol Ave	W. Sac.	UST 393 Waste Oil, Gasoline	Closed	FILE A PRE 1993 DATA - TWO GASOLINE & ONE WASTE OIL TANK REMOVED. CONTAMINATED SOIL EXCAVATED. SOIL BORING & MONITORING WELLS INDICATE BOTH SOIL & GROUNDWATER IMPACTED. FILE B 1993: CONTAINS PRELIMINARY INVESTIGATION REPORT WHICH PARTIALLY DEFINES PLUME & QUARTERLY MONITORING REPORTS. QUARTERLY MONITORING CONTINUES. ONLY TPH OBSERVED IN 1 OF 6 WELLS 2ND QTR '93. FILE C 1994-1996 DATA: QUARTERLY MONITORING OF LOW LEVELS OF GASOLINE IN GROUNDWATER CONTINUES. YOLO COUNTY & THE RWQCB ISSUED NO FURTHER ACTION REQUIRED LETTER. CASE CLOSED AUGUST 1997. File scanned to 293UTH June 2003.
UPRR/AMTRAK STATION Second & H	Davis	HM 324 e Gasoline, Chlorinated Solvents	Open	PHASE I SITE ASSESSMENT WORKPLAN FOR PROPERTY TRANSACTION. SUBSURFACE SOIL & GROUNDWATER INVESTIGATION REPORT SUBMITTED REVIEW OF FILE SHOWED CONCENTRATIONS OF BENZENE, CHLORINATED SOLVENTS. PROPOSITION 65 ISSUED.
UPS FREIGHT(MOTOR CARGO FACILITY) 917 STILLWATER ROAD	WEST SACRA	L 533 E DIESEL LEAK	OPEN	
URIBE, MARIE (PROPERTY) 128 Second St	Yolo	HM 134 Diesel	Closed	TENANT HAD DIESEL LEAKING ONTO GROUND, SOIL EXCAVATED, & AERATED.
USACE - BRYTE YARD 1645 Riverbank Rd	W. Sac.	UST 397 Gasoline	Closed	SOILS EXCEEDING 50 PPM TPH WERE EXCAVATED & AERATED ONSITE. FILE CLOSED JUNE 1990. File scanned to 397UTH June 2003.
USAF TRANSMITT ER SITE CR 36 & Mace Blvd	Davis	UST 255 e Diesel, TCE, PCE, EDB	Closed	FILE AB: SAMPLING & ANALYSIS PLAN FOR GROUNDWATER TREATMENT SYSTEM (B & C AQUIFERS).

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AG: INTERIM PUMP & TREATMENT SYSTEM REMEDIAL ACTION PLAN.
		Diesel, TCE, PCE, EDB		
USAF Transmitter Site CR 36 & Mace Blvd	Davis	UST 255 e	Open	File BB: 2002 - 2003 Data - PROJECT SUMMARY JUNE 2003 - Environmental Health maintains a technical file on the Davis Global Communications site with substantial technical data. Our files include information on the removal of former underground tanks and related environmental investigation and cleanup activities. This file (L 255) is available for review in our office. The underground tanks were removed from in 1985 under Yolo County permit. Soil contamination was observed during the tank removal and the Air Force ordered to initiate an environmental investigation to determine the extent of contamination. That investigation revealed that in addition to soil and groundwater petroleum contamination from the underground tanks there was also contamination from a solvent Tetrachloroethene (PCE) present in both soil and groundwater beneath the site. Investigation continued through 1995 finding these solvents and related chemicals in the five uppermost hydro geologic zones at the site to a depth of 245 feet. Although the solvents have migrated down gradient several thousand feet the entire contaminated plume is contained on Air Force property. Cleanup goals acceptable to Environmental Health and the State Water Board have been established for the site. A network of 46 groundwater monitoring wells at different depths are sampled quarterly to monitor the movement of contaminants in the groundwater and the progress of the remediation project. Quarterly and annual reports are prepared by the Air Force and submitted to the Regional Board and Yolo County for review. In 1995 a groundwater extraction and treatment plant was installed. As remediation progressed the system has been modified several times. The current system configuration uses six wells to extract contaminated groundwater from different hydro geologic zones. The groundwater is treated by passing the water through massive carbon filters. The treated water is then injected into the ground if front of the leading edge of contaminated plume to provide a barrier to further down gradient solvent migration. This system treats approximately 25 to 35 million gallons of groundwater quarterly. Analytical testing results of the effluent water out of the treatment system are below detection limits for site constituents of concern before it is injected back into the ground.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AH: OPERATION & MAINTENANCE MANUAL FOR SOIL VAPOR EXTRACTION SYSTEM.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AW: 2000 GENERAL FILE INCLUDING UST SOIL VAPOR EXTRACTION SYSTEM DOCUMENTS AND GROUNDWATER EXTRACTION SYSTEM EVALUATION REPORTS.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & MACE BLVD	DAVIS	UST 255 e	OPEN	FILE BF: FOURTH QUARTER 2003 GROUNDWATER MONITORING AND OPERATIONS REPORT VOLUME 1.
		DIESEL, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & MACE BLVD	DAVIS	UST 255 e	OPEN	FILE BH: DRAFT FIVE-YEAR REVIEW REPORT
		DIESEL, PCE, TCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AJ: CYCLE ONE & CYCLE TWO TEST SUMMARY RESULTS (1995/1996).
		Diesel, TCE, PCE, EDB		

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE, PCE, EDB	Closed	FILE AK: 1996 GROUNDWATER SAMPLING & ANALYSIS REPORTS.
USAF TRANSMITTER SITE CR 36 & MACE BLVD	UST 255 e DAVIS DIESEL, PCE, TCE, EDB	OPEN	FILE BG: FOURTH QUARTER 2003 GROUNDWATER MONITORING AND OPERATIONS REPORT VOLUME 2
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE, PCE, EDB	Closed	FILE Y: 1995 GENERAL DATA -
USAF TRANSMITTER SITE CR 36 7 MACE BLVD	UST 255 e Davis Diesel, TCE, PCE, EDB	Closed	FILE AS: 1999 FORTH QUARTERLY OPERATIONS REPORTS FOR THE INTERIM GROUNDWATER TREATMENT PLANT. LEAD AGENCY IS THE REGIONAL WATER QUALITY CONTROL BOARD, CONTACT MR Randy Adams of CalEPA 916-255-3591.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE	Closed	FILE AD: RD/RA WORKPLAN FOR VOC CONTAMINATED SOILS. SOIL VAPOR EXTRACTION SYSTEM FOR VADOSE ZONE USING 5 EXTRACTION WELLS, TREATMENT BY ACTIVATED CARBON WITH DISCHARGE TO ATMOSPHERE. CONSTRUCTION SCHEDULED FOR APR '96.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE	Closed	FILE AC: OPERATION & MAINTENANCE MANUAL FOR GROUNDWATER TREATMENT PLANT.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE, PCE, EDB	Closed	FILE AT: 1999 GENERAL FILE. UST SOIL VAPOR EXTRACTION SYSTEM CLOSURE PLAN. DRAFT FINAL FEASIBILITY STUDY ADDENDUM. FINAL GROUNDWATER EXTRACTION SYSTEM EVALUATION REPORT FOR THE INTERIUM PUMP AND TREAT SYSTEM. CONTACT MR. MOOK AT (916) 643-0839 EXT. 327 FOR INFORMATION.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE, PCE, EDB	Closed	FILE X 1995 DATA: QUARTERLY MONITORING OF B, C & D ZONES CONTINUES. EXTRACTION/TREATMENT & RE-INJECTION OF B & C ZONES INITIATED IN OCT.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE, PCE, EDB	Closed	FILE AX: 2000 GROUNDWATER SAMPLING AND ANALYSIS DATA SUMMARY REPORTS.
USAF Transmitter Site CR 36 & Mace	UST 255 e Davis Diesel, TCE, PCE, EDB	Open	
USAF TRANSMITTER SITE CR 36 & Mace Blvd	UST 255 e Davis Diesel, TCE	Closed	FILE AF: 1996 DATA - GROUNDWATER EXTRACTION, UV TREATMENT, & INJECTION BEGAN 10/95.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE H TO M - - FILE H - TECHNICAL REVIEW COMMITTEE MINUTES: TAC Formed & began meeting on quarterly basis in Jan 1992. FILE J: Site Remedial investigations work plan dated Sept. 2, 1992. FILE K: Intermediate Remedial design report proposes extraction of groundwater from B & C Aquifers, groundwater treatment, & on-site re-injection. FILE L: Community Relations Plan. FILE M 1993 Technical review committee proceedings: during 1993 Four groundwater extraction wells, 7 Monitoring Wells, & 2 CPT soundings were completed. Short duration aquifer pump tests completed, soil piles tested for hydrocarbons.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE W BIO-VENTING PILOT TEST WORKPLAN: TWO FILES WITH THE FIRST CONTAINING THE PRIMARY REPORT & THE SECOND CONTAINING VOL. 2 (APPENDICES) UST SOIL DIESEL REMEDIATION PROJECT.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AU: 1999 GROUNDWATER SAMPLING AND ANALYSIS DATA SUMMARY REPORTS.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AL: 1997 GROUNDWATER SAMPLING & ANALYSIS REPORTS.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AE: RD/RA WORKPLAN B/C CONTAMINATED GROUNDWATER EXTRACTION SYSTEM. ADDRESS INSTALLATION & OPERATION OF EXTRACTION & TREATMENT SYSTEMS FOCUSES ON END-USE SYSTEMS.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILES A TO G - -FILE A 1985/86 DATA: Soil contamination by diesel found during removal of UST. Subsequent investigation found soil & groundwater TCE contamination. FILE B 1987 DATA: Diesel leak occurred in remaining diesel tank. Piping replaced. File contains 1987 reports & correspondence including draft work plan for site characterization task one. FILE C 1988 DATA: Proposition 65 news release, several news articles & Phase I Report. FILE D 1989: File includes soil & groundwater analysis data gained during RI. Further assessment is documented. . FILE E 1990 DATA: Investigation continued to deeper aquifers as it is discovered from the ground to the second or third aquifers contaminated by TCE & it,s breakdown products. FILE F 1991 DATA/CORRESPONDENCE FILE: Investigation fully focused on TCE in groundwater. Diesel no longer considered a problem at this site since it has not been found in groundwater. FILE G 92 FILE: Additional MW installed. TAC meeting held in Apr. City & County expressed concern. Project stalled. Copy of Fed Facility site remediation agreement with DTSC & RWQCB. Also contains community profile. Report by radian.
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE Z: 1995 TECHNICAL REVIEW COMMITTEE
USAF TRANSMITTER SITE CR 36 7 MACE BLVD	Davis	UST 255 e	Closed	FILE AV: 2000 QUARTERLY OPERATIONS REPORTS FOR THE INTERIM GROUNDWATER TREATMENT PLANT. The Interim Groundwater Treatment Plant at this site treated approximately 27.1 million gallons of impacted groundwater during the first quarter of 2000. Approximately 4.71 pounds of the selected constituents of concern were removed by the granular activated carbon filtration process. Analytical testing results of the effluent water were below detection limits for site constituents of concern. The treated groundwater was injected into the groundwater aquifer down gradient of the extraction wells. LEAD AGENCY IS THE REGIONAL WATER QUALITY CONTROL BOARD, CONTACT MR ALEX MACDONALD.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AQ: 1998 GROUNDWATER TREATMENT PLANT QUARTERLY OPERATION REPORTS.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AR: 1998 GENERAL CORRESPONDENCE FILE AND SOIL VAPOR EXTRACTION SYSTEM REPORTS.
		Diesel, TCE, PCE, EDB		
USAF Transmitter Site CR 36 & Mace Blvd	Davis	UST 255 e	Closed	File AZ: 2001GENERAL FILE INCLUDING UST SOIL VAPOR EXTRATION SYSTEM DOCUMENTS AND GROUNDWATER EXTRACTION SYSTEM EVALUATION REPORTS.
		Diesel, TCE, PCE, EDB		
USAF Transmitter Site CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AY: 2001 QUARTERLY OPERATIONS REPORTS FOR THE INTERIM GROUNDWATER TREATMENT PLANT. The Interim Groundwater Treatment Plant at this site treats approximately 25 to 35 million gallons of impacted groundwater quarterly. Constituents of concern are removed by a granular activated carbon filtration process. Analytical testing results of the effluent water were below detection limits for site constituents of concern. The treated groundwater is injected into the groundwater aquifer down gradient of the extraction wells. LEAD AGENCY IS THE REGIONAL WATER QUALITY CONTROL BOARD, CONTACT MR ALEX MACDONALD.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AP: 1998 GROUNDWATER SAMPLING & ANALYSIS REPORTS.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILES N TO V : - FILE N 1993 GENERAL DATA & CORRESPONDENCE FILE: 1993 intermediate design report, community relations plan, draft remedial investigation/feasibility study & draft risk assessment reports. FILE P: Risk assessment report. No eminent & substantial human health risk identified. Some ecological risks are present, other short-term risks associated with remedial activities identified. FILE Q: Remedial Investigation Feasibility Study volume I- documentation of current understanding of site contamination & evaluation of potential mitigation actions. FILE R: Remedial investigation/feasibility study vol. II including Appendix A To P. FILE S: Remedial investigation/feasibility study vol III including appendix Q To U. FILE T: 1994 Tech Rev Comm min: gndwtr will be contained with extraction well (installed) and treated by ultraviolet/oxidation & activated carbon filter & reinjection (wells installed). Treatment system has not been installed as of Nov 1994. FILE V - 1994 GEN FILE: Soil contamination will be removed by soil vapor extraction and carbon filtration. System to be installed during summer of 1995.
		Diesel, TCE		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AN: 1997 GENERAL FILE & SOIL VAPOR EXTRACTION SYSTEM REPORTS.
		Diesel, TCE, PCE, EDB		
USAF TRANSMITTER SITE CR 36 & Mace Blvd	Davis	UST 255 e	Closed	FILE AM: 1997 GROUNDWATER TREATMENT PLANT REPORTS.
		Diesel, TCE, PCE, EDB		
VALERO 1592 EAST MAIN STREET	WOODLAND	UST 506	OPEN	CONTAMINATION FOUND OCTOBER 24, 2003 ON NORTH SIDE OF PROPERTY DURING REPAIR/UPGRADE WORK. LIMITED SOIL OVER EXCAVATION REMOVED CONTAMINATED SOIL. CONTAMINATED SOIL WAS FOUND JANUARY 8, 2004 ON THE SOUTH SIDE FUELING CIRCLE. LIMITED SOIL OVEREXCAVATION REMOVED THE MAJORITY OF CONTAMINATION. TPHD WAS PRESENT AT LOW CONCENTRATIONS. GROUNDWATER SAMPLES INDICATE DIESEL AND GASOLINE CONTAMINATION IN GROUNDWATER.
		DIESEL AND GASOLINE		

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
VAN WERT MOTORS 1700 Olive Dr	Davis	HM 257 Petroleum	Closed	H 257 INVESTIGATION OF COMPLAINT. THE CURRENT OCCUPANT HAS ALLOWED WASTE OIL DISCHARGES TO THE GROUND DUE TO POOR HANDLING AND STORAGE PRACTICES. CASE CLOSED.
Van Wert Motors (Timperley Property) 1700 Olive Dr	Davis	UST 89 Unleaded Gasoline	Open	L 89: Tanks were removed in 1988, six assessments conducted between 1989 and 1992 defined the lateral and vertical extent of soil and groundwater impacts. The Water Board issued a cleanup and abatement order in 1992. Based upon the results of these assessments a site remediation program was implemented using combined GWE/SVE. The SVE system operated through the 4th Qtr of 1995 and the GWE system operated through the 2nd quarter of 1996. The City of Davis municipal water supply well number 24 is located approximately 330 feet down-gradient of the former UST location. The well surface seal was extended from 50 to 186 bgs to protect the deep aquifers from the first- encountered aquifer. Oxygen injection into groundwater began during the first quarter of 2000. Currently the A and B zones are being monitored quarterly. The first quarterly report for 2001 indicates that the contaminated plume has been generally defined and stable, or concentrations are decreasing in the monitoring well sampled. FILE A - Pre 1996 data, FILE B 1992 Superior Court Case Documents, FILE C 1996 data, FILE D 1997 data, FILE E 1998 data, FILE F 1999 data, FILE G 2000 data, FILE H 2001 data. Groundwater monitoring continues through 2002. File I 2002/2003 data.
VAN WERT/SWIFT 5100 Chiles Rd	Davis	HM 373 Hydrocarbons	Closed	H 373 – Three 1,000-gallon tanks containing gasoline, diesel and waste oil was removed. Benzene & chlorinated solvents found in shallow groundwater Proposition 65 Report was issued. The CVRWQCB found in March 2002 that investigations show that hydrocarbons from former USTs and a sump affect soil and groundwater beneath the site. Soil and groundwater data show that gasoline and diesel hydrocarbons are predominantly within the capillary fringe/smear zone, 15 to 35 feet bgs and the top portion of the shallow groundwater. This plume of hydrocarbons in soil and ground water is defined laterally and vertically. The nearby water supply Well No. 21 does not appear to be threatened, because ground water data shows that in 34 years, hydrocarbons have not migrated beyond the site. Also, pumping from well No. 21 does not appear to affect ground water beneath the site. Natural attenuation data shows both oxidizing and reducing environments beneath the site, and fate and transport modeling shows that hydrocarbons should be 100 percent degraded within 50 years. Hydrocarbons in soil and ground water beneath the site do not represent a threat to water quality or beneficial uses; therefore, a No Further Action Required letter is recommended for this site after the monitoring wells have been destroyed. Yolo Count records indicate the wells were removed in April 2002. Case closed.
VAN WINKLE FACILITY 3141 South River Road	W. Sac.	HM 218 Waste Oil	Closed	W. SAC. CODE ENFORCEMENT OFFICER FOUND PIT WITH 2 TO 3 INCHES OF PONDED WASTE OIL. INSPECTION CONDUCTED OCT 29 FOUND CONTAMINATED SOILS REMOVED & PROPERLY DISPOSED. CASE CLOSED.
Varquez Property 3300 CR 99	Dunnigan	HM 427 Waste Oil	Closed	Waste oil disposed to soil along driveway. Owner removed oil. Case closed
VASQUEZ RESIDENCE 901 Casselman Dr	W. Sac.	HM 280 Transformer Oil	Closed	POWER TRANSFORMER LEAKED ONTO TREE, FENCE, AND YARD. OWNER CLAIMED TREE DIED. PG & E CONDUCTED SOIL & OIL TESTS FINDING VERY LOW LEVELS OF PCB. PG & E CLEANED FENCE, REPLACED TREE AND SOILS. CASE CLOSED.
VECTRA TRANSPORTATION 621 Houston St	W. Sac.	UST 182 Petroleum/diesel	Closed	MINOR SOIL & GROUNDWATER CONTAMINATION ASSOCIATED WITH UST. FURTHER ASSESSMENT & GROUNDWATER MONITORING DETERMINED THAT NO REMEDIAL ACTION REQUIRED. FILE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
VIC'S HARBOR REPAIR SHOP 408 Harbor Blvd	HM W. Sac.	64 Hydrocarbons, Caustics	Closed H 64 - Complaint investigation in 1987 discovered soil contamination from caustic tank & general machine shop activities. Soils excavated & disposed. Site inspected by city of W Sacramento. A second investigation found minor waste oil soil contamination. Case closed Nov 9, 1992. File archived to 5477HWG in December 2003.
VIKING FREIGHT 1820 Parkway Blvd	HM W. Sac.	103 Haz Waste	Closed INVESTIGATION OF WASTE OIL & OTHER HAZARDOUS WASTES INTO REGULAR GARBAGE CONTAINERS. CASE REFERRED TO THE DISTRICT ATTORNEY & DHS JAN 28, 1992. FILE CLOSED.
VIKING PROPANE 1111 Railroad Ave	HM Madison	177 Anhydrous Ammonia	Closed File H 177 - Two Hazmat emergency response reports in 1992 to regarding anhydrous ammonia releases. File archived to 04598 in January 2004.
VILLAGE GARDEN APARTMENTS 900 Todhunter #9	HM W. Sac.	231 Oil/Gas Mixture	Closed ALLEGED DUMPING OF 5 GALS OIL/GAS MIXTURE TO GROUND. INVESTIGATION PENDING STAFF AVAILABILITY. CASE CLOSE DUE TO LACK OF EVIDENCE.
VIRCON PROPERTY Harbor & Evergreen Ave	HM W. Sac.	144 Diesel, Gasoline	Closed File H 144 - Soils from former Kings Truck Stop scales aerated in windrow in lot north of ARCO station. Verification samples indicate TPH as diesel is less than 100ppm. Case closed June 1994. File archived as 00225UTH in January 2004.
VOLKL & SONS, INC 38 Harter Ave	HM Woodland	130 Waste Oil	Closed File H 130 - Soils from waste oil drum storage area excavated for offsite treatment & disposal. File closed October 1991. File archived to 04388HWG in January 2004.
VONDOLLAN, ROY/JOANN, ORCHARD 16002 CR 82B	UST CAPAY	2503 Diesel	Closed YOLO COUNTY ENV HEALTH WAS REQUESTED TO WITNESS THE REMOVAL OF AN EXEMPTED FARM UNDERGROUND TANK. DURING THE REMOVAL, ONE SOIL SAMPLE WAS COLLECTED BENEATH THE TANK. THE LAB RESULTS SHOW DIESEL CONTAMINATION. Further investigation found minor soil and groundwater contamination, the site was determined to be a low risk and the case closed in October 1996. The file was archived to 2503UTH in December 2003.
W F LEWIS CO 506 Glide Ave	HM W. Sac.	69 No Release	Closed INVESTIGATION OF TIP THAT PCB CONTAMINATED SOILS DISPOSED AT THIS SITE. INVESTIGATION FOUND NO CONFIRMING EVIDENCE.
W SAC BLDG B (MENTAL HEALTH) 500 B Jefferson Blvd	HM W. Sac.	391 Indoor Air Quality	Closed INDOOR AIR QUALITY COMPLAINT INVESTIGATION. Case closed.
W SAC BRODERICK SEWER Broderick Area	HM W. Sac.	260 Sewer Improvement	Closed SPECIFICATIONS FOR SEWER IMPROVEMENTS.
W SAC BROWNFIELD Washington Fireho 305-317 3rd Street	HM W. Sac.	390 Metals, VOCs, SVOC	Open BROWNFIELD ASSESSMENT COMPLETED SHOWING MIGRATION OF METALS IN SURFACE SOIL AND IN THE GROUNDWATER. GROUNDWATER CONTAMINATION LIMITED TO SOUTHERN PROPERTY LINE. SEE BROWNFIELD REPORT IN DEPT

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
W SAC CITY HALL, Old Port Bld 2101 Stone Blvd	HM W. Sac.	428 Asbestos	Open File H 428 - City hall was vandalized, water was released inside building. Asbestos impacted on several floors.
W SAC CITY HALL, PROPOSED 1101 W Capitol Ave	HM W. Sac.	380 Gasoline	Closed FORMER GAS STATION 30 YEARS AGO. SOME SOIL & WATER CONTAMINATION FOUND. WORKPLAN SUBMITTED. WELLS ABANDONED. NFAR LETTER ISSUED BY CVRWQCB. CASE CLOSED.
W SAC CODE ENFORCEMENT 1049 Orchard Way	HM W. Sac.	239 Waste Oil	Closed ALLEGED OFFICER REMOVED DRUM OF WASTE OIL FROM LEAKING VEHICLE & THREW INTO TRASH. INVESTIGATION PENDING STAFF AVAILABILITY. CASE CLOSED DUE TO LACK OF EVIDENCE.
W SAC CORP YARD 1951 South River Road	UST W. Sac.	160 Diesel	Closed DIESEL CONTAMINATION FOUND DURING REMOVAL OF 2 TANKS. SOILS EXCAVATED TO ABE AERATED ONSITE. NO CLOSURE REPORT SUBMITTED. CASE CLOSED. File was scanned January 2002 and can be found in the 160UTH file.
W SAC FIRE STATION 132 Fifteenth St	UST W. Sac.	494 Gasoline	Closed TPHD soil contamination detected in 1988. A 500-gallon UST that contained gasoline as well as 400 cubic yards of surrounding soil was removed. Two wells installed in cavity were monitored over time. Results obtained from 1988, 1992 and 1993, as well as 1994, indicate decreasing levels of TPHg and non-detectable levels of Benzene. Three additional wells were installed around the perimeter of the site during July of 1994. Samples indicated non-detectable levels of contamination in 1999. W-4 did detect small amounts of diesel hydrocarbon in 1999. In the 6 January 1997 Tier I RBCA, Wallace and Kuhl state that petroleum hydrocarbons in soil and ground water beneath the site do not pose a significant health risk. The combined results indicate no risk. Closure of this site was granted on January 12, 2000, by the CVRWCCB. Destruction of the five monitoring wells occurred on August 7, 2000. A member of the Yolo County Environmental health staff observed the destruction. File closed. File archived to 494UTH in November 2003.
W SAC JEFFERSON SEWERLINE Jefferson Blvd	HM W. Sac.	240 Gasoline	Closed SITE INVESTIGATION TO ACCESS CONDITIONS TO BE ENCOUNTERED DURING SEWERLINE CONSTRUCTION THROUGH GASOLINE CONTAMINATED AREA.
W SAC LAND CO (MOBIL)(REDWOOD) 1400 W Capitol Ave	USTL W. Sac.	10 Gasoline	Closed FILE LR 10 - In the spring of 1985, three underground gasoline storage tanks were removed from the site. Two of these tanks were pitted and leaking. Soil contamination was observed, floating product was found on the groundwater. Soils were excavated in 1986 and remediated on site. Groundwater extraction and treatment was implemented. Based on the levels of contaminants remaining after excavation of the tank pits and the low to non-detect levels of contaminants in groundwater following the groundwater remediation efforts, it appears that there is no longer a threat to water quality from the soils at this site. The case was closed in July 1997. File was archived to 3133UTH in December 2003.
W SAC REDEVELOPMENT AGENCY 4756 W Capitol Ave	HM W. Sac.	165 Petroleum	Closed INITIAL SITE ASSESSMENT TOOK 8 SURFACE & 8 SAMPLES TWO FT BELOW GROUND SURFACE. ONE SAMPLE CONTAINED 12,000 PPM TOTAL LEAD. PHASE II ASSESSMENT EITHER NEVER COMPLETED OR NO RESULTS SUBMITTED. CASE CLOSED.
W SAC WASTEWATER TREATMENT PLT 1950 South River Road	HM W. Sac.	74 Sewage	Closed H 74 - This file was moved November 2002 to the Water Program files.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
WANTZ EQUIPMENT CO 3203 W Capitol Ave	HM W. Sac.	199 Hydrocarbons	Closed VIOLATION OF WASTE WATER REGS FOUND BY CITY. COUNTY ORDERED CLEAN-UP OF STEAM CLEANING AREA. SITE FORMERLY CLOUGH EQUIPMENT CO (H-16). CASE CLOSED.
WARD LABOR CAMP CR 102 1 Mi N Of Cache Creek	HM Woodland	67 EDB	Closed ETHYLENE DIBROMIDE FOUND IN DRINKING WATER WELL IN THIS AGRICULTURAL AREA. REFERRED TO DRINKING WATER PROGRAM.
WASHINGTON U.S.D. STORAGE FACILIT 931 WESTACRE ROAD	UST WEST SAC	5657 HYDROCARBIN IN SOIL AND GND	CLOSED
WASHINGTON USD 1706 GRANDA VISTA	UST W. Sac.	407 Gas & Diesel	Open Soil and groundwater removal during the UST removal appears to have removed secondary sources of petroleum fuel contamination, because petroleum fuel hydrocarbons were non-detect in soil samples from borings in and around the former UST cavity. The mass of hydrocarbons remaining beneath the site consists of very small amounts of diesel and MtBE that were defined to be largely in and near the former UST cavity. A RBCA assessment showed MtBE in groundwater is not a health risk to site occupants. The sensitive receptor survey showed water supply wells are not within 2,000 feet of the site. Wallace-Kuhl concluded that the site should be closed as a "low risk groundwater site" because water supply wells are not near the site, and the plume of hydrocarbons remaining does not represent a threat to drinking water supplies. A No Further Action Required letter was issued by the Central Valley Regional Water Quality Control Board in September 2001.
WELLS CARGO 617 Houston St	UST W. Sac.	416 Diesel, Gasoline	Closed CASE CLOSED BY REGIONAL WATER QUALITY CONTROL BOARD.
WEST CAPITOL / ANDERSON SITE 4225 WEST CAPITOL AVE	HM WEST SACRA	482 LEAD, NICKEL, MOTOR OIL	OPEN 1998 PHASE I SITE ASSESSMENT NOTED CONCERNS REGARDING THE PROPERTY. 2001 PHASE II SITE ASSESSMENT CONFIRMED LEAD, NICKEL, AND MOTOR OIL CONTAMINATION IN SOIL, DRILLING AND ADDITIONAL SAMPLING PROPOSED IN MAY 2004
WEST CAPITOL AVE / ANDERSON SITE 4203 WEST CAPITOL AVE	HM WEST SACRA	482 LEAD, NICKEL, MOTOR OIL	OPEN 1998 PHASE I SITE ASSESSMENT NOTED CONCERNS REGARDING THE PROPERTY. 2001 PHASE II SITE ASSESSMENT CONFIRMED LEAD, NICKEL, AND MOTOR OIL CONTAMINATION IN SOIL, DRILLING AND ADDITIONAL SAMPLING PROPOSED IN MAY 2004.
WEST CAPITOL AVE / ANDERSON SITE 4205 WEST CAPITOL AVE	HM WEST SACRA	482 LEAD, NICKEL, MOTOR OIL	OPEN 1998 PHASE I SITE ASSESSMENT NOTED CONCERNS REGARDING THE PROPERTY. 2001 PHASE II SITE ASSESSMENT CONFIRMED LEAD, NICKEL, AND MOTOR OIL CONTAMINATION IN SOIL, DRILLING AND ADDITIONAL SAMPLING PROPOSED IN MAY 2004
WEST SACRAMENTO 76 4010 LAKE RD	UST W. Sac.	580 Gasoline	Open Installed dispenser container and replaced dispensers and some piping in fall of 2000. Soil contaminated with gasoline, BTEX and oxygenates. Further investigation found groundwater impacted with hydrocarbons and MTBE. RWQB requested work plan for investigation September 2002.
WESTERN TRUCK SCHOOL 4521 W Capitol Ave	HM W. Sac.	279 e Waste Oil	Closed DTSC ENF ORDER TO CORRECT CONDITIONS ALLOWING WASTE OIL SPILLAGE, CLEAN UP SPILLAGE, CORRECT TECHNICAL VIOLATIONS, PROPOSES PENALTY OF \$1,800. CASE CLOSED.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
Westlake Plaza (Lake Cleaners) 1260 Russell Blvd	HM Davis	424 TCE	Open
WEYERHAEUSER 1925 Enterprise Ave	UST W. Sac.	418 Diesel	Closed
WHITE PROPERTY OAK GROVE & SIXTH ST KNIGHTS LAN	H TPH AS DIESEL AND BTEX	498	OPEN
WILBER ELLIS 350 Industrial Way	HM Woodland	332 Pesticide	Closed
WILDHORSE GROUP SUBDIVISION	HM Davis	371 High PH Material	Closed
WILLIG FREIGHT LINES 850 F ST	UST W. Sac.	420 Gasoline	Closed
WILLOW OAK GROCERY 37030 SR 16	UST Woodland	421 Gasoline	Closed
WILLOW POINT RANCH 0	HM Clarksburg	120	Closed
WING LEE MEATS 3075 W Capitol Ave	UST W. Sac.	423 Gasoline	Closed
Winters City Waste Water Treatment Plan CR 32	HM Winters	434 Inspection	Closed
WINTERS FIRE DEPARTMENT 10 Abbey Street	UST Winters	424 Diesel	Closed

File H 424:Site assessment conducted for loan review found TCE in soils up to 71 PPM in one boring and lower levels in both additional borings. Further investigation approved by Yolo County June 2001.

DURING TANK REMOVAL, SOIL SAMPLES SHOWED LARGE LEVELS OF DIESEL CONTAMINATION. SITE CLOSED. File Archived November 2003 to 418UTH.

CONTAMINATED SOIL WAS EXCAVATED AROUND AST TANK AREA TO A DEPTH OF UP TO 15 FEET. FOUR DIRECT PUSH BORINGS WERE CONDUCTED AROUND EXCAVATION. GROUNDWATER WAS NON DETECT FOR TPH AS DIESEL HOWEVER, ONE SOIL SAMPLE DID DETECT VERY MINOR AMOUNTS OF DIESEL IN SOIL. SIE HAS BEEN CLOSED AFTER CONSULTING WITH THE RWQCB AST SLICK UNIT.

ALLEGED PESTICIDE DISPOSAL REFERRAL TO CVRWQCB. CASE CLOSED.

NOTICE OF VIOLATIONS BY RWQCB FOR DISCHARGE OF SILT, HIGH PH SUBSTANCES INTO STORM DRAIN BY CONTRACTORS. INFORMATION FILE ONLY.

TANK FAILED TESTING FEB 1986, LEAKING BUNG IN VENT LINE REPLACED, TANK RETESTED AND PASSED. NO REMEDIATION WAS REQUIRED. FILE CLOSED. File archived November 2003 to 420UTH.

DURING ROUTINE TANK REMOVAL, CONTAMINATION FOUND AT DISPENSER ISLAND. SOIL EXCAVATED, TREATED ONSITE AND EXCAVATION BACKFILLED. NO FURTHER WORK REQUIRED. File archived to 421UTH November 2002.

SOIL EXCAVATED TO 13 FT. ALL EXCAVATION SAMPLES NON-DETEABLE. NO GROUNDWATER CONTAMINATION DETECTED. SITE CLOSED ON AUG 14, 1991.

DURING ROUTINE TANK REMOVAL SOIL SAMPLES TAKEN. SOIL ANALYSIS INDICATED CONTAMINATION PRESENT. SOIL EXCAVATED TO 14 FT. RESIDUAL CONTAMINATION OF 54-73 PPM LEFT BECAUSE OF IMPACT TO UTILITIES. SITE CLOSURE LETTER WRITTEN. FILE CLOSED. File archived to 423UTH November 2003.

H 434 - This file was moved November 2002 to the Water Program files.

R B C A DONE. REMAINING SOIL IS NOT A RISK TO GROUNDWATER & DRINKING WATER WELLS. FILE CLOSED. File archived to 424UTH November 2003.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
WINTERS GARAGE 2 Russell St	HM Winters	66 Waste Oil <i>Closed</i>	WASTE OIL DISCHARGED TO GROUND, SOILS EXCAVATED & DISPOSED AS HAZARDOUS WASTE. FURTHER DISCHARGE PROHIBITED.
WOOD, RON 1460 Main St (East)	HM Woodland	310 Waste Oil <i>Closed</i>	IMPROPER DISPOSAL OF WASTE ENGINE OIL INTO OIL-WATER SEPARATOR. CASE CLOSED OCT 22, 1995.
WOODLAND (CITY OF) 300 First St	HM Woodland	76 Penachlorophenol (PCP) Cots <i>Closed</i>	INVESTIGATION OF ILLNESS ASSOCIATED WITH USE OF MILITARY SURPLUS COTS REVEALED COTS TREATED WITH WOOD PERSERVATIVE PCP. OES REQUESTED AID OF DTSC. FILE CLOSED.
WOODLAND BEAMER ST PONDS Between CR 101 & CR 102	HM Woodland	68 PCB Metals <i>Open</i>	INVESTIGATION OF SLUDGE AT FORMER CITY WASTE WATER PONDS IDENTIFIED SEVERAL CONSTITUENTS AT ELEVATED LEVELS. INVESTIGATION CONTINUES. RWQCB IS LEAD AGENCY.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 E Lead <i>Closed</i>	FILE E: LEAD INVESTIGATION REPORT PART ONE - THROUGH THE CITY CONDITIONAL USE PERMIT PROCESS THE PLANT IS REQUIRED TO PROVIDE A SEMI ANNUAL REPORT OF ASH GENERATION AND ANALYSIS.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 A Lead <i>Closed</i>	FILE A: 1987 PROJECT INITIAL STUDY - WOODLAND BIOMASS PLANT (BP) OBTAINED PLANNING APPROVAL (FILE A TO D) TO CONSTRUCT ELECTRICITY GENERATING FACILITY USING AGRICULTURAL WASTES AS FUEL.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 N Ash Disposal/Chamberlin Far <i>Open</i>	FILE N - CHAMBERLAIN FARMS LANDSPREADING ASH TO BE INCORPORATED ON SEVERAL FIELDS AS AN AGRICULTURAL SOIL AMENDMENT.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 M Lead <i>Closed</i>	FILE M: 1994/1995 FILE GENERAL CORRESPONDENCE & SELF-MONITORING REPORTS.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 P Gen File 1996 - 2000 <i>Open</i>	FILE P: 1996-2002 GENERAL CORRESPONDENCE & SELF-MONITORING REPORTS. Includes semi annual monitoring reports & results and investigation of high lead in ash found in early 1999.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 K Lead <i>Closed</i>	FILE K: GENERAL FILE APRIL TO DECEMBER 1992.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 J Lead <i>Closed</i>	FILE J: GENERAL FILE THROUGH MARCH 1992.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 G Lead <i>Closed</i>	FILE G: LEAD INVESTIGATION BACKGROUND RESEARCH - THESE LOCATIONS ARE IN SUTTER COUNTY, THE PROGRAM HAS MET LOCAL OPPOSITION.

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 I Lead	Closed FILE I: LEAD/ASH STABILIZATION PROJECT.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 H Lead	Closed FILE H: LEAD INVESTIGATION CHAIN OF CUSTODY - THE CVRWQCB ALLOWS ASH BELOW THE HAZ WASTE LEVEL TO BE LANDFARMED WITHOUT REGULATORY OVERSIGHT.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 F Lead	Closed FILE F: LEAD INVESTIGATION REPORT PART TWO - THE DTSC HAS ALLOWED SOME ASH LAND SPREADING EXCEEDING HAZ WASTE LEAD LEVELS AT SPECIFIC LOCATIONS PROVIDED CERTAIN PARAMETERS ARE MET.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 L Lead	Closed FILE L: 1993 FILE
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 D Lead	Closed FILE D: FINAL PROJECT EIR DECISION - ASH FROM DESERET FARMS & GENERATED BY WBP EXCEEDING LEAD LIMITS WAS TREATED BY LIME STABILIZATION AND USED AS ROADBASE AT THE PLANT SITE (SEE FILE I).
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 C Lead	Closed FILE C: FINAL EIR PROJECT REPORT - ASH STOCKPILED AT DESERET FARMS WAS RETURNED TO THE PLANT. ASH GENERATED AT PLANT DURING 1992 NOT ALLOWED TO BE LANDFARMED. HAZARDOUS WASTE DISPOSAL CASE WAS SETTLED OUT OF COURT.
WOODLAND BIOMASS POWER LTD 1786 Kentucky Ave (East)	HM Woodland	157 B Lead	Closed FILE B: 1988 DRAFT EIR - ACTING ON A TIP YOLO COUNTY SERVED A SEARCH WARRANT INITIATING AN INVESTIGATION OF ASH DISPOSAL PRACTICES. ASH WAS FOUND TO CONTAIN LEAD CONCENTRATIONS EXCEEDING HAZARDOUS WASTE LEVELS (SEE FILES E TO H).
WOODLAND CHRISTIAN SCHOOL Cottonwood & Lincoln	HM Woodland	72 Waste Oil	Closed SOILS AT PROPOSED JUNIOR HIGH CAMPUS SITE FOUND TO HAVE WASTE OIL STAINS. SOILS REMOVED & STOCKPILED IN SECURED LOCATION TO ALLOW NATURAL DEGRADATION OF OIL.
WOODLAND CITY ERKEIN POND CR 24 & CR 102	UST Woodland	123 Diesel	Closed File L 123 - Soil contamination discovered during 1990 UST removal. Soil excavated & aerated on-site to less than 900 mg/kg. File archived to 00123UTH in January 2004.
WOODLAND JUSD 526 Marshall Ave	HM Woodland	188 Non-Storm Water	Closed FILE CONTAINS INFORMATION DURING STUDY FOR PREPARATION OF RWQCB STORM WATER DISCHARGE PERMIT. CASE CLOSED.
WOODLAND JUSD 910 College St	HM Woodland	398 Haz Waste Investigation	Closed Investigation conducted at the request of the School District regarding handling, storage and disposal procedures. Large quantity of hazardous waste found. SAR written. Waste removed by licensed hauler. File closed.
WOODLAND JUSD 910 College St	HM Woodland	401 Indoor Air Quality, Bioaersol	Closed INDOOR AIR QUALITY INVESTIGATION OF THREE SCHOOLS NO PROBLEMS FOUND. FILE CLOSED.

Facility	File/Number	Status	Comments	
WOODLAND JUSD/ADULT ED 575 HAYS	HM Woodland	393 Mold	Open	FINAL REPORT OF SAMPLING MOLD FOUND AT LOW LEVELS. BUILDING CAN BE REOCCUPIED.
WOODLAND JUSD/Dingle Elementary Sc 625 Elm St	HM Woodland	392	Closed	Indoor Air Study.
WOODLAND OLD CITY CORP YARD 20 Sutter St	HM Woodland	161 Unknown	Closed	CITY OF WOODLAND REQUESTED YCEH IN 1993 TO REVIEW THE SITE ASSESSMENT OF THE OLD CORP YARD. Further investigation was conducted in 1999 through 2001 to further investigate prior to development. Motor Oil was found in a limited area. FILE CLOSED.
WOODLAND PISTOL RANGE CR 102 Btwn Kentucky & Beamer	HM Woodland	151 Lead	Open	ASSESSMENT & MITIGATION OF ELEVATED SOIL LEAD LEVELS AT POLICE PISTOL RANGE. SOIL EVALUATION PREPARED FOR CITY PLANNING OCT 1991. YCEH LEAD AGENCY. GROUNDWATER EVALUATION FOUND NO LEAD IMPACT.
WOODLAND PLAZA 151 W. MAIN ST	HM Woodland	426 Waste Oil	Open	H 426 - A 55 Gal drum of waste oil behind dumpster over spilled onto ground. Owner directed to clean up.
WOODLAND REDEV (NORTH) 920 North St	HM Woodland	194 Investigation	Closed	PROPOSED CITY REDEVELOPMENT SITE INVESTIGATION. CASE CLOSED
WOODLAND REDEV (VOLKL\SYAR) Beamer St (East)	HM Woodland	170 Potentially Contaminated Soil	Open	FORMER GRAVEL PIT PROPOED FOR DEVELOPMENT BEING FILLED WITH SOILS & INERT MATERIALS. SOME SOIL FOUND TO CONTAIN HYDROCARBONS. CITY REQUESTS COUNTY REVIEW OF SITE PRIOR TO DEVELOPMENT. REVIEW CONTINUES AS SITE IS FILLED.
WOODLAND RICE GROWERS 215 East St	UST Woodland	411 Gasoline	Closed	FILE 411: AUG 1987 TANK REMOVAL FOUND SOILS CONTAMINATED TO 22 FT. Investigation completed, remediation completed, Case closed by the RWQCB May 2001. File archived to Adobe 411UTH November 2003.
WOODLAND TRACTOR 95 Kentucky Ave (West)	UST Woodland	412 Waste Oil	Closed	MAY 5, 1993 YCEH RECEIVED REMEDIATION REPORT. 18 YDS OF WASTE OIL CONTAMINATED SOIL EXCAVATED, TRANSPORTED UNDER MANIFEST & DISPOSED. SOIL SAMPLES COLLECTED RESIDUAL OIL PRESENT BELOW REGULATORY LEVELS. NO COUNTY OVERSIGHT OCCURRED. SITE CLOSED. File contents archived to Adobe system file number 412UTH in November 2003.
WOODLAND WAREHOUSE (FORMER) 509 Fifth St	UST Woodland	434 Gasoline	Closed	SOIL CONTAMINATION DISCOVERED DURING 1989 REMOVAL OF 1500 GAL STEEL TANK. SOILS EXCAVATED, AERATED ONSITE & BACKFILLED INTO EXCAVATION. SITE TO BECOME WOODLAND POLICE STATION. FILE CLOSED MAY 1990. File archived to 434UTH November 2003.
WOODLAND WASTE WATER PLANT CR 24	HM Woodland	341 NPDES Permit	Closed	H 341 - This file was moved November 2002 to the Water Program files.

<i>Facility</i>		<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
YC CORP YARD 213 Fourth St	W. Sac.	HM 323 Hydraulic Oil	Closed	SMALL CONCENTRATION OF HYDRAULIC OIL DETECTED IN HYDRAULIC LIFT AREA. NO FURTHER WORK REQUIRED. SITE CLOSED.
YOLO CENTRAL LANDFILL Yolo Central Landfill	Davis	HM 70 Waste Oil	Closed	File H 70 - In 1987 a septic tank pumper disposed oily waste from steam cleaning sump into class iii pond. Booms used to contain waste in one end of pond where it was solidified in soil, the soil was excavated and disposed as hazardous waste. This pond is now closed. Case closed. File archived to 2125 in December 2003.
YOLO CENTRAL LANDFILL - AST CR 28H	Davis	HM 197 Diesel	Closed	FILE H 197 - A 10,000 AST diesel tank removed in 1991 had extensive corrosion on the under side of the tank. Investigation determined that soil and groundwater beneath the tank had been impacted. Soils were excavated and treated on site and groundwater monitoring conducted for four quarters. Groundwater impact was determined to be less than water quality criteria resulting in no further action being required. File archived as 02125HWG in February 2004.
YOLO CO AIRPORT - ARMY CORPS CR 29 & CR 29	Davis	HM 294	Closed	PIPING REMOVED NO CONTAMINATION FOUND. CLOSURE REPORT RECEIVED (SEELIBRARY). SITE CLOSED.
YOLO CO AIRPORT - PESTICIDES CR 29 & CR 95	Davis	HM 91 Pesticides	Closed	File H 91 - Yolo County conducted investigation in 1990/1991 of crop duster loading area. Minor surface contamination identified. Compliant investigation by the RWQCB in 1995 also included. Case closed. File archived to 02123HWG in January 2004.
YOLO CO AIRPORT/CURTIS & ASSOC CR 29 & CR 95	Davis	HM 73 C Dichloromethene, Phenols	Open	FILE C 1990 TO PRESENT: CURTIS SHUT DOWN IN 1990. MOVED OUT OF STATE. LEGAL ACTION BY DTSC IN PROGRESS.
YOLO CO AIRPORT/CURTIS & ASSOC CR 29 & CR 95	Davis	HM 73 A Dichloromethene, Phenols	Closed	FILE A PRE 1989: AIRPLANE PAINT REMOVAL OPERATION FROM 1982-1990 DISCHARGED TO SURFACE IMPOUNDMENT FROM 1982-1987. BECAUSE METHYLENE CHLORIDE USED RWQCB & DTSC REQUESTED INVESTIGATION. FILE CONTINUES TO 8793B.
YOLO CO AIRPORT/CURTIS & ASSOC CR 29 & CR 95	Davis	HM 73 B Dichloromethene, Phenols	Closed	FILE B 1989: LOW LEVELS OF SEVERAL ORGANIC COMPOUNDS FOUND IN UPPER SOILS UNDER FORMER POND. NO DEEP BORINGS OR GROUNDWATER ANALYSIS HAVE BEEN COMPLETED. FILE CONTINUES TO 8793C.
YOLO CO AIRPORT/NON-STORM WAT CR 29 & CR 95	Davis	HM 189 Non-Storm Water	Closed	FILE CONTAINS INFORMATION GATHERED DURING STUDY FOR PREPARATION OF RWQCB STORM WATER DISCHARGE PERMIT. CASE CLOSED.
YOLO CO FAIRGROUNDS 1250 Gum Ave (East)	Woodland	UST 63 A Gasoline	Open	L 63 A: Soil and groundwater contamination discovered during 1962 removal of two--500 gallon underground tanks. The investigation appeared complete for hydrocarbons in 1995, except for MTBE. Due to a lack of funding the State of California performed no further work from January 2000 through December 2003.
YOLO CO FARM BUREAU 69 Kentucky Ave (West)	Woodland	HM 106 Petroleum Hydrocarbons	Closed	SURFACE SOIL CONTAMINATION IDENTIFICATION DURING PURCHASE OF PROPERTY BY BUREAU. PROPOSAL FOR SOIL EXCAVATION SUBMITTED TO YOLO COUNTY DEC 1990.

Facility	File/Number	Status	Comments	
YOLO CO FLOOD CONTROL 34274 HWY 16	UST Woodland	440 A Gasoline	Closed	FILE 430: PRELIMINARY SOIL INVESTIGATION REPORT-SOIL CONTAMINATION FOUND DURING UST REMOVAL. SOILS EXCAVATED TO 25 FT & STOCKPILED ONSITE. EXCAVATION OF CONTAMINATED SOILS COMPLETED. SOILS STOCKPILED ON-SITE. COUNTY REQUESTING PROPOSAL FOR TREATMENT AND/OR DISPOSAL OF EXCAVATED SOILS.
YOLO CO HOUSING AUTHORITY HWY 16	HM Madison	171 Waste Oil	Closed	REMOVAL OF ASPHALT PAD FOR VEHICLE OIL CHANGES REVEALED SOIL CONTAMINATION BY WASTE OIL. FILE CLOSED.
YOLO CO HOUSING AUTHORITY 1230 Leman Ave	UST Woodland	2584 Diesel	Closed	SMALL ISOLATED AMOUNT OF TPH-D REMAINS IN SOIL. CASE CLOSED. File archived to 2584UTH in December 2003
YOLO CO INVESTIGATIONS 120 Main St (West)	HM Woodland	104 Investigations	Closed	INVESTIGATED AIR QUALITY FOR SOCIAL SERVICES, SALUD CLINIC, YOLO COUNTY BOARD OF EDUCATION, & PUBLIC WORKS TRAFFIC PAINT. AIR COMPLAINT FROM A BURNED HEATING SYSTEM MORTOR WAS INVESTIGATED ON 1/9/92 AT PROBATION DEPARTMENT. NO OTHER ACTION TAKEN.
YOLO CO PUBLIC WORKS 292 BEAMER ST (WEST)	HM Woodland	360 Sulfur	Closed	AIR SAMPLES COLLECTED ON SULFUR. NOTHING WAS FOUND.
YOLO CO PUBLIC WORKS Fourth & B St	UST W. Sac.	442 Gasoline	Closed	TANK FAILED TESTING JANUARY 1986, PIPE LEAK REPAIRED MAR 1986, NO REMEDIATION REQUIRED. FILE CLOSED. File archived to 442UTH November 2003.
YOLO CO PUBLIC WORKS 292 Beamer ST (West)	UST Woodland	443 Gasoline, Diesel, Tetrachlorid	Closed	TURBINE SHUTOFF WAS CAUSED BY LEAKY FOOT VALVE ON DROP TUBE. TANKS AND PIPING REMOVED. NO LEAK CONFIRMED. When tanks were removed some minor diesel contamination was observed in soils, which was excavated and treated. A monitoring well was installed to groundwater, no petroleum was identified in the ground water sample. Case closed.
YOLO CO PUBLIC WORKS ESPARTO 26981 Woodland Ave	UST Esparto	444 C Diesel, Gasoline, Tetrachlorid	Open	L 444 - FILE C: 1999/2000 DATA, File D 2001 Data QUARTERLY MONITORING CONTINUES. RWQCB IS THE LEAD AGENCY.
YOLO CO PUBLIC WORKS ESPARTO Woodland Ave	UST Esparto	444 B Diesel, Gasoline, Tetrachlorid	Closed	Third quarter 2001 monitoring indicates MW 3 & MW 4 have significant impact from underground storage tanks. MW 1-3 has chloroform. MW 2 has carbon tetrachloride. All levels were reported to be steady or decreasing in 2002.
YOLO CO PUBLIC WORKS ESPARTO 26981 Woodland Ave	UST Esparto	444 A Gasoline, Diesel, Tetrachlorid	Closed	GROUNDWATER INVESTIGATION. FIRST & SECOND QUARTER GROUNDWATER MONITORING.
Yolo County Library 1001 Railroad Street	HM Winters	450 Phase 1 Site Assess.	Open	Phase I Site Assessment "revealed no direct evidence of recognized environmental conditions in connection with the subject property"

<i>Facility</i>	<i>File/Number</i>	<i>Status</i>	<i>Comments</i>
YOLO FLIERS CLUB CR 94B & CR 22	UST Woodland	448 Gasoline	Closed
			FILE 448: Soil contamination found during 9991 removal of 350 gal UST. PIER completed Sept. 1991 confirmed groundwater contamination. Problem Assessment Report completed Nov 1992. Vadose zone soils to 18 ft excavated & treated on-site. Groundwater monitoring initiated may 1992 continued quarterly. 1992/1993 quarterly groundwater monitoring continued. Four wells constructed for vapor extraction/air sparging feasibility study. Two converted to monitoring wells (six total). In 1994 remedial feasibility studies conducted. State cleanup fund commitment letter received. 1997 all wells abandoned, State issues No Further Action Letter in 1997. File closed. File archived to 448UTH in November 2003.
YOLO SHORTLINE RAILROAD 341 Industrial Way	HM Woodland	226 Waste Oil	Closed
			REPORT OF ILLEGAL WASTE OIL DISPOSAL. INVESTIGATION PENDING STAFF AVAILABILITY. COULD NOT DOCUMENT DISPOSAL FOR ENFORCEMENT. CASE CLOSED.
YOLO SPORTSMEN'S ASSOCIATION 24189 AVIATION AVE	HM Davis	382 Lead	Open
			EXTENT OF LEAD CONTAMINATION BEING ASSESED.
Yolo/Solano Used Oil Collection Program County-wide	HM Woodland	436	Closed
			Variance for used oil Ag Collection Program
Zieman Manufacturing Co 1805 Beamer St	HM Woodland	417 Paint	Closed
			Disposal of paint to Yolo Central Landfill. Facility picked up paint for proper disposal
Zimmerman Dentistry 127 Court St	HM Woodland	135 Medical Waste	Closed
			A COMPLAINT INITIATED INSPECTION. FOUND SHARPS & OTHER MEDICAL WASTES IN DUMPSTER.