

County Road 98

Bike and Safety Improvement Project, Phase 2



Location 1 - County Road 98/ Hutchison Dr

Comment

- 1 Improve Intersection safety to reduce accidents
- 2 Bike path- separated to Russell Blvd.

Location

- (Hutchison Road/County Road 98)
- (East side of County Road to County Road 32)



Location 2 - County Road 98/County Road 32 (Russell Blvd.)

Comment

- 1 Match existing bike path
- 2 Provide raised center island for roundabout. Put cacti there
- 3 Move cacti to center of roundabout
- 4 Provide separate bike path to Hutchison

Location

- (County Road 32)
- (County Rd 98/County Road 32 intersection)
- (South-East quadrant corner by intersection)
- (Along CR 98/East side)



Location 3 - County Road 98/ County Road 31 (W Covell Blvd).

Comment

- 1 Improve drainage so intersection doesn't flood
- 2 Improve water flow under CR 98. Currently both summer irrigation and winter flood waters backup here.
- 3 Provide adequate lighting and signing. High Speed is a factor.
- 4 Important that drainage water from CR31-98 intersection does not come into this field.

Location

- (Intersection)
- (Intersection)
- (Intersection)
- 700 ft S/W of intersection

