

**TECHNICAL STUDIES AND
RECOMMENDATIONS FOR THE
LOWER CACHE CREEK
RESOURCE MANAGEMENT PLAN**

Prepared for:

Yolo County Community Development Agency

Prepared by:

EIP Associates
Northwest Hydraulic Consultants
David Keith Todd, Consulting Engineers

October, 1995

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1. INTRODUCTION	1-1
2. EXECUTIVE SUMMARY	2-1
3. CACHE CREEK STREAMWAY STUDY	3-1
3.1 Introduction	
Introduction	3.1-1
Location and Study Area	3.1-1
Need for a Streamway Investigation	3.1-1
Objectives and Scope	3.1-3
3.2 Basin Geology and Geomorphology	
Historical Background and Geomorphology Methods	3.2-1
Geologic Structure and Tectonism	3.2-14
Uplift and Subsidence	3.2-15
Basin and Channel Geomorphology	3.2-21
Physiographic Provinces of Cache Creek	3.2-22
Geomorphic Reaches Distinguished in this Study	3.2-23
Temporal Variability and Channel Dynamics	3.2-24
3.3 Hydrology, Hydraulics, and Sediment Yield	
Basin Characteristics	3.3-1
Previous Studies	3.3-6
Methods	3.3-7
Flow Variability	3.3-11
Sediment Yield	3.3-24
Aggregate Extraction	3.3-29
3.4 Cache Creek History of Human Influences	
Purpose of Historical Analysis	3.4-1
Early Settlement	3.4-1
Agriculture	3.4-4
Surface Water Diversions and Irrigation	3.4-11
Floods and Flood Control	3.4-16

TABLE OF CONTENTS (cont)

<u>Section</u>	<u>Page</u>
3.4	History of Human Influences (cont)
	Gravel Mining 3.4-23
	Bridges 3.4-27
	Historical Descriptions of Channel Morphology 3.4-29
	Summary of Historical Analysis 3.4-36
3.5	Changes in Channel Geomorphology
	Introduction 3.5-1
	Methods 3.5-1
	Examination of Aerial Photographs 3.5-14
	Summary of Changes in Significant Channel Characteristics . . . 3.5-22
	Changes in Active Channel Area Over Time 3.5-23
3.6	Channel Dynamics
	General 3.6-1
	Present Hydraulic Conditions 3.6-2
	Bridge Hydraulics 3.6-5
	Sediment Transport 3.6-16
	Channel Responses to Altered Conditions 3.6-35
4.	LOWER CACHE CREEK GROUNDWATER STUDY 4-1
4.1	Introduction 4.1-1
4.2	Available Data 4.2-1
	Rainfall 4.2-1
	Streamflow 4.2-5
	Irrigation Diversions 4.2-5
	Land Use 4.2-5
	Geologic Logs 4.2-5
	Groundwater Levels 4.2-8
	Groundwater Use 4.2-8
	Groundwater Quality 4.2-8
	Aggregate Excavation and Production 4.2-10
4.3	Hydrogeologic Setting 4.3-1
	Geologic Setting 4.3-1
	Aquifers and Groundwater Occurrence 4.3-1
	Aquifer Hydraulic Properties 4.3-7
	Groundwater Storage 4.3-8
	Groundwater Quality 4.3-10

TABLE OF CONTENTS (cont)

<u>Section</u>	<u>Page</u>
4.4	Historical Perspective 4.4-1
	Introduction 4.4-1
	Early History (to 1940) 4.4-1
	Middle History, 1941 - 1977 4.4-10
	Recent History, 1978 - 1995 4.4-26
4.5	Aggregate Mining and Groundwater Resources 4.5-1
	Introduction 4.5-1
	Impacts on Groundwater Quantity 4.5-2
	Groundwater Flow 4.5-4
	Streambed Lowering 4.5-14
	Impacts on Groundwater Quality 4.5-15
	Summary: Major Mining and Reclamation Alternatives 4.5-19
	Aggregate Mining and Groundwater Management 4.5-21
	Monitoring 4.5-22
	Use of a Regional Model 4.5-25
5.	BIOLOGICAL RESOURCES STUDY 5-1
5.1	Introduction 5.1-1
	Contents of the Report 5.1-1
	Regional Setting of Cache Creek 5.1-1
	Conservation and Restoration 5.1-3
5.2	Ecology of Riparian Habitat 5.2-1
	Introduction 5.2-1
	Physical Basis of Riparian Ecosystems 5.2-1
	Physical Parameters of Riparian Habitats 5.2-2
5.3	History of Habitat and Human Influences 5.3-1
	Introduction 5.3-1
	Prehistoric Period 5.3-1
	Early History 5.3-2
	Twentieth Century 5.3-3
5.4	Existing Conditions 5.4-1
	Introduction 5.4-1
	Habitat Conditions Within the Study Area 5.4-4
	Fisheries 5.4-6

TABLE OF CONTENTS (cont)

<u>Section</u>	<u>Page</u>
5.5	Special-Status Species and Other Wildlife 5.5-1
	Introduction 5.5-1
	Species Known to Occur Along Cache Creek 5.5-3
	Additional Species for Which Suitable Habitat Occurs Along Cache Creek 5.5-8
	Restoration Potential Species 5.5-13
5.6	Weeds 5.6-1
	Introduction 5.6-1
	Tamarisk <i>Tamarix ramossissima</i> (<i>T. pentandra</i>) 5.6-2
	Giant Reed <i>Arundo donax</i> 5.6-5
5.7	Habitat Restoration: Present Potential and Limitations 5.7-1
	Introduction 5.7-1
	Present Riparian Habitat Limitations 5.7-1
	Riparian Habitat Planting Guidelines for Cache Creek 5.7-3
6.	RECOMMENDATIONS 6-1
7.	REPORT PREPARATION 7-1
8.	REFERENCES 8-1
9.	GLOSSARY 9-1

LIST OF FIGURES (cont)

<u>Figure No.</u>	<u>Page</u>
Figure 1-1 Cache Creek Primary Study Area	1.1-3
 3. Cache Creek Streamway Study	
Figure 3.1-1 Primary Study Area	3.1-2
Figure 3.2-1 Watershed Schematic	3.2-2
Figure 3.2-2 Map of Cache Creek Drainage Basin	3.2-4
Figure 3.2-3 Geologic Time Scale	3.2-5
Figure 3.2-4 Proportion of Each Lithology in Representative Gravel Samples	3.2-9
Figure 3.2-5 Grain Size Plot	3.2-10
Figure 3.2-6 SLA/Wet Grain Size Analysis	3.2-11
Figure 3.2-7 Definition of Sediment Load Components	3.2-12
Figure 3.2-8 Structure Map of Drainage Basin	3.2-16
Figure 3.2-9 Schematic for Blind Thrust System	3.2-17
Figure 3.2-10 Subsidence Diagram	3.2-18
Figure 3.2-11 Location of Geodetic Survey	3.2-19
Figure 3.2-12 Rate of Ground Movement	3.2-20
Figure 3.2-13 Cache Creek Geomorphic Subreaches	3.2-24
Figure 3.2-14 Photo of Capay Reach	3.2-25
Figure 3.2-15 Photo of Hungry Hollow Reach	3.2-26
Figure 3.2-16 Photo of Madison Reach	3.2-27
Figure 3.2-17 Geusisosi Reach	3.2-30
Figure 3.2-18 Photo of Dunnigan Hills Reach	3.2-31
Figure 3.2-19 Photo of Hoppin Reach	3.2-32
Figure 3.2-10 Photo of Rio Jesus Maria Reach	3.2-33
 Figure 3.3-1 Stream Gage Station Location Map	 3.3-2
Figure 3.3-2 1983 Hydrograph	3.3-12
Figure 3.3-3 1977 Hydrograph	3.3-13
Figure 3.3-4 1984 Hydrograph	3.3-14
Figure 3.3-5 Mean Monthly Flows at Yolo and Rumsey	3.3-15
Figure 3.3-6 Distribution of Water at Capay Dam	3.3-16
Figure 3.3-7 Woodland Precipitation	3.3-17
Figure 3.3-8 Peak Annual Discharge-Cache Creek at Yolo	3.3-18
Figure 3.3-9 Histogram of Provisional Measured Flows at Rumsey	3.3-20
Figure 3.3-10 100-Year Hydrograph	3.3-21
Figure 3.3-11 50-Year Hydrograph	3.3-22
Figure 3.3-12 Suspended Sediment Rating	3.3-25
Figure 3.3-13 Bedload Rating Curve	3.3-26
Figure 3.3-14 Cache Creek Aggregate Extraction/Production	3.3-27

LIST OF FIGURES (cont)

<u>Figure No.</u>	<u>Page</u>
Figure 3.3-15 Cumulative Extraction Cache Creek 1919-1994	3.3-30
Figure 3.3-16 Cumulative Sand and Gravel Yield	3.3-31
Figure 3.3-17 Cumulative Change in Stream Bed Sediment Storage	3.3-33
Figure 3.3-18 Project Change in Stream Deposits	3.3-38
Figure 3.4-1 John Bidwell's 1844 "Mapa del Valle Sacramento"	3.4-3
Figure 3.4-2 Diseño for Rancho Cañada de Capay	3.4-5
Figure 3.4-3 Government Survey of Rancho Cañada de Capay	3.4-6
Figure 3.4-4 Early Irrigation Works	3.4-13
Figure 3.4-5 Early Irrigation Works	3.4-14
Figure 3.4-6 Early Irrigation Works - Capay Dam	3.4-17
Figure 3.4-7 Moore Dam 1892-1914	3.4-18
Figure 3.4-8 Irrigation Canal System, 1915 and Present	3.4-19
Figure 3.4-9 Net Irrigation Diversions	3.4-20
Figure 3.4-10 Gravel Extraction on Cache Creek	3.4-25
Figure 3.4-11 Gravel Extraction in Cache Creek	3.4-26
Figure 3.4-12 Esparto Bridge Plan	3.4-28
Figure 3.4-13 The Esparto Bridge Washout	3.4-30
Figure 3.4-14 Stevens Bridge	3.4-31
Figure 3.4-15 Cache Creek Timeline	3.4-37
Figure 3.5-1 Cache Creek Study Area Map	3.5-2
Figure 3.5-2 Channel Conditions for Pre-1937	3.5-7
Figure 3.5-3 Channel Conditions for 1937	3.5-8
Figure 3.5-4 Channel Conditions for 1952	3.5-9
Figure 3.5-5 Channel Conditions for 1964	3.5-10
Figure 3.5-6 Channel Conditions for 1978	3.5-11
Figure 3.5-7 Channel Conditions for 1981-1994	3.5-12
Figure 3.5-8 Average Reach Width Over Time	3.5-17
Figure 3.5-9 Change in Thalweg Elevation Under Bridges 1905-1994	3.5-20
Figure 3.5-10 Longitudinal Profiles from Topographic Maps	3.5-24
Figure 3.5-11 Historical Channel Cross Section Measured at Highway 505	3.5-25
Figure 3.5-12 Historical Cross Section Changes Since 1905 at 818+00	3.5-26
Figure 3.5-13 Historical Cross Section Changes Since 1905 at 1077+00	3.5-27
Figure 3.5-14 Historical Cross Section Changes Since 1905 at 1270+00	3.5-28
Figure 3.5-15 Historical Cross Section Changes Since 1905 at 1375+00	3.5-29
Figure 3.5-16 Historical Cross Section Changes Since 1905 at 1435+00	3.5-30
Figure 3.6-1 1994 and 1905 Profile	3.6-3
Figure 3.6-2 Reach Average Flow for 100-yr Flood	3.6-4
Figure 3.6-3 Effects of Levees on Flood Hydrographs	3.6-6
Figure 3.6-4 Cache Creek Looking Upstream from Capay Bridge, May 31, 1994	3.6-13
Figure 3.6-5 Cache Creek Looking Upstream from Capay Bridge, June 6, 1995	3.6-13

LIST OF FIGURES (cont)

Figure No.	Page
Figure 3.6-6	Emergency Repair of North Abutment of Capay Bridge 3.6-14
Figure 3.6-7	Reach Averaged Sediment Load Changes for the 2-Year Event 3.6-17
Figure 3.6-8	Reach Averaged Sediment Load Changes for the 10-Year Event 3.6-18
Figure 3.6-9	Reach Averaged Sediment Load Changes for the March 1995 Event 3.6-19
Figure 3.6-10	Reach Averaged Sediment Load Changes for the 100-Year Event 3.6-20
Figure 3.6-11	Reach Averaged Sediment Load Changes for the 500-Year Event 3.6-21
Figure 3.6-12(a)	Reach Averaged Sediment Load Changes 3.6-26
Figure 3.6-13	Typical Channel Adjustment After 100 Years of Continuous Flow Simulation 3.6-27
Figure 3.6-14	Generalized Equilibrium Concept for Long-Term Formation 3.6-29
Figure 3.6-15	Complex Profile Response to Channelization 3.6-31
Figure 3.6-16	Sensitivity Test Number Three 3.6-32
Figure 3.6-17	Reach Average Flow Characteristics for 100-Year Event 3.6-33
Figure 3.6-18	Generalized Equilibrium Concept for Long-Term Formation and Response of Erodible Channels 3.6-36
Figure 3.6-19	Example of Complex Profile Response to Channelization 3.6-37
 4. Lower Cache Creek Groundwater Study	
Figure 4.1-1	Location Map 4.1-2
Figure 4.2-1	Davis Precipitation (1874-1994) 4.2-2
Figure 4.2-2	Woodland Precipitation (1927-1994) 4.2-3
Figure 4.2-3	Esparto Precipitation (1918-1994) 4.2-4
Figure 4.2-4	Stretch of Diversions on Cache Creek 4.2-6
Figure 4.2-5	Irrigation Diversion on Cache Creek (1929-1994) 4.2-7
Figure 4.2-6	Woodland Wells Annual Production (1960-1994) 4.2-9
Figure 4.2-7	Cache Creek Aggregate Extraction/Production (1919-1994) 4.2-11
Figure 4.3-1	Regional Superficial Geologic Map 4.3-2
Figure 4.3-2	Geologic Profile A-A' 4.3-3
Figure 4.3-3	Geologic Profile B-B' 4.3-5
Figure 4.3-4	Geologic Profile C-C' 4.3-6
Figure 4.4-1	Longitudinal Profiles from Topographic Maps 4.4-4
Figure 4.4-2	Groundwater Level Map, 1912-1913 4.4-5
Figure 4.4-3	Groundwater Levels in Selected Wells 4.4-7
Figure 4.4-4	Distribution of Water at Capay Dam, 1943-1974 4.4-13
Figure 4.4-5	Water Distribution Between Capay and Yolo, 1943-1974 4.4-15
Figure 4.4-6	Wells Constructed in 10N1IE and 10N1IW (1920-1989) 4.4-18
Figure 4.4-7	Groundwater Levels in Selected Wells through 1994 4.4-20
Figure 4.4-8	Spring 1959 Groundwater Elevation Contour Map 4.4-21
Figure 4.4-9	Spring 1977 Groundwater Elevation Contour Map 4.4-22

LIST OF FIGURES (cont)

<u>Figure No.</u>	<u>Page</u>
Figure 4.4-10 Fall 1977 Groundwater Elevation Contour Map	4.4-23
Figure 4.4-11 Spring 1983 Groundwater Elevation Contour Map	4.4-32
Figure 4.4-12 Fall 1991 Groundwater Elevation Contour Map	4.4-33
Figure 4.4-13 Spring 1993 Groundwater Elevation Contour Map	4.4-34
Figure 4.4-14 Groundwater Levels in Two Wells Showing Thalweg Effect	4.4-36
Figure 4.4-15(a) Water Chemistry Well 10NI2W 26ML, Lamb Valley	4.4-40
Figure 4.4-15(b) Water Chemistry Wells 10NI2WIML and 10NI2W 1M2, Hungry Hollow	4.4-41
Figure 4.4-15(c) Water Chemistry Well 10NISW 28C1, Madison	4.4-42
Figure 4.4-15(d) Water Chemistry Well 10NIIE 33JI, Plainfield Ridge	4.4-43
Figure 4.4-15(e) Water Chemistry Well 10NIIE 1542, Yolo	4.4-44
Figure 4.5-1 Estimated Groundwater Flow Along Cache Creek	4.5-5
Figure 4.5-2 Wellhead Protection Area	4.5-16
Figure 4.5-3 Wellhead Protection Area, Domestic Well	4.5-17
5. Biological Resource Study	
Figure 5.1-1 Primary Study Area	5.1-2
Figure 5.4-1 Existing Riparian Habitat on Cache Creek	5.4-2
6. Recommendations	
Figure 6-1 Recommended Management Activity Zones	6-3
Figure 6-2 Generalized Cross Section Template	6-6
Figure 6-3 Wide Cross Section	6-7
Figure 6-4 Narrow Cross Section with Adjacent Pits	6-8
Figure 6-5 Narrow Cross Section	6-9
Figure 6-6 Typical Channel Transition at Bridges	6-10

LIST OF TABLES

<u>Table No.</u>	<u>Page</u>
3. Cache Creek Streamway Study	
Table 3.2-1	Reported Values of D16, D50, D84 3.2-13
Table 3.2-2	Summary of Reach Characteristics 3.2-28
Table 3.3-1	Stream Gaging Stations 3.3-3
Table 3.3-2	Stream Flow Frequencies 3.3-4
Table 3.3-3	Principal Historical References 3.3-8
Table 3.3-4	Relevant Previous Studies 3.3-9
Table 3.3-5	Annual Sediment Loads 3.3-28
Table 3.4-1	Summary of the Growth of Stock Raising in Yolo County 3.4-8
Table 3.4-2	Summary of the Growth of Farming in Yolo County 3.4-9
Table 3.4-3	Summary of Cache Creek Irrigation Works, 1880 3.4-15
Table 3.4-4	Summary of Bridge History in Cache Creek Study Area 3.4-32
Table 3.5-1	Maps Utilized in this Study 3.5-3
Table 3.5-2	Aerial Photographs Examined in this Study 3.5-5
Table 3.5-3	Comparison of Area Mined Within the Channel, Pre-1937 to 1994 ... 3.5-31
Table 3.6-1	Table of Reach Averaged Hydraulic Characteristics 3.6-7
Table 3.6-2	Hydraulic Parameters for Bridges Scour Evaluation 3.6-8
Table 3.6-3	Cache Creek Bridges Scour Evaluation at 10-year Flood 3.6-9
Table 3.6-4	Cache Creek Bridges Scour Evaluation at 50-year Flood 3.6-10
Table 3.6-5	Cache Creek Bridges Scour Evaluation at 100-year Flood 3.6-11
Table 3.6-6	Comparison of Sediment 3.6-34
4. Lower Cache Creek Groundwater Study	
Table 4.4-1	Extent of Irrigated Agriculture, 1961-1968, Acres 4.4-11
Table 4.4-2	Estimated Groundwater Pumpage for Irrigation, 1966-1968 4.4-16
Table 4.5-1	Evapotranspiration Losses of Alternative Land Uses 4.5-3
5. Biological Resources Study	
Table 5.4-1	Habitat Acreage on Cache Creek 5.4-3
6. Recommendations	
Table 6-1	Summary of Recommendations 6-28
Table 6-2	Reach Characteristics 6-5