

Job#: 11275.00 - Yolo County Airport Drainage Basin Improvements

SUBMITTAL

Document No. 3 - Rev 0

10/17/2019

County of Yolo

Yolo County Airport Drainage Basin Improvements County Rd. 95 & County Rd. 29 Davis, CA

ATTENTION: Gene Wais

SUBJECT: Embankment Fill Per the table below enclosed and the attached documents are submittal items for review. Please review and respond by: 11/07/2019

ltem	Description	Rev	Date	Spec Section
1	Embankment Fill	0	10/17/2019	Bid Addendum No.2

Comments:

ORIGINATED BY:

Company: Teichert Construction Woodland OfficePhone: 530-341-4282Contact: Armando AguilarFax: 530-406-4299Title: Project ManagerEmail: AAGUILAR@teichert.com

Armando Aguilar

Contact: Armando Aguilar Title: Project Manager



Engineered Soil Report

Project No.: <u>190030</u> Project Name: <u>2019 Laboratory Testing</u> Client: <u>Teichert Aggregates</u> Lab No.: <u>L192712</u>

Sieve Analysis

Mass of Dry Sample, g:	10962
Mass of Dry Sub-Sample(if applicable), g:	514

Sampled By / Date: <u>Client / 10-11-2019</u> Tested By / Date: <u>J. Sturges / 10-16-2019</u> Material: <u>Screened Soil</u> Source: <u>Woodland</u> Load: Station: <u>Pile #2</u>

Sieve	Sieve Size		Percent	Percent	
U.S.	Metric	Retained	Retained	Passing	
2"	50 mm	0	0	100	
1 1/2"	37.5 mm	0	0	100	
1"	25 mm	130	1	99	
3/4"	19 mm	294	3	97	
1/2"	12.5 mm	724	7	93	
3/8"	9.5 mm	1120	10	90	
No.4	4.75 mm	2736	25	75	
No.8	2.36 mm	98	39	61	
No.16	1.18 mm	131	44	56	
No.30	600 mm	157	48	52	
No.50	300 mm	184	52	48	
No.100	150 mm	227	58	42	
No.200	75 mm	280	65.8	34.2	

Plastic & Liquid Limits

Liquid Limit	23
Plastic Limit	17
Plasticity Index	6
USCS Classification	

Graig Long Reviewed By:

Craig W. Long Laboratory Operations Manager

Serving California since 1987